FIRE ALARM TOP LOCATIONS - LAST THREE MONTHS 04/04/2022



Address	Incident Date	Incident Type	Response Zone	Primary Action Taken	Incident Number	Incident Status	Number of Apparatus	Dispatch Code
Alarm Count: 18								
169 East 200 South	03/17/2022 03:44:28	Smoke detector activation, no fire - unintentional	1EF	Investigate	CF22- 9404	Officer reviewed	1	ALARMF
169 East 200 South	03/16/2022 18:43:07	Smoke detector activation, no fire - unintentional	1EF	Investigate	CF22- 9364	Officer reviewed	1	ALARMF
169 East 200 South	03/08/2022 23:25:39	Dispatched and cancelled en route	1EF	Cancelled en route	CF22- 8443	Officer reviewed	1	ALARMF
169 East 200 South	03/03/2022 12:22:02	False alarm or false call, other	1EF	Investigate	CF22- 7668	Officer reviewed	1	ALARMF
169 East 200 South	03/01/2022 18:44:51	Dispatched and cancelled en route	1EF	Cancelled en route	CF22- 7471	Officer reviewed	1	ALARMF
169 East 200 South	02/24/2022 11:09:38	Dispatched and cancelled en route	1EF	Cancelled en route	CF22- 6853	Officer reviewed	1	ALARMF
169 East 200 South	02/18/2022 19:41:03	Dispatched and cancelled en route	1EF	Cancelled en route	CF22- 6133	Officer reviewed	1	ALARMF
169 East 200 South	02/16/2022 15:21:10	Dispatched and cancelled en route	1EF	Cancelled en route	CF22- 5858	Officer reviewed	1	ALARMF
169 East 200 South	02/08/2022 13:41:06	Dispatched and cancelled en route	1EF	Cancelled en route	CF22- 4894	Officer reviewed	1	ALARMF
169 East 200 South	02/08/2022 04:02:38	Dispatched and cancelled en route	1EF	Cancelled en route	CF22- 4831	Officer reviewed	1	ALARMF
169 East 200 South	02/06/2022 00:41:10	Alarm system activation, no fire - unintentional	1EF	Investigate	CF22- 4587	Officer reviewed	1	ALARMF
169 East 200 South	02/03/2022 15:41:43	Good intent call, other	1EF	Investigate	CF22- 4278	Officer reviewed	1	ALARMF
169 East 200 South	01/30/2022 00:01:24	Dispatched and cancelled en route	1EF	Cancelled en route	CF22- 3619	Officer reviewed	1	ALARMF
169 East 200 South	01/29/2022 03:33:17	Smoke detector activation, no fire - unintentional	1EF	Investigate	CF22- 3523	Officer reviewed	1	ALARMF
169 East 200 South	01/28/2022 19:19:23	Smoke detector activation, no fire - unintentional	1EF	Investigate	CF22- 3488	Officer reviewed	1	ALARMF
169 East 200 South	01/26/2022 22:14:48	False alarm or false call, other	1EF	Investigate	CF22- 3237	Officer reviewed	1	ALARMF
169 East 200 South	01/16/2022 18:17:13	Dispatched and cancelled en route	1EF	Cancelled en route	CF22- 2001	Officer reviewed	1	ALARMF
169 East 200 South	01/11/2022 15:12:25	Water problem, other	1EF	Shut down system	CF22- 1407	Officer reviewed	2	ALARMW
650 South MAIN Street	03/31/2022 09:21:44	Dispatched and cancelled en route	8LF	Cancelled en route	CF22- 11148	Officer reviewed	1	ALARMF
650 South MAIN Street	02/24/2022 09:09:59	Dispatched and cancelled en route	8LF	Cancelled en route	CF22- 6842	Officer reviewed	1	ALARMF
650 South MAIN Street	02/21/2022 10:57:08	Dispatched and cancelled en route	8LF	Cancelled en route	CF22- 6462	Officer reviewed	1	ALARMF
650 South MAIN Street	02/20/2022 09:09:07	Dispatched and cancelled en route	8LF	Cancelled en route	CF22- 6340	Officer reviewed	1	ALARMF
650 South MAIN Street	02/18/2022 09:13:28	Dispatched and cancelled en route	8LF	Cancelled en route	CF22- 6055	Officer reviewed	1	ALARMF
650 South MAIN Street	02/17/2022 08:08:44	Dispatched and cancelled en route	8LF	Cancelled en route	CF22- 5932	Officer reviewed	1	ALARMF
650 South MAIN Street	02/16/2022 11:34:49	Dispatched and cancelled en route	8LF	Cancelled en route	CF22- 5838	Officer reviewed	1	ALARMF
650 South MAIN Street	02/16/2022	Dispatched and	8LF	Cancelled en route	CF22-	Officer	1	ALARMF

Address	Incident Date	Incident Type	Response Zone	Primary Action Taken	Incident Number	Incident Status	Number of Apparatus	Dispatch Code
	10:26:00	cancelled en route			5832	reviewed	-p p at at at	1
650 South MAIN Street	02/16/2022 08:43:29	Dispatched and cancelled en route	8LF	Cancelled en route	CF22- 5820	Officer reviewed	1	ALARMF
650 South MAIN Street	02/15/2022 15:26:52	Dispatched and cancelled en route	8LF	Cancelled en route	CF22- 5740	Officer reviewed	1	ALARMF
650 South MAIN Street	02/15/2022 11:10:13	Dispatched and cancelled en route	8LF	Cancelled en route	CF22- 5716	Officer reviewed	2	ALARMF
650 South MAIN Street	02/15/2022 09:08:29	Dispatched and cancelled en route	8LF	Cancelled en route	CF22- 5706	Officer reviewed	1	ALARMF
650 South MAIN Street	02/12/2022 09:06:59	Dispatched and cancelled en route	8LF	Cancelled en route	CF22- 5388	Officer reviewed	1	ALARMF
650 South MAIN Street	02/11/2022 14:05:21	Dispatched and cancelled en route	8LF	Cancelled en route	CF22- 5291	Officer reviewed	1	ALARMF
650 South MAIN Street	02/11/2022 09:11:45	Dispatched and cancelled en route	8LF	Cancelled en route	CF22- 5249	Officer reviewed	1	ALARMF
650 South MAIN Street	02/11/2022 07:44:51	False alarm or false call, other	8LF	Investigate	CF22- 5243	Officer reviewed	2	ALARMF
650 South MAIN Street	02/10/2022 08:57:53	Dispatched and cancelled en route	8LF	Cancelled en route	CF22- 5096	Officer reviewed	1	ALARMF
650 South MAIN Street	02/03/2022 13:05:10	Dispatched and cancelled en route	8LF	Cancelled en route	CF22- 4248	Officer reviewed	1	ALARMF
Alarm Count: 15								
204 West 200 North	04/03/2022 19:07:44	Smoke detector activation, no fire - unintentional	2AF	Investigate	CF22- 11571	Officer reviewed	1	ALARMF
204 West 200 North	03/17/2022 08:56:54	False alarm or false call, other	2AF	Investigate	CF22- 9421	Officer reviewed	1	ALARMF
204 West 200 North	03/15/2022 17:48:11	Alarm system activation, no fire - unintentional	2AF	Restore fire alarm system	CF22- 9230	Officer reviewed	2	ALARMW
204 West 200 North	02/20/2022 19:34:48	False alarm or false call, other	2AF	Investigate	CF22- 6404	Officer reviewed	1	ALARMF
204 West 200 North	02/17/2022 08:34:39	Dispatched and cancelled en route	2AF	Cancelled en route	CF22- 5936	Officer reviewed	2	ALARMW
204 West 200 North	02/12/2022 17:34:28	False alarm or false call, other	2AF	Restore fire alarm system	CF22- 5440	Officer reviewed	1	ALARMF
204 West 200 North	02/10/2022 10:40:53	False alarm or false call, other	2AF	Investigate	CF22- 5115	Officer reviewed	1	ALARMF
204 West 200 North	02/06/2022 09:51:34	False alarm or false call, other	2AF	Investigate	CF22- 4619	Officer reviewed	1	ALARMF
204 West 200 North	02/05/2022 07:42:26	False alarm or false call, other	2AF	Investigate	CF22- 4486	Officer reviewed	1	ALARMF
204 West 200 North	02/03/2022 21:14:59	False alarm or false call, other	2AF	Investigate	CF22- 4303	Officer reviewed	2	ALARMF
204 West 200 North	01/29/2022 22:56:57	False alarm or false call, other	2AF	Investigate	CF22- 3615	Officer reviewed	1	ALARMF
204 West 200 North	01/22/2022 19:42:06	False alarm or false call, other	2AF	Investigate	CF22- 2729	Officer reviewed	1	ALARMF
204 West 200 North	01/22/2022 10:36:43	False alarm or false call, other	2AF	Investigate	CF22- 2680	Officer reviewed	1	ALARMF
204 West 200 North	01/09/2022 16:08:44	Alarm system activation, no fire - unintentional	2AF	Investigate	CF22- 1138	Officer reviewed	2	ALARMW
204 West 200 North	01/08/2022 19:40:53	Unintentional transmission of alarm, other	2AF	Investigate	CF22- 1057	Officer reviewed	1	ALARMF
Alarm Count: 13								
660 South 300 East	04/01/2022 22:17:48	Smoke detector activation, no fire - unintentional	1DF	Investigate	CF22- 11371	Officer reviewed	1	ALARMF
660 South 300 East	03/19/2022 19:11:23	Dispatched and cancelled en route	1DF	Cancelled en route	CF22- 9751	Officer reviewed	1	ALARMF
660 South 300 East		False alarm or false call, other	1DF	Investigate	CF22- 8852	Officer reviewed	1	ALARMF
660 South 300 East	02/22/2022 10:31:33	Dispatched and cancelled en route	1DF	Cancelled en route	CF22- 6583	Officer reviewed	1	ALARMF
2 of 31						D. S. L. L. O.	• 04/04/2022 (

Address	Incident Date	Incident Type	Response Zone	Primary Action Taken	Incident Number	Incident Status	Number of Apparatus	Dispatch Code
660 South 300 East	02/20/2022 07:33:32	Dispatched and cancelled en route	1DF	Cancelled en route	CF22- 6333	Officer reviewed	1	ALARMF
660 South 300 East	02/20/2022 07:30:11	Dispatched and cancelled en route	1DF	Cancelled en route	CF22- 6331	Officer reviewed	1	ALARMF
660 South 300 East	02/20/2022 07:11:31	Dispatched and cancelled en route	1DF	Cancelled en route	CF22- 6327	Officer reviewed	1	ALARMF
660 South 300 East	02/11/2022 00:07:59	Dispatched and cancelled en route	1DF	Cancelled en route	CF22- 5204	Officer reviewed	1	ALARMF
660 South 300 East	02/10/2022 05:56:16	Dispatched and cancelled en route	1DF	Cancelled en route	CF22- 5081	Officer reviewed	1	ALARMF
660 South 300 East	01/30/2022 18:55:19	False alarm or false call, other	1DF	Investigate	CF22- 3703	Officer reviewed	1	ALARMF
660 South 300 East	01/27/2022 15:28:55	Unintentional transmission of alarm, other	1DF	Investigate	CF22- 3327	Officer reviewed	2	ALARMF
660 South 300 East	01/26/2022 19:43:32	False alarm or false call, other	1DF	Investigate	CF22- 3222	Officer reviewed	1	ALARMF
660 South 300 East	01/08/2022 07:31:29	Unintentional transmission of alarm, other	1DF	Investigate	CF22- 989	Officer reviewed	1	ALARMF
Alarm Count: 10								
230 East 300 South	04/03/2022 20:20:06		1IF		CF22- 11576	Initiated	1	ALARMF
230 East 300 South	03/21/2022 14:32:36	Dispatched and cancelled en route	1IF	Cancelled en route	CF22- 9953	Officer reviewed	1	ALARMF
230 East 300 South	02/28/2022 20:48:26	Alarm system activation, no fire - unintentional	1IF	Investigate	CF22- 7358	Officer reviewed	1	ALARMF
230 East 300 South	02/24/2022 16:36:59	Unintentional transmission of alarm, other	1IF	Investigate	CF22- 6881	Officer reviewed	1	ALARMF
230 East 300 South	02/24/2022 11:18:28	Unintentional transmission of alarm, other	1IF	Investigate	CF22- 6855	Officer reviewed	1	ALARMF
230 East 300 South	02/23/2022 09:43:26	Dispatched and cancelled en route	1IF	Cancelled en route	CF22- 6712	Officer reviewed	1	ALARMF
230 East 300 South	02/20/2022 15:20:32	Dispatched and cancelled en route	1IF	Cancelled en route	CF22- 6373	Officer reviewed	1	ALARMF
230 East 300 South	01/31/2022 07:50:23	Dispatched and cancelled en route	1IF	Cancelled en route	CF22- 3752	Officer reviewed	1	ALARMF
230 East 300 South	01/23/2022 13:01:28	False alarm or false call, other	1IF	Information, investigation & enforcement, other	CF22- 2802	Officer reviewed	1	ALARMF
230 East 300 South	01/12/2022 08:11:30	Dispatched and cancelled en route	1IF	Cancelled en route	CF22- 1475	Officer reviewed	1	ALARMF
Alarm Count: 9								
350 South 200 East	04/03/2022 00:42:11	Dispatched and cancelled en route	1HF	Cancelled en route	CF22- 11492	Officer reviewed		ALARMF
350 South 200 East	03/08/2022 18:53:28	Dispatched and cancelled en route	1HF	Cancelled en route	CF22- 8411	Officer reviewed	1	ALARMF
350 South 200 East	03/03/2022 21:39:19	Dispatched and cancelled en route	1HF	Cancelled en route	CF22- 7742	Officer reviewed	1	ALARMF
350 South 200 East	02/06/2022 18:47:34	Dispatched and cancelled en route	1HF	Cancelled en route	CF22- 4664	Officer reviewed	1	ALARMF
350 South 200 East	02/05/2022 12:43:57	Dispatched and cancelled en route	1HF	Cancelled en route	CF22- 4506	Officer reviewed	1	ALARMF
350 South 200 East	02/04/2022 09:43:00	Alarm system activation, no fire - unintentional	1HF	Investigate	CF22- 4343	Officer reviewed	1	ALARMF
350 South 200 East	01/19/2022 01:01:18	Alarm system activation, no fire - unintentional	1HF	Investigate	CF22- 2326	Officer reviewed	1	ALARMF
350 South 200 East	01/09/2022 12:12:17	Smoke detector activation, no fire - unintentional	1HF	Investigate	CF22- 1124	Officer reviewed	1	ALARMF
350 South 200 East	01/06/2022 21:40:29	Alarm system activation, no fire - unintentional	1HF	Investigate	CF22- 853	Officer reviewed	1	ALARMF
404 West 700 South 3 of 31	03/15/2022	Smoke detector	6IF	Investigate	CF22-	Officer Brinted On	0	ALARMF

Address	Incident Date	Incident Type	Response Zone	Primary Action Taken	Incident Number	Incident Status	Number of Apparatus	Dispatch Code
	11:31:17	activation, no fire - unintentional		1	9200	reviewed		1
404 West 700 South	02/28/2022 08:03:24	System malfunction, other	6IF	Investigate	CF22- 7277	Officer reviewed	0	ALARMF
404 West 700 South	02/23/2022 14:16:52	Dispatched and cancelled en route	6IF	Cancelled en route	CF22- 6748	Officer reviewed	0	ALARMF
404 West 700 South	02/22/2022 07:58:01	Dispatched and cancelled en route	6IF	Cancelled en route	CF22- 6569	Officer reviewed	0	ALARMF
404 West 700 South	02/22/2022 06:48:18	Smoke detector activation due to malfunction	6IF	Investigate	CF22- 6560	Officer reviewed	1	ALARMF
404 West 700 South	01/26/2022 13:12:55	Dispatched and cancelled en route	6IF	Cancelled en route	CF22- 3180	Officer reviewed	0	ALARMF
404 West 700 South	01/22/2022 15:20:23	Smoke detector activation, no fire - unintentional	6IF	Investigate	CF22- 2709	Officer reviewed	0	ALARMF
404 West 700 South	01/15/2022 08:37:41	Dispatched and cancelled en route	6IF	Cancelled en route	CF22- 1826	Officer reviewed	1	ALARMF
404 West 700 South	01/13/2022 10:38:35	False alarm or false call, other	6IF	Investigate	CF22- 1593	Officer reviewed	1	ALARMF
999 South MAIN Street	03/28/2022 15:34:00	Dispatched and cancelled en route	8FF	Cancelled en route	CF22- 10854	Officer reviewed	1	ALARMF
999 South MAIN Street	03/12/2022 14:12:24	Alarm system sounded due to malfunction	8FF	Investigate	CF22- 8863	Officer reviewed	1	ALARMF
999 South MAIN Street	03/06/2022 09:43:42	Dispatched and cancelled en route	8FF	Cancelled en route	CF22- 8099	Officer reviewed	1	ALARMW
999 South MAIN Street	02/28/2022 09:16:04	Dispatched and cancelled en route	8FF	Cancelled en route	CF22- 7282	Officer reviewed	1	ALARMF
999 South MAIN Street	02/10/2022 18:56:37	Good intent call, other	8FF	Assistance, other	CF22- 5178	Officer reviewed	1	ALARMF
999 South MAIN Street	02/10/2022 12:29:43	False alarm or false call, other	8FF	Investigate	CF22- 5127	Officer reviewed	2	ALARMF
999 South MAIN Street	02/05/2022 18:58:08	Dispatched and cancelled en route	8FF	Cancelled en route	CF22- 4541	Officer reviewed	1	ALARMF
999 South MAIN Street	01/12/2022 16:33:33	Dispatched and cancelled en route	8FF	Cancelled en route	CF22- 1525	Officer reviewed	1	ALARMF
999 South MAIN Street	01/11/2022 14:13:16	Dispatched and cancelled en route	8FF	Cancelled en route	CF22- 1400	Officer reviewed	1	ALARMF
Alarm Count: 6								
2455 West 1500 South	04/01/2022 16:32:31	Smoke detector activation, no fire - unintentional	14BF	Investigate	CF22- 11334	Officer reviewed	1	ALARMF
2455 West 1500 South	03/26/2022 10:09:52	System malfunction, other	14BF	Investigate	CF22- 10567	Officer reviewed	1	ALARMW
2455 West 1500 South	03/21/2022 00:44:18	Alarm system sounded due to malfunction	14BF	Restore fire alarm system	CF22- 9884	Officer reviewed	2	ALARMW
2455 West 1500 South	03/20/2022 04:54:28	Alarm system activation, no fire - unintentional	14BF	Investigate	CF22- 9792	Officer reviewed	1	ALARMF
2455 West 1500 South	03/03/2022 03:14:22	Alarm system activation, no fire - unintentional	14BF	Investigate	CF22- 7641	Officer reviewed	1	ALARMW
2455 West 1500 South	01/31/2022 12:33:36	Dispatched and cancelled en route	14BF	Cancelled en route	CF22- 3787	Officer reviewed	1	ALARMF
265 South 1850 East	03/09/2022 23:45:06	Alarm system activation, no fire - unintentional	10BF	Investigate	CF22- 8552	Officer reviewed	1	ALARMF
265 South 1850 East	02/24/2022 06:35:32	Cooking fire, confined to container	10BF	Investigate	CF22- 6827	Officer reviewed	1	ALARMF
265 South 1850 East	02/08/2022 10:29:13	Dispatched and cancelled en route	10BF	Cancelled en route	CF22- 4867	Officer reviewed	1	ALARMF
265 South 1850 East	01/27/2022 14:15:27	Unintentional transmission of alarm, other	10BF	Investigate	CF22- 3318	Officer reviewed	1	ALARMF
265 South 1850 East	01/16/2022 19:48:10	Detector activation, no fire - unintentional	10BF	Investigate	CF22- 2013	Officer reviewed	1	ALARMF
265 South 1850 East	01/04/2022	Dispatched and	10BF	Cancelled en route	CF22-	Officer	1	ALARMF

Address	Incident Date	Incident Type	Response Zone	Primary Action Taken	Incident Number	Incident Status	Number of Apparatus	Dispatch Code
	13:23:29	cancelled en route			492	reviewed		1
350 South 600 East	03/13/2022 23:43:12	Smoke detector activation, no fire - unintentional	1IF	Investigate	CF22- 9037	Officer reviewed	1	ALARMF
350 South 600 East	03/12/2022 17:28:08	Smoke detector activation, no fire - unintentional	1IF	Investigate	CF22- 8884	Officer reviewed	1	ALARMF
350 South 600 East	02/28/2022 21:00:56	Alarm system activation, no fire - unintentional	1IF	Investigate	CF22- 7360	Officer reviewed	1	ALARMF
350 South 600 East	02/12/2022 20:09:39	False alarm or false call, other	1IF	Restore fire alarm system	CF22- 5458	Officer reviewed	1	ALARMF
350 South 600 East	02/01/2022 15:57:46	False alarm or false call, other	1IF	Investigate	CF22- 3988	Officer reviewed	1	ALARMF
350 South 600 East	01/11/2022 13:43:04	False alarm or false call, other	1IF	Investigate	CF22- 1397	Officer reviewed	1	ALARMF
360 West 300 South	03/18/2022 12:20:03		2CF		CF22- 9575	Initiated	2	ALARMF
360 West 300 South	03/18/2022 09:30:22		2CF		CF22- 9562	Initiated	1	ALARMF
360 West 300 South	03/15/2022 18:09:54	Alarm system sounded due to malfunction	2CF	Investigate	CF22- 9232	Officer reviewed	1	ALARMF
360 West 300 South	02/12/2022 18:32:26	False alarm or false call, other	2CF	Investigate	CF22- 5445	Officer reviewed	1	ALARMF
360 West 300 South	02/09/2022 18:25:57	False alarm or false call, other	2CF	Investigate	CF22- 5031	Officer reviewed	1	ALARMF
360 West 300 South	02/03/2022 05:22:07	False alarm or false call, other	2CF	Investigate	CF22- 4186	Officer reviewed	1	ALARMF
500 South MAIN Street	03/22/2022 18:57:06	Dispatched and cancelled en route	8LF	Cancelled en route	CF22- 10102	Officer reviewed	1	ALARMF
500 South MAIN Street	02/21/2022 10:14:52	Dispatched and cancelled en route	8LF	Cancelled en route	CF22- 6455	Officer reviewed	1	ALARMF
500 South MAIN Street	02/02/2022 07:12:04	Dispatched and cancelled en route	8LF	Cancelled en route	CF22- 4058	Officer reviewed	1	ALARMF
500 South MAIN Street	02/02/2022 06:52:01	Dispatched and cancelled en route	8LF	Cancelled en route	CF22- 4055	Officer reviewed	1	ALARMF
500 South MAIN Street	01/14/2022 14:11:14	Dispatched and cancelled en route	8LF	Cancelled en route	CF22- 1737	Officer reviewed	1	ALARMF
500 South MAIN Street	01/14/2022 13:35:30	Dispatched and cancelled en route	8LF	Cancelled en route	CF22- 1730	Officer reviewed	1	ALARMF
57 South 500 West	03/01/2022 10:09:26	Dispatched and cancelled en route	2AF	Cancelled en route	CF22- 7402	Officer reviewed	1	ALARMF
57 South 500 West	03/01/2022 09:46:13	Dispatched and cancelled en route	2AF	Cancelled en route	CF22- 7400	Officer reviewed	1	ALARMF
57 South 500 West	02/12/2022 20:13:49	Dispatched and cancelled en route	2AF	Cancelled en route	CF22- 5461	Officer reviewed	1	ALARMF
57 South 500 West	01/31/2022 08:51:16	Alarm system activation, no fire - unintentional	2AF	Investigate	CF22- 3760	Officer reviewed	1	ALARMF
57 South 500 West	01/27/2022 15:43:21	Dispatched and cancelled en route	2AF	Cancelled en route	CF22- 3333	Officer reviewed	1	ALARMF
57 South 500 West	01/27/2022 13:44:37	Dispatched and cancelled en route	2AF	Cancelled en route	CF22- 3315	Officer reviewed	1	ALARMF
777 East SOUTH TEMPLE Street	03/28/2022 18:36:15	Good intent call, other	1KF	Investigate	CF22- 10878	Officer reviewed	1	ALARMF
777 East SOUTH TEMPLE Street	03/25/2022 12:25:17	Dispatched and cancelled en route	1KF	Cancelled en route	CF22- 10449	Officer reviewed	1	ALARMF
777 East SOUTH TEMPLE Street	02/22/2022 03:40:59	Smoke detector activation, no fire - unintentional	1KF	Investigate	CF22- 6542	Officer reviewed	1	ALARMF
777 East SOUTH TEMPLE Street	02/15/2022 23:26:26	Smoke detector activation due to malfunction	1KF	Investigate	CF22- 5797	Officer reviewed	1	ALARMF
777 East SOUTH TEMPLE Street	02/12/2022 14:51:27	False alarm or false call, other	1KF	Restore fire alarm system	CF22- 5420	Officer reviewed	1	ALARMF
777 East SOUTH TEMPLE	02/12/2022	False alarm or false call,	1KF	Restore fire alarm	CF22-	Officer	1	ALARMF

Address	Incident Date	Incident Type	Response Zone	Primary Action Taken	Incident Number	Incident Status	Number of Apparatus	Dispatch Code
Street	13:21:26	other		system	5410	reviewed		
90 South RIO GRANDE Street	03/13/2022 16:49:40	Dispatched and cancelled en route	2AF	Cancelled en route	CF22- 8998	Officer reviewed	1	ALARMF
90 South RIO GRANDE Street	03/03/2022 19:00:44	Dispatched and cancelled en route	2AF	Cancelled en route	CF22- 7728	Officer reviewed	1	ALARMF
90 South RIO GRANDE Street	03/01/2022 19:51:45	Dispatched and cancelled en route	2AF	Cancelled en route	CF22- 7482	Officer reviewed	1	ALARMF
90 South RIO GRANDE Street	02/21/2022 20:28:10	Dispatched and cancelled en route	2AF	Cancelled en route	CF22- 6510	Officer reviewed	1	ALARMF
90 South RIO GRANDE Street	02/15/2022 16:25:10	Dispatched and cancelled en route	2AF	Cancelled en route	CF22- 5744	Officer reviewed	1	ALARMF
90 South RIO GRANDE Street	02/11/2022 12:28:01	Dispatched and cancelled en route	2AF	Cancelled en route	CF22- 5275	Officer reviewed	1	ALARMF
Alarm Count: 5								
1212 East WILMINGTON Avenue	03/21/2022 08:32:21	Dispatched and cancelled en route	3CF	Cancelled en route	CF22- 9914	Officer reviewed	1	ALARMF
1212 East WILMINGTON Avenue	02/28/2022 12:21:07	Dispatched and cancelled en route	3CF	Cancelled en route	CF22- 7302	Officer reviewed	1	ALARMF
1212 East WILMINGTON Avenue	02/18/2022 15:17:17	Dispatched and cancelled en route	3CF	Cancelled en route	CF22- 6101	Officer reviewed	1	ALARMW
1212 East WILMINGTON Avenue	02/14/2022 15:50:04	Dispatched and cancelled en route	3CF	Cancelled en route	CF22- 5651	Officer reviewed	1	ALARMF
1212 East WILMINGTON Avenue	01/05/2022 17:48:29	Sprinkler activation, no fire - unintentional	3CF	Shut down system	CF22- 674	Officer reviewed	1	ALARMF
1755 South FREMONT Drive	03/09/2022 17:55:52	Dispatched and cancelled en route	14BF	Cancelled en route	CF22- 8509	Officer reviewed	1	ALARMF
1755 South FREMONT Drive	03/07/2022 18:31:02	Dispatched and cancelled en route	14BF	Cancelled en route	CF22- 8302	Officer reviewed	1	ALARMF
1755 South FREMONT Drive	02/03/2022 17:59:42	Dispatched and cancelled en route	14BF	Cancelled en route	CF22- 4288	Officer reviewed	1	ALARMF
1755 South FREMONT Drive	01/06/2022 18:17:11	Dispatched and cancelled en route	14BF	Cancelled en route	CF22- 822	Officer reviewed	1	ALARMF
1755 South FREMONT Drive	01/05/2022 18:15:07	Dispatched and cancelled en route	14BF	Cancelled en route	CF22- 676	Officer reviewed	1	ALARMF
2000 East CIRCLE OF HOPE Drive	03/24/2022 07:47:43	Dispatched and cancelled en route	4EF	Cancelled en route	CF22- 10274	Officer reviewed	1	ALARMF
2000 East CIRCLE OF HOPE Drive	03/06/2022 14:01:30	Water problem, other	4EF	Investigate	CF22- 8139	Officer reviewed	1	ALARMF
2000 East CIRCLE OF HOPE Drive	03/06/2022 13:24:14	Water problem, other	4EF	Investigate	CF22- 8134	Officer reviewed	2	ALARMW
2000 East CIRCLE OF HOPE Drive	02/16/2022 06:47:07	Dispatched and cancelled en route	4EF	Cancelled en route	CF22- 5814	Officer reviewed	1	ALARMF
2000 East CIRCLE OF HOPE Drive	02/15/2022 17:15:06	False alarm or false call, other	4EF	Information, investigation & enforcement, other	CF22- 5749	Officer reviewed	1	ALARMF
2001 North WARM SPRINGS Road	02/09/2022 12:35:50	Dispatched and cancelled en route	2FF	Cancelled en route	CF22- 4998	Officer reviewed	2	ALARMW
2001 North WARM SPRINGS Road	02/07/2022 08:56:01	Dispatched and cancelled en route	2FF	Cancelled en route	CF22- 4718	Officer reviewed	2	ALARMW
2001 North WARM SPRINGS Road	01/23/2022 09:56:52	Dispatched and cancelled en route	2FF	Cancelled en route	CF22- 2788	Officer reviewed	2	ALARMW
2001 North WARM SPRINGS Road	01/20/2022 06:41:02	Dispatched and cancelled en route	2FF	Cancelled en route	CF22- 2454	Officer reviewed	1	ALARMF
2001 North WARM SPRINGS Road	01/09/2022 11:30:40	False alarm or false call, other	2FF	Investigate	CF22- 1118	Officer reviewed	1	ALARMF
274 West 200 South	03/30/2022 17:13:26		2GF		CF22- 11073	Initiated	1	ALARMF
274 West 200 South	02/04/2022 04:52:01	Smoke detector activation, no fire - unintentional	2GF	Investigate	CF22- 4322	Officer reviewed	1	ALARMF
274 West 200 South	01/13/2022 14:33:39	Dispatched and cancelled en route	2GF	Cancelled en route	CF22- 1614	Officer reviewed	1	ALARMF
274 West 200 South	01/08/2022 11:42:55	Dispatched and cancelled en route	2GF	Cancelled en route	CF22- 1007	Officer reviewed	1	ALARMF

Address	Incident Date	Incident Type	Response Zone	Primary Action Taken	Incident Number	Incident Status	Number of Apparatus	Dispatch Code
274 West 200 South	01/08/2022 08:30:01	Unintentional transmission of alarm, other	2GF	Investigate	CF22- 991	Officer reviewed	1	ALARMF
3405 West 900 South	03/02/2022 17:05:49	Dispatched and cancelled en route	14EF	Cancelled en route	CF22- 7577	Officer reviewed	2	ALARMW
3405 West 900 South	02/28/2022 02:41:36	False alarm or false call, other	14EF	Investigate	CF22- 7264	Officer reviewed	1	ALARMW
3405 West 900 South	02/05/2022 17:39:09	Water or steam leak	14EF	Investigate	CF22- 4535	Officer reviewed	2	ALARMW
3405 West 900 South	01/18/2022 05:20:30	Dispatched and cancelled en route	14EF	Cancelled en route	CF22- 2206	Officer reviewed	1	ALARMF
3405 West 900 South	01/04/2022 04:47:47	Dispatched and cancelled en route	14EF	Cancelled en route	CF22- 433	Officer reviewed	2	ALARMW
50 North MEDICAL Drive	03/29/2022 08:44:02	Dispatched and cancelled en route	4EF	Cancelled en route	CF22- 10934	Officer reviewed	1	ALARMF
50 North MEDICAL Drive	03/21/2022 14:13:10	False alarm or false call, other	4EF	Information, investigation & enforcement, other	CF22- 9952	Officer reviewed	1	ALARMF
50 North MEDICAL Drive	03/11/2022 13:42:09	Dispatched and cancelled en route	4EF	Cancelled en route	CF22- 8727	Officer reviewed	1	ALARMF
50 North MEDICAL Drive	02/16/2022 12:35:31	Detector activation, no fire - unintentional	4EF	Action taken, other	CF22- 5841	Officer reviewed	1	ALARMF
50 North MEDICAL Drive	02/10/2022 08:00:33	Dispatched and cancelled en route	4EF	Cancelled en route	CF22- 5089	Officer reviewed	2	ALARMF
55 South REDWOOD Road	02/13/2022 19:23:20	Dispatched and cancelled en route	7CF	Cancelled en route	CF22- 5559	Officer reviewed	1	ALARMF
55 South REDWOOD Road	02/13/2022 04:56:18	Dispatched and cancelled en route	7CF	Cancelled en route	CF22- 5494	Officer reviewed	1	ALARMF
55 South REDWOOD Road	02/08/2022 10:31:34	Dispatched and cancelled en route	7CF	Cancelled en route	CF22- 4869	Officer reviewed	1	ALARMF
55 South REDWOOD Road	02/04/2022 13:44:28	Dispatched and cancelled en route	7CF	Cancelled en route	CF22- 4371	Officer reviewed	1	ALARMF
55 South REDWOOD Road	01/04/2022 05:27:29	Dispatched and cancelled en route	7CF	Cancelled en route	CF22- 437	Officer reviewed	1	ALARMF
75 South WEST TEMPLE Street	03/11/2022 10:11:06	Dispatched and cancelled en route	2GF	Cancelled en route	CF22- 8698	Officer reviewed	1	ALARMF
75 South WEST TEMPLE Street	02/04/2022 07:26:54	Dispatched and cancelled en route	2GF	Cancelled en route	CF22- 4328	Officer reviewed	1	ALARMF
75 South WEST TEMPLE Street	02/01/2022 11:52:20	False alarm or false call, other	2GF	Investigate	CF22- 3960	Officer reviewed	1	ALARMF
75 South WEST TEMPLE Street	01/18/2022 23:38:45	Dispatched and cancelled en route	2GF	Cancelled en route	CF22- 2321	Officer reviewed	1	ALARMF
75 South WEST TEMPLE Street	01/05/2022 11:35:24	Dispatched and cancelled en route	2GF	Cancelled en route	CF22- 619	Officer reviewed	1	ALARMF
844 South WEST TEMPLE Street	01/17/2022 18:56:28	Dispatched and cancelled en route	8EF	Cancelled en route	CF22- 2144	Officer reviewed	1	ALARMF
844 South WEST TEMPLE Street	01/17/2022 18:10:50	False alarm or false call, other	8EF	Restore fire alarm system	CF22- 2139	Officer reviewed	1	ALARMF
844 South WEST TEMPLE Street	01/17/2022 16:18:27	False alarm or false call, other	8EF	Restore fire alarm system	CF22- 2129	Officer reviewed	1	ALARMF
844 South WEST TEMPLE Street	01/15/2022 04:56:13	Heat detector activation due to malfunction	8EF	Investigate	CF22- 1816	Officer reviewed	1	ALARMF
844 South WEST TEMPLE Street	01/15/2022 04:21:21	Heat detector activation due to malfunction	8EF	Investigate	CF22- 1812	Officer reviewed	1	ALARMF
866 West SOUTH TEMPLE Street	03/26/2022 19:14:06	Dispatched and cancelled en route	7BF	Cancelled en route	CF22- 10627	Officer reviewed	1	ALARMF
866 West SOUTH TEMPLE Street	03/26/2022 18:30:07	Dispatched and cancelled en route	7BF	Cancelled en route	CF22- 10621	Officer reviewed	1	ALARMF
866 West SOUTH TEMPLE Street	02/27/2022 20:38:31	Dispatched and cancelled en route	7BF	Cancelled en route	CF22- 7246	Officer reviewed	1	ALARMF
866 West SOUTH TEMPLE Street	01/31/2022 07:12:55	False alarm or false call, other	7BF	Investigate	CF22- 3750	Officer reviewed	1	ALARMF
866 West SOUTH TEMPLE Street	01/27/2022 12:16:52	Dispatched and cancelled en route	7BF	Cancelled en route	CF22- 3305	Officer reviewed	2	ALARMF

Address	Incident Date	Incident Type	Response Zone	Primary Action Taken	Incident Number	Incident Status	Number of Apparatus	Dispatch Code
Alarm Count: 4								
1169 East WILMINGTON Avenue	03/07/2022 20:32:45	False alarm or false call, other	3CF	Investigate	CF22- 8310	Officer reviewed	1	ALARMF
1169 East WILMINGTON Avenue	03/05/2022 04:24:15	Alarm system activation, no fire - unintentional	3CF	Investigate	CF22- 7869	Officer reviewed	1	ALARMF
1169 East WILMINGTON Avenue	03/05/2022 03:21:02	Alarm system activation, no fire - unintentional	3CF	Investigate	CF22- 7865	Officer reviewed	1	ALARMF
1169 East WILMINGTON Avenue	02/22/2022 21:07:06	False alarm or false call, other	3CF	Investigate	CF22- 6651	Officer reviewed	1	ALARMF
120 South 300 East	03/24/2022 09:18:47	Alarm system activation, no fire - unintentional	1GF	Investigate	CF22- 10283	Officer reviewed	1	ALARMF
120 South 300 East	02/23/2022 14:12:43	Alarm system activation, no fire - unintentional	1GF	Investigate	CF22- 6747	Officer reviewed	1	ALARMF
120 South 300 East	01/27/2022 15:21:17	False alarm or false call, other	1GF	Investigate	CF22- 3326	Officer reviewed	1	ALARMF
120 South 300 East	01/15/2022 00:59:51	False alarm or false call, other	1GF	Investigate	CF22- 1802	Officer reviewed	1	ALARMF
125 South 300 East	03/16/2022 14:16:52	Detector activation, no fire - unintentional	1GF	Investigate	CF22- 9331	Officer reviewed	1	ALARMF
125 South 300 East		False alarm or false call, other	1GF	Investigate	CF22- 9198	Officer reviewed	1	ALARMF
125 South 300 East	03/15/2022 01:24:47	False alarm or false call, other	1GF	Investigate	CF22- 9158	Officer reviewed	1	ALARMF
125 South 300 East	03/15/2022 00:31:52	False alarm or false call, other	1GF	Investigate	CF22- 9156	Officer reviewed	1	ALARMF
136 East SOUTH TEMPLE Street	03/07/2022 14:17:30	Dispatched and cancelled en route	1AF	Cancelled en route	CF22- 8273	Officer reviewed	1	ALARMF
136 East SOUTH TEMPLE Street	03/07/2022 10:23:37	Dispatched and cancelled en route	1AF	Cancelled en route	CF22- 8243	Officer reviewed	1	ALARMF
136 East SOUTH TEMPLE Street	02/23/2022 15:37:32	Dispatched and cancelled en route	1AF	Cancelled en route	CF22- 6756	Officer reviewed	1	ALARMF
136 East SOUTH TEMPLE Street	02/20/2022 03:01:04	False alarm or false call, other	1AF	Investigate	CF22- 6312	Officer reviewed	1	ALARMF
1710 South FOOTHILL Drive	03/06/2022 04:50:34	False alarm or false call, other	13AF	Information, investigation & enforcement, other	CF22- 8043	Officer reviewed	1	ALARMW
1710 South FOOTHILL Drive	02/11/2022 00:56:51	Alarm system sounded due to malfunction	13AF	Investigate	CF22- 5206	Officer reviewed	2	ALARMW
1710 South FOOTHILL Drive	02/10/2022 06:46:40	Alarm system activation, no fire - unintentional	13AF	Investigate	CF22- 5084	Officer reviewed	2	ALARMW
1710 South FOOTHILL Drive	01/31/2022 12:11:05	Dispatched and cancelled en route	13AF	Cancelled en route	CF22- 3781	Officer reviewed	2	ALARMW
20 South 400 West	03/12/2022 03:50:02	Alarm system sounded due to malfunction	2AF	Investigate	CF22- 8819	Officer reviewed	1	ALARMF
20 South 400 West	02/01/2022 07:12:55	Dispatched and cancelled en route	2AF	Cancelled en route	CF22- 3930	Officer reviewed	1	ALARMF
20 South 400 West	01/29/2022 23:34:27	False alarm or false call, other	2AF	Investigate	CF22- 3618	Officer reviewed	1	ALARMF
20 South 400 West	01/26/2022 13:11:13	Dispatched and cancelled en route	2AF	Cancelled en route	CF22- 3179	Officer reviewed	1	ALARMF
209 East 500 South	04/03/2022 18:14:09		1DF		CF22- 11563	Initiated	1	ALARMF
209 East 500 South	02/06/2022 07:27:21	Alarm system activation, no fire - unintentional	1DF	Investigate	CF22- 4607	Officer reviewed	1	ALARMF
209 East 500 South	02/05/2022 07:25:55	Alarm system activation, no fire - unintentional	1DF	Investigate	CF22- 4484	Officer reviewed	1	ALARMF
209 East 500 South	01/22/2022 07:24:25	Smoke detector activation, no fire - unintentional	1DF	Investigate	CF22- 2668	Officer reviewed	1	ALARMF
28 South STATE Street	03/30/2022 12:32:11		1AF		CF22- 11045	Initiated	1	ALARMF
28 South STATE Street	02/28/2022 09:31:59	Dispatched and cancelled en route	1AF	Cancelled en route	CF22- 7286	Officer reviewed	1	ALARMF
28 South STATE Street	02/11/2022 16:42:55	Dispatched and cancelled en route	1AF	Cancelled en route	CF22- 5306	Officer reviewed	1	ALARMF
8 of 31							: 04/04/2022 0	0 00 47 44

Address	Incident Date	Incident Type	Response Zone	Primary Action Taken	Incident Number	Incident Status	Number of Apparatus	Dispatch Code
28 South STATE Street	01/27/2022 08:56:41	Dispatched and cancelled en route	1AF	Cancelled en route	CF22- 3283	Officer reviewed	1	ALARMF
331 East SOUTH TEMPLE Street	02/05/2022 03:50:53	Alarm system activation, no fire - unintentional	1JF	Investigate	CF22- 4469	Officer reviewed	1	ALARMF
331 East SOUTH TEMPLE Street	02/05/2022 02:05:38	Alarm system activation, no fire - unintentional	1JF	Investigate	CF22- 4455	Officer reviewed	1	ALARMF
331 East SOUTH TEMPLE Street	02/02/2022 12:21:07	Dispatched and cancelled en route	1JF	Cancelled en route	CF22- 4086	Officer reviewed	1	ALARMF
331 East SOUTH TEMPLE Street	01/23/2022 13:54:52	Alarm system activation, no fire - unintentional	1JF	Investigate	CF22- 2809	Officer reviewed	1	ALARMF
360 South STATE Street	03/30/2022 12:31:25	Alarm system activation, no fire - unintentional	1HF	Investigate	CF22- 11044	Officer reviewed	1	ALARMF
360 South STATE Street	01/28/2022 16:46:23	Dispatched and cancelled en route	1HF	Cancelled en route	CF22- 3467	Officer reviewed	1	ALARMF
360 South STATE Street	01/22/2022 18:22:03	Dispatched and cancelled en route	1HF	Cancelled en route	CF22- 2724	Officer reviewed	1	ALARMF
360 South STATE Street	01/19/2022 10:05:55	Dispatched and cancelled en route	1HF	Cancelled en route	CF22- 2355	Officer reviewed	1	ALARMF
3780 West DIRECTORS Row	02/14/2022 11:26:56	Smoke detector activation due to malfunction	14EF	Investigate	CF22- 5620	Officer reviewed	1	ALARMF
3780 West DIRECTORS Row	02/10/2022 01:05:46	Unintentional transmission of alarm, other	14EF	Investigate	CF22- 5065	Officer reviewed	1	ALARMF
3780 West DIRECTORS Row	01/24/2022 09:45:38	System malfunction, other	14EF	Investigate	CF22- 2900	Officer reviewed	1	ALARMF
3780 West DIRECTORS Row	01/04/2022 17:42:34	Dispatched and cancelled en route	14EF	Cancelled en route	CF22- 531	Officer reviewed	1	ALARMF
435 South 400 East	03/14/2022 14:03:39	Dispatched and cancelled en route	1IF	Cancelled en route	CF22- 9100	Officer reviewed	1	ALARMF
435 South 400 East	03/11/2022 21:36:21	Smoke detector activation, no fire - unintentional	1IF	Investigate	CF22- 8781	Officer reviewed	1	ALARMF
435 South 400 East	02/23/2022 16:17:18	Dispatched and cancelled en route	1IF	Cancelled en route	CF22- 6760	Officer reviewed	1	ALARMF
435 South 400 East	02/22/2022 16:15:18	Dispatched and cancelled en route	1IF	Cancelled en route	CF22- 6619	Officer reviewed	1	ALARMF
511 West 400 North	03/21/2022 20:33:34	False alarm or false call, other	2AF	Restore fire alarm system	CF22- 9999	Officer reviewed	1	ALARMF
511 West 400 North	02/04/2022 16:37:08	False alarm or false call, other	2AF	Investigate	CF22- 4406	Officer reviewed	1	ALARMW
511 West 400 North	02/04/2022 14:08:00	Water or steam leak	2AF	Remove water	CF22- 4379	Officer reviewed	2	ALARMW
511 West 400 North	01/28/2022 08:06:08	Dispatched and cancelled en route	2AF	Cancelled en route	CF22- 3409	Officer reviewed	1	ALARMF
5433 West WILEY POST Way	02/18/2022 10:39:47	System malfunction, other	9AF	Investigate	CF22- 6063	Officer reviewed	1	ALARMF
5433 West WILEY POST Way	02/08/2022 18:53:28	Dispatched and cancelled en route	9AF	Cancelled en route	CF22- 4922	Officer reviewed	1	ALARMF
5433 West WILEY POST Way	02/07/2022 11:51:23	System malfunction, other	9AF	Investigate	CF22- 4734	Officer reviewed	1	ALARMF
5433 West WILEY POST Way	02/01/2022 16:32:02	Dispatched and cancelled en route	9AF	Cancelled en route	CF22- 3994	Officer reviewed	1	ALARMF
555 South MAIN Street	03/31/2022 11:55:26	Dispatched and cancelled en route	8LF	Cancelled en route	CF22- 11163	Officer reviewed	1	ALARMF
555 South MAIN Street	03/24/2022 10:19:31	Dispatched and cancelled en route	8LF	Cancelled en route	CF22- 10291	Officer reviewed	1	ALARMF
555 South MAIN Street	03/17/2022 15:07:50	False alarm or false call, other	8LF	Investigate	CF22- 9466	Officer reviewed	1	ALARMF
555 South MAIN Street	01/19/2022 09:54:29	Smoke detector activation due to malfunction	8LF	Investigate	CF22- 2352	Officer reviewed	1	ALARMF

Alarm Count: 3

Address	Incident Date	Incident Type	Response Zone	Primary Action Taken	Incident Number	Incident Status	Number of Apparatus	Dispatch Code
1025 East 2100 South	02/23/2022 08:25:26	False alarm or false call, other	3BF	Investigate	CF22- 6701	Officer reviewed	1	ALARMF
1025 East 2100 South	02/21/2022 20:56:06	False alarm or false call, other	3BF	Investigate	CF22- 6517	Officer reviewed	1	ALARMF
1025 East 2100 South	02/06/2022 18:45:46	Dispatched and cancelled en route	3BF	Cancelled en route	CF22- 4663	Officer reviewed	1	ALARMF
130 South 500 East	03/06/2022 11:06:07	Alarm system sounded due to malfunction	1GF	Investigate	CF22- 8113	Officer reviewed	1	ALARMF
130 South 500 East	02/05/2022 04:58:17	Alarm system activation, no fire - unintentional	1GF	Investigate	CF22- 4475	Officer reviewed	1	ALARMF
130 South 500 East	02/05/2022 03:36:30	Alarm system activation, no fire - unintentional	1GF	Investigate	CF22- 4468	Officer reviewed	1	ALARMF
1381 East PENROSE Drive	03/26/2022 19:34:37	Dispatched and cancelled en route	4BF	Cancelled en route	CF22- 10633	Officer reviewed	1	ALARMF
1381 East PENROSE Drive	02/26/2022 08:37:02	Dispatched and cancelled en route	4BF	Cancelled en route	CF22- 7068	Officer reviewed	1	ALARMF
1381 East PENROSE Drive	02/26/2022 08:28:38	Dispatched and cancelled en route	4BF	Cancelled en route	CF22- 7067	Officer reviewed	1	ALARMF
1450 South WEST TEMPLE Street	03/24/2022 20:03:00	Carbon monoxide incident	8IF	Investigate	CF22- 10376	Officer reviewed	1	ALARMF
1450 South WEST TEMPLE Street	03/23/2022 04:30:36	Smoke scare, odor of smoke	8IF	Investigate	CF22- 10139	Officer reviewed	5	ALARMF
1450 South WEST TEMPLE Street	03/02/2022 22:57:55	Smoke detector activation due to malfunction	8IF	Investigate	CF22- 7621	Officer reviewed	1	ALARMF
150 West 500 South	04/01/2022 09:28:17	Dispatched and cancelled en route	2DF	Cancelled en route	CF22- 11293	Officer reviewed	1	ALARMF
150 West 500 South	01/20/2022 00:57:24	Water problem, other	2DF	Shut down system	CF22- 2441	Officer reviewed	1	ALARMF
150 West 500 South	01/11/2022 09:36:25	Dispatched and cancelled en route	2DF	Cancelled en route	CF22- 1368	Officer reviewed	1	ALARMF
1675 South EMPIRE Road	03/12/2022 01:30:36	False alarm or false call, other	14BF	Investigate	CF22- 8810	Officer reviewed	1	ALARMF
1675 South EMPIRE Road	03/08/2022 03:17:07	Alarm system sounded due to malfunction	14BF	Investigate	CF22- 8328	Officer reviewed	1	ALARMF
1675 South EMPIRE Road	01/13/2022 17:47:53	Alarm system activation, no fire - unintentional	14BF	Investigate	CF22- 1638	Officer reviewed	1	ALARMF
175 South 300 East	04/03/2022 13:02:32		1GF		CF22- 11537	Initiated	1	ALARMF
175 South 300 East	03/23/2022 14:47:07	Smoke detector activation, no fire - unintentional	1GF	Investigate	CF22- 10199	Officer reviewed	1	ALARMF
175 South 300 East	02/04/2022 14:14:20	Smoke detector activation, no fire - unintentional	1GF	Investigate	CF22- 4380	Officer reviewed	1	ALARMF
175 South WEST TEMPLE Street	02/12/2022 12:59:03	False alarm or false call, other	2GF	Investigate	CF22- 5407	Officer reviewed	1	ALARMF
175 South WEST TEMPLE Street	02/03/2022 14:22:42	Dispatched and cancelled en route	2GF	Cancelled en route	CF22- 4261	Officer reviewed	1	ALARMF
175 South WEST TEMPLE Street	01/07/2022 07:43:00	False alarm or false call, other	2GF	Incident command	CF22- 882	Officer reviewed	1	ALARMF
202 West 300 South	02/12/2022 20:50:37	Dispatched and cancelled en route	2CF	Cancelled en route	CF22- 5465	Officer reviewed	1	ALARMF
202 West 300 South	02/05/2022 19:35:31	Dispatched and cancelled en route	2CF	Cancelled en route	CF22- 4549	Officer reviewed	1	ALARMF
202 West 300 South	01/22/2022 16:02:06	Dispatched and cancelled en route	2CF	Cancelled en route	CF22- 2712	Officer reviewed	1	ALARMF
2166 South 1700 East	02/04/2022 14:34:48	Dispatched and cancelled en route	13BF	Cancelled en route	CF22- 4385	Officer reviewed	1	ALARMF
2166 South 1700 East		Building fire	13BF	Investigate	CF22- 4367	Officer reviewed	2	ALARMF
2166 South 1700 East	01/10/2022 22:07:33	Alarm system activation, no fire - unintentional	13BF	Investigate	CF22- 1323	Officer reviewed	1	ALARMF
223 North JIMMY DOOLITTLE	03/05/2022	False alarm or false call,	9AF	Investigate	CF22-	Officer	1	ALARMF

Address	Incident Date	Incident Type	Response Zone	Primary Action Taken	Incident Number	Incident Status	Number of Apparatus	Dispatch Code
Road	19:29:47	other			7956	reviewed		
223 North JIMMY DOOLITTLE Road	02/04/2022 15:26:53	Alarm system activation, no fire - unintentional	9AF	Investigate	CF22- 4393	Officer reviewed	1	ALARMF
223 North JIMMY DOOLITTLE Road	01/17/2022 01:47:16	Dispatched and cancelled en route	9AF	Cancelled en route	CF22- 2049	Officer reviewed	1	ALARMF
2333 West NORTH TEMPLE Street	02/16/2022 16:37:10	Dispatched and cancelled en route	11AF	Cancelled en route	CF22- 5866	Officer reviewed	1	ALARMF
2333 West NORTH TEMPLE Street	02/09/2022 15:41:30	Dispatched and cancelled en route	11AF	Cancelled en route	CF22- 5015	Officer reviewed	1	ALARMF
2333 West NORTH TEMPLE Street	01/05/2022 12:28:04	Detector activation, no fire - unintentional	11AF	Investigate	CF22- 631	Officer reviewed	1	ALARMF
242 West PARAMOUNT Avenue	02/15/2022 22:23:55	False alarm or false call, other	8IF	Investigate	CF22- 5791	Officer reviewed	0	ALARMF
242 West PARAMOUNT Avenue	02/08/2022 08:23:50	Dispatched and cancelled en route	8IF	Cancelled en route	CF22- 4849	Officer reviewed	0	ALARMF
242 West PARAMOUNT Avenue	01/11/2022 23:41:07	Malicious, mischievous false call, other	8IF	Information, investigation & enforcement, other	CF22- 1449	Officer reviewed	1	ALARMF
326 West 700 South	02/06/2022 17:59:05	Dispatched and cancelled en route	6IF	Cancelled en route	CF22- 4657	Officer reviewed	0	ALARMF
326 West 700 South	01/19/2022 22:10:36	Dispatched and cancelled en route	6IF	Cancelled en route	CF22- 2426	Officer reviewed	0	ALARMF
326 West 700 South	01/15/2022 06:59:43	Dispatched and cancelled en route	6IF	Cancelled en route	CF22- 1820	Officer reviewed	0	ALARMF
327 West 200 South	01/17/2022 15:05:25	System malfunction, other	2CF	Investigate	CF22- 2122	Officer reviewed	0	ALARMF
327 West 200 South	01/13/2022 17:43:41	Dispatched and cancelled en route	2CF	Cancelled en route	CF22- 1636	Officer reviewed	1	ALARMF
327 West 200 South	01/12/2022 17:43:41	False alarm or false call, other	2CF	Incident command	CF22- 1530	Officer reviewed	1	ALARMF
360 South 200 West	03/14/2022 12:53:19	Dispatched and cancelled en route	2CF	Cancelled en route	CF22- 9094	Officer reviewed	1	ALARMF
360 South 200 West	03/12/2022 23:11:24		2CF		CF22- 8920	Initiated	0	ALARMF
360 South 200 West	02/23/2022 15:10:53	Dispatched and cancelled en route	2CF	Cancelled en route	CF22- 6753	Officer reviewed	1	ALARMF
37 North 2000 East	03/24/2022 10:52:33	Dispatched and cancelled en route	4EF	Cancelled en route	CF22- 10292	Officer reviewed	1	ALARMF
37 North 2000 East	03/23/2022 17:50:19	Dispatched and cancelled en route	4EF	Cancelled en route	CF22- 10218	Officer reviewed	1	ALARMF
37 North 2000 East	03/04/2022 13:12:09	Dispatched and cancelled en route	4EF	Cancelled en route	CF22- 7807	Officer reviewed	1	ALARMF
379 North REDWOOD Road	03/21/2022 21:44:34	Cooking fire, confined to container	11AF	Fire control or extinguishment, other	CF22- 10005	Officer reviewed	1	ALARMF
379 North REDWOOD Road	01/28/2022 10:29:14	Detector activation, no fire - unintentional	11AF	Investigate	CF22- 3424	Officer reviewed	1	ALARMF
379 North REDWOOD Road	01/19/2022 23:30:04	Dispatched and cancelled en route	11AF	Cancelled en route	CF22- 2433	Officer reviewed	1	ALARMF
593 North WRIGHT BROTHERS Drive	02/25/2022 15:02:25	False alarm or false call, other	9AF	Investigate	CF22- 7002	Officer reviewed	1	ALARMF
593 North WRIGHT BROTHERS Drive	01/29/2022 02:27:43	Dispatched and cancelled en route	9AF	Cancelled en route	CF22- 3519	Officer reviewed	1	ALARMF
593 North WRIGHT BROTHERS Drive	01/28/2022 10:51:38	Alarm system sounded due to malfunction	9AF	Investigate	CF22- 3427	Officer reviewed	1	ALARMW
602 East 500 South	03/27/2022 02:48:28	Steam, other gas mistaken for smoke, other	5AF	Investigate	CF22- 10673	Officer reviewed	1	ALARMF
602 East 500 South	02/07/2022 11:16:58	Water or steam leak	5AF	Investigate	CF22- 4729	Officer reviewed	2	ALARMW
602 East 500 South	01/04/2022 10:32:36	Alarm system activation, no fire - unintentional	5AF	Investigate	CF22- 470	Officer reviewed	2	ALARMW
702 South MAIN Street	03/18/2022 09:00:49	Detector activation, no fire - unintentional	8BF	Investigate	CF22- 9561	Officer reviewed	1	ALARMW
702 South MAIN Street	03/17/2022	Dispatched and	8BF	Cancelled en route	CF22-	Officer	3	ALARMW

Address	Incident Date	Incident Type	Response Zone	Primary Action Taken	Incident Number	Incident Status	Number of Apparatus	Dispatch Code
	18:15:42	cancelled en route			9496	reviewed		
702 South MAIN Street	03/11/2022 18:13:17	Service call, other	8BF	Assistance, other	CF22- 8757	Officer reviewed	1	ALARMF
727 East 600 South	03/30/2022 18:07:18	System malfunction, other	5AF	Investigate	CF22- 11077	Officer reviewed	1	ALARMF
727 East 600 South	02/15/2022 21:39:54	False alarm or false call, other	5AF	Investigate	CF22- 5783	Officer reviewed	1	ALARMF
727 East 600 South	01/23/2022 14:04:58	False alarm or false call, other	5AF	Restore fire alarm system	CF22- 2813	Officer reviewed	1	ALARMF
750 West SOUTH TEMPLE Street	03/26/2022 16:28:58	False alarm or false call, other	7BF	Investigate	CF22- 10607	Officer reviewed	1	ALARMF
750 West SOUTH TEMPLE Street	03/08/2022 18:34:43	Dispatched and cancelled en route	7BF	Cancelled en route	CF22- 8407	Officer reviewed	1	ALARMF
750 West SOUTH TEMPLE Street	03/06/2022 20:22:18	Dispatched and cancelled en route	7BF	Cancelled en route	CF22- 8177	Officer reviewed	1	ALARMF
Alarm Count: 2								
1001 North FEATHERSTONE Drive	03/26/2022 08:33:49	Dispatched and cancelled en route	11AF	Cancelled en route	CF22- 10557	Officer reviewed	1	ALARMF
1001 North FEATHERSTONE Drive	02/09/2022 20:28:52	Detector activation, no fire - unintentional	11AF	Investigate	CF22- 5044	Officer reviewed	1	ALARMF
102 South 200 East	03/21/2022 12:17:22	Dispatched and cancelled en route	1EF	Cancelled en route	CF22- 9938	Officer reviewed	1	ALARMF
102 South 200 East	02/02/2022 10:11:00	Dispatched and cancelled en route	1EF	Cancelled en route	CF22- 4070	Officer reviewed	1	ALARMF
102 West 500 South	03/03/2022 13:46:02	Unintentional transmission of alarm, other	2DF	Investigate	CF22- 7679	Officer reviewed	2	ALARMW
102 West 500 South	02/07/2022 15:55:40	False alarm or false call, other	2DF	Investigate	CF22- 4761	Officer reviewed	1	ALARMF
1020 East YALE Avenue	02/14/2022 15:50:38	Dispatched and cancelled en route	5KF	Cancelled en route	CF22- 5652	Officer reviewed	1	ALARMF
1020 East YALE Avenue	01/29/2022 19:26:39	Dispatched and cancelled en route	5KF	Cancelled en route	CF22- 3596	Officer reviewed	1	ALARMF
1106 South LEGACY VIEW Street	02/10/2022 15:45:04	Alarm system sounded due to malfunction	9BF	Investigate	CF22- 5155	Officer reviewed	1	ALARMF
1106 South LEGACY VIEW Street	02/06/2022 11:53:07	Alarm system sounded due to malfunction	9BF	Investigate	CF22- 4625	Officer reviewed	1	ALARMF
1165 East WILMINGTON Avenue	03/02/2022 11:17:22	Dispatched and cancelled en route	3CF	Cancelled en route	CF22- 7531	Officer reviewed	1	ALARMF
1165 East WILMINGTON Avenue	01/13/2022 07:56:39	Dispatched and cancelled en route	3CF	Cancelled en route	CF22- 1580	Officer reviewed	1	ALARMF
1234 East 700 South	03/12/2022 03:16:51	False alarm or false call, other	5BF	Investigate	CF22- 8818	Officer reviewed	1	ALARMF
1234 East 700 South	03/05/2022 10:15:39	Dispatched and cancelled en route	5BF	Cancelled en route	CF22- 7893	Officer reviewed	1	ALARMF
131 East 700 South	03/12/2022 21:19:17	Smoke detector activation, no fire - unintentional	1DF	Investigate	CF22- 8905	Officer reviewed	1	ALARMF
131 East 700 South	01/19/2022 06:46:45	Dispatched and cancelled en route	1DF	Cancelled en route	CF22- 2339	Officer reviewed	1	ALARMF
132 South STATE Street	03/05/2022 14:07:07	Smoke detector activation, no fire - unintentional	1EF	Investigate	CF22- 7918	Officer reviewed	1	ALARMF
132 South STATE Street	03/05/2022 12:10:19	Smoke detector activation, no fire - unintentional	1EF	Investigate	CF22- 7904	Officer reviewed	1	ALARMF
135 East 100 South	03/18/2022 22:12:58	False alarm or false call, other	1AF	Investigate	CF22- 9666	Officer reviewed	2	ALARMW
135 East 100 South	01/15/2022 19:36:54	Smoke detector activation, no fire - unintentional	1AF	Investigate	CF22- 1888	Officer reviewed	1	ALARMF
135 West GOLTZ Avenue	02/23/2022 17:32:21	False alarm or false call, other	8EF	Investigate	CF22- 6767	Officer reviewed	0	ALARMF
135 West GOLTZ Avenue	02/23/2022	False alarm or false call,	8EF	Investigate	CF22-	Officer	1	ALARMF

Address	Incident Date	Incident Type	Response Zone	Primary Action Taken	Incident Number	Incident Status	Number of Apparatus	Dispatch Code
	06:30:27	other		1	6693	reviewed	••	11
136 South 300 East	03/03/2022 20:33:57	Smoke scare, odor of smoke	1GF	Investigate	CF22- 7736	Officer reviewed	1	ALARMF
136 South 300 East	02/04/2022 19:00:39	Alarm system activation, no fire - unintentional	1GF	Investigate	CF22- 4428	Officer reviewed	1	ALARMF
1398 East MICHIGAN Avenue	03/28/2022 17:30:05		5IF		CF22- 10868	Initiated	1	ALARMF
1398 East MICHIGAN Avenue	01/27/2022 17:32:56	Dispatched and cancelled en route	5IF	Cancelled en route	CF22- 3346	Officer reviewed	1	ALARMF
1431 East 100 South	01/21/2022 22:47:16	Dispatched and cancelled en route	4BF	Cancelled en route	CF22- 2644	Officer reviewed	1	ALARMF
1431 East 100 South	01/13/2022 22:20:39	Dispatched and cancelled en route	4BF	Cancelled en route	CF22- 1663	Officer reviewed	1	ALARMF
155 South 400 West	03/05/2022 02:58:53	Dispatched and cancelled en route	2GF	Cancelled en route	CF22- 7864	Officer reviewed	1	ALARMF
155 South 400 West	01/06/2022 22:43:31	False alarm or false call, other	2GF	Incident command	CF22- 860	Officer reviewed	1	ALARMF
155 West 200 North	03/31/2022 12:31:25		2AF		CF22- 11167	Initiated	1	ALARMF
155 West 200 North	03/01/2022 19:06:24	Cooking fire, confined to container	2AF	Ventilate	CF22- 7475	Officer reviewed	1	ALARMF
1576 South 300 West	04/02/2022 20:14:17		8HF		CF22- 11464	Initiated	0	ALARMF
1576 South 300 West	03/26/2022 01:26:32	Alarm system activation, no fire - unintentional	8HF	Investigate	CF22- 10524	Officer reviewed	1	ALARMF
1580 South 500 West	03/15/2022 10:36:10	Dispatched and cancelled en route	8HF	Cancelled en route	CF22- 9193	Officer reviewed	1	ALARMF
1580 South 500 West	02/17/2022 10:30:16	Dispatched and cancelled en route	8HF	Cancelled en route	CF22- 5950	Officer reviewed	1	ALARMF
1655 South AWL Circle	03/21/2022 09:31:00	Dispatched and cancelled en route	14BF	Cancelled en route	CF22- 9919	Officer reviewed	1	ALARMF
1655 South AWL Circle	03/21/2022 08:26:05	Dispatched and cancelled en route	14BF	Cancelled en route	CF22- 9913	Officer reviewed	1	ALARMF
166 East 200 South	03/08/2022 09:34:24	Dispatched and cancelled en route	1FF	Cancelled en route	CF22- 8342	Officer reviewed	1	ALARMF
166 East 200 South	02/28/2022 15:07:22	Alarm system activation, no fire - unintentional	1FF	Investigate	CF22- 7321	Officer reviewed	1	ALARMF
170 East BELMONT Avenue	03/01/2022 19:43:04	Dispatched and cancelled en route	8FF	Cancelled en route	CF22- 7479	Officer reviewed	1	ALARMF
170 East BELMONT Avenue	03/01/2022 16:56:17	Dispatched and cancelled en route	8FF	Cancelled en route	CF22- 7451	Officer reviewed	1	ALARMF
1701 East STUDENT LIFE Way	02/24/2022 19:34:37	Fire, other	10AF	Extinguishment by fire service personnel	CF22- 6900	Officer reviewed	1	ALARMF
1701 East STUDENT LIFE Way	01/26/2022 16:34:20	Smoke detector activation, no fire - unintentional	10AF	Investigate	CF22- 3201	Officer reviewed	1	ALARMF
1718 South 3230 West	02/25/2022 16:34:55	Dispatched and cancelled en route	14BF	Cancelled en route	CF22- 7006	Officer reviewed	1	ALARMF
1718 South 3230 West	02/25/2022 07:30:10	Dispatched and cancelled en route	14BF	Cancelled en route	CF22- 6949	Officer reviewed	1	ALARMF
1770 South 5350 West	01/17/2022 12:36:17	Smoke detector activation due to malfunction	14JF	Investigate	CF22- 2095	Officer reviewed	1	ALARMF
1770 South 5350 West	01/12/2022 13:40:33	False alarm or false call, other	14JF	Investigate	CF22- 1502	Officer reviewed	1	ALARMF
1818 South 300 West	03/15/2022 12:30:02	Dispatched and cancelled en route	8KF	Cancelled en route	CF22- 9206	Officer reviewed	0	ALARMF
1818 South 300 West	01/05/2022 08:03:29	Dispatched and cancelled en route	8KF	Cancelled en route	CF22- 595	Officer reviewed	1	ALARMF
1845 South PASCHAL Circle	04/02/2022 20:50:19	False alarm or false call, other	13AF	Investigate	CF22- 11472	Officer reviewed	1	ALARMF
1845 South PASCHAL Circle	04/02/2022 17:14:58	Dispatched and cancelled en route	13AF	Cancelled en route	CF22- 11438	Officer reviewed	1	ALARMF

Address	Incident Date	Incident Type	Response Zone	Primary Action Taken	Incident Number	Incident Status	Number of Apparatus	Dispatch Code
1955 East STRATFORD Avenue	02/17/2022 12:11:59	Dispatched and cancelled en route	13BF	Cancelled en route	CF22- 5953	Officer reviewed		ALARMF
1955 East STRATFORD Avenue	01/05/2022 15:16:12	Dispatched and cancelled en route	13BF	Cancelled en route	CF22- 657	Officer reviewed	1	ALARMF
1966 South 200 East	01/27/2022 10:59:04	False alarm or false call, other	8DF	Assistance, other	CF22- 3295	Officer reviewed	1	ALARMF
1966 South 200 East	01/07/2022 19:28:15	Smoke detector activation due to malfunction	8DF	Investigate	CF22- 947	Officer reviewed	1	ALARMF
1988 South 1100 East	03/11/2022 14:53:18	Alarm system activation, no fire - unintentional	3BF	Investigate	CF22- 8739	Officer reviewed	1	ALARMF
1988 South 1100 East	03/04/2022 04:21:58	Water or steam leak	3BF	Salvage & overhaul	CF22- 7759	Officer reviewed	1	ALARMF
200 South CENTRAL CAMPUS Drive	03/16/2022 15:01:11	False alarm or false call, other	4EF	Investigate	CF22- 9337	Officer reviewed	1	ALARMF
200 South CENTRAL CAMPUS Drive	01/07/2022 17:46:42	False alarm or false call, other	4EF	Restore fire alarm system	CF22- 935	Officer reviewed	1	ALARMF
201 East SOUTH TEMPLE Street	02/08/2022 12:01:37	Dispatched and cancelled en route	2BF	Cancelled en route	CF22- 4881	Officer reviewed	2	ALARMF
201 East SOUTH TEMPLE Street	02/08/2022 08:47:25	Dispatched and cancelled en route	2BF	Cancelled en route	CF22- 4855	Officer reviewed	1	ALARMF
205 East 1ST Avenue	02/10/2022 09:53:52	Dispatched and cancelled en route	1JF	Cancelled en route	CF22- 5104	Officer reviewed	1	ALARMW
205 East 1ST Avenue	01/13/2022 12:32:14	Dispatched and cancelled en route	1JF	Cancelled en route	CF22- 1601	Officer reviewed	1	ALARMF
206 North E Street	03/10/2022 13:13:12	Dispatched and cancelled en route	4AF	Cancelled en route	CF22- 8619	Officer reviewed	1	ALARMF
206 North E Street	03/10/2022 13:06:31	Dispatched and cancelled en route	4AF	Cancelled en route	CF22- 8612	Officer reviewed	1	ALARMF
2120 South HIGHLAND Drive	02/24/2022 00:37:17	False alarm or false call, other	3CF	Investigate	CF22- 6807	Officer reviewed	1	ALARMW
2120 South HIGHLAND Drive	02/16/2022 20:32:26	False alarm or false call, other	3CF	Investigate	CF22- 5889	Officer reviewed	1	ALARMW
215 South STATE Street	02/04/2022 09:36:47	Dispatched and cancelled en route	1FF	Cancelled en route	CF22- 4341	Officer reviewed	1	ALARMF
215 South STATE Street	01/13/2022 16:39:55	Dispatched and cancelled en route	1FF	Cancelled en route	CF22- 1631	Officer reviewed	1	ALARMF
215 West SOUTH TEMPLE Street	01/22/2022 14:51:54	Dispatched and cancelled en route	2GF	Cancelled en route	CF22- 2706	Officer reviewed	1	ALARMF
215 West SOUTH TEMPLE Street	01/14/2022 14:03:22	Dispatched and cancelled en route	2GF	Cancelled en route	CF22- 1734	Officer reviewed	1	ALARMF
2180 South 1300 East	02/07/2022 03:13:47	Water or steam leak	3CF	Investigate	CF22- 4701	Officer reviewed	1	ALARMF
2180 South 1300 East	01/05/2022 20:27:53	Sprinkler activation, no fire - unintentional	3CF	Shut down system	CF22- 687	Officer reviewed	1	ALARMF
220 South STATE Street	02/03/2022 04:46:45	Dispatched and cancelled en route	1FF	Cancelled en route	CF22- 4184	Officer reviewed	1	ALARMF
220 South STATE Street	01/24/2022 16:29:05	Dispatched and cancelled en route	1FF	Cancelled en route	CF22- 2955	Officer reviewed	1	ALARMF
222 South MAIN Street	03/07/2022 13:20:10	Smoke scare, odor of smoke	2DF	Investigate	CF22- 8265	Officer reviewed	1	ALARMF
222 South MAIN Street	02/10/2022 18:34:07	Dispatched and cancelled en route	2DF	Cancelled en route	CF22- 5173	Officer reviewed	1	ALARMF
230 East BROADWAY Street	03/27/2022 01:54:53	Alarm system activation, no fire - unintentional	1IF	Investigate	CF22- 10668	Officer reviewed	1	ALARMF
230 East BROADWAY Street	02/17/2022 16:18:48	Dispatched and cancelled en route	1IF	Cancelled en route	CF22- 5974	Officer reviewed	2	ALARMF
2305 South DALLIN Street	02/11/2022 16:04:36	Dispatched and cancelled en route	13BF	Cancelled en route	CF22- 5302	Officer reviewed	2	ALARMF
2305 South DALLIN Street	02/03/2022 10:55:43	Dispatched and cancelled en route	13BF	Cancelled en route	CF22- 4220	Officer reviewed	1	ALARMF
	03/24/2022		2AF		CF22-			ALARMF

244 North 300 West Q3/11/2022 Am System sounded 21:07:207 QAR Mark System Version	Address	Incident Date	Incident Type	Response Zone	Primary Action Taken	Incident Number	Incident Status	Number of Apparatus	Dispatch Code
00-33.58 transmission of latm, other S802 reviewed 251 H East 1300 South 03/11/2022 Dispatched and cancelled on route 010F Cancelled on route CF2.2 Officer reviewed 1 ALARNF 255 South WEST TEMPLE 03/25/2022 Dispatched and cancelled on route CF2.2 Officer reviewed 1 ALARNF 255 South WEST TEMPLE 03/05/2022 Dispatched and cancelled on route CF2.2 Officer reviewed 1 ALARNF 257 East 200 South 03/05/202 False alarm or false call 1GF Investigate CF2.2 Officer reviewed 1 ALARNF 258 Vest 700 South 03/12/222 False alarm or false call 1GF Investigate CF2.2 Officer reviewed 2 ALARNF 2787 South PRESTON Street 03/12/222 Sprinter activation BLF Investigate CF2.2 Officer reviewed 2 ALARNF 2787 South PRESTON Street 03/12/222 Sprinter activation BLF Investigate CF2.2 Officer reviewed 2 ALARNF 2873 South PRE	244 North 300 West			2AF	Investigate				ALARMW
19-30-11 cancelled en route 8769 reviewed 1 1 ALARME SS bout WEST TEMPLE 02/2022 Dispationed and cancelled en route DF Cancelled en route 02/52- Officer 1 ALARME SS bout WEST TEMPLE 02/10/202 Dispationed and cancelled en route DF Cancelled en route DF Cancelled en route DF Cancelled en route DF ALARME SS bout WEST TEMPLE 02/10/2022 Dispatione and context in the call DF Indestined and context in the call DF Cancelled en route CANCEN 2 ALARME SS bout MEST TEMPLE 02/10/2022 Dispatione and context in the call DF Indestined and context in the call DF Cancelled en route DF Dispatione	2511 East 1300 South		transmission of alarm,	10DF	Investigate		•••••	1	ALARMF
Sinet 09:57:18 cancelled en route 10565 reviseed 255 cutt 09:57:18 cancelled en route 27 Cancelled en route 27 Cancelled en route 27 Cancelled en route 14.ARMF 257 E sat 200 South 020:522 West 700 Cancelled en route 167 Nuestigate 27 Cancelled en route 2 ALARMW 257 F sat 200 South 020:522 Faite alum or false call, 01 10F Investigate CF2- Officer 1 ALARW 280 West 700 South 01:22:022 Sprinte activation, no I.F. Investigate CF2- Officer 2 ALARWW 273 South PRESTON Stret 00:16:10 To maturation due 13F Investigate CF2- Officer 2 ALARWW 273 South PRESTON Stret 00:18:102 Zoancelled en route 13F Investigate CF2- Officer 1 ALARW 273 South PRESTON Stret 00:18:202 Dispatched and route 13F Cancelled en route CF2- Officer 1 <	2511 East 1300 South			10DF	Cancelled en route			1	ALARMF
Street 08:59:15 cancelled en route 5097 reviewed 257 East 200 South 02/37022 Water problem, other 1GF Shut down system CF222 Officer 2 ALARMF 257 East 200 South 02/37022 False alarm or false call. 1GF Furweilgale CF222 Officer 1 ALARMF 258 West 700 South 01/27022 Furweilgale CF22 Officer 2 ALARMF 257 South PRESTON Strett 01/26022 Sprinter activation, too 3136F Investigate CF22- Officer 2 ALARMF 2673 South PRESTON Strett 01/26022 Sprinter activation due 313F Cancelled en route CF22- Officer 2 ALARMF 29 East 900 South 03/3702 Dispatched and 318F Cancelled en route CF22- Officer 1 ALARMF 29 East 900 South 03/3702 Dispatched and 8FF Cancelled en route CF22- Officer 1 ALARMF 29 East 900 South 03/3708 cancolled	255 South WEST TEMPLE Street			2DF	Cancelled en route		•••••	1	ALARMF
17:57:15 77:16 77:16 relevand 257 East 200 South 02/05/2022 False alarm or false call. 1GF Investigate CP22 Officer 1 ALARMF 258 West 700 South 01/02/202 Winter or steam leak. 8LF Investigate CP22. Officer 2 ALARMF 258 West 700 South 01/20/202 Water or steam leak. 8LF Shut down system CP22. Officer 2 ALARMF 2673 South PRESTON Street 02/16/2022 Investigate CP22. Officer 2 ALARMF 2673 South PRESTON Street 02/16/2022 inpatched and 138F Cancelled en route CP22. Officer 2 ALARMF 29 East 900 South 02/16/2022 inpatched and 08FF Cancelled en route CP22. Officer 1 ALARMF 29 East 900 South 01/16/2022 inpatched and 0AFF Cancelled en route CP22. Officer 1 ALARMF 20 South FORT DOUGLAS 01/16/2022 inpatched and 1AAF	255 South WEST TEMPLE Street			2DF	Cancelled en route			1	ALARMF
09:08:00 other 44.88 reviewed 258 West 700 South 03:162022 Spinkler activation, no BLF Investigate CF22. Officer 1 ALAR8W 258 West 700 South 03:162022 Spinkler activation and 81.F Shut down system CF22. Officer 2 ALAR8W 2673 South PRESTON Stret 03:06:16:18 to mailunction 13BF Investigate CF22. Officer 2 ALAR8W 2673 South PRESTON Stret 03:18:102 Dispatched and 13BF Cancelled en route CF22. Officer 2 ALAR8W 28 East 900 South 03:19:2022 Dispatched and BFF Cancelled en route CF22. Officer 1 ALAR8W 29 East 900 South FORT DOUGLAS 02:28:2022 Dispatched and BFF Cancelled en route CF22. Officer 1 ALAR8W 29 East 900 South FORT DOUGLAS 02:28:2022 Dispatched and BFF Cancelled en route CF22. Officer 1 ALAR8W 20 South FORT DOUGLAS	257 East 200 South		Water problem, other	1GF	Shut down system			2	ALARMW
13:37:29 fire - unintentional 9326 reviewed 258 West 700 South 01/22/022 Water or steam leak 8LF Shut down system 36/69 2 ALARMW 2673 South PRESTON Street 30/68/2022 Spinkler activation due 138F Investigate CF22 Officer 2 ALARMW 2873 South PRESTON Street 30/68/2022 Dispatched and 138F Canceilled en route CF22 Officer 2 ALARMW 29 East 900 South PRESTON Street 30/38/2022 Dispatched and 8FF Canceilled en route CF22 Officer 1 ALARMF 29 East 900 South FORT DUGLAS 20/28/2022 Ipisatched and 6FF Canceilled en route CF22 Officer 1 ALARMF 29 South FORT DUGLAS 20/08/2022 Dispatched and 10AF Investigate CF22 Officer 1 ALARMF 208 South FORT DUGLAS 20/08/2022 Dispatched and 4EF Canceiled en route	257 East 200 South			1GF	Investigate			1	ALARMF
14:48:35 1366 reviewed 2 ALARMW 2873 South PRESTON Stree 00:06/022 Spinkler activation due 138F Investigate 6722 Officer 2 ALARMW 2873 South PRESTON Stree 02:16:18 to maifunction due 138F Cancelled en route CF22 Officer 2 ALARMW 28 East 900 South 00:11/9/2022 Dispatched and 8FF Cancelled en route CF22 Officer 1 ALARMF 29 East 900 South 00:11/9/2022 Dispatched and 8FF Cancelled en route CF22 Officer 1 ALARMF 296 South FORT DOUGLAS 02/26/2022 False alarm or false call, 10AF Investigate CF22 Officer 1 ALARMF 206 South FORT DOUGLAS 02/03/202 Sipatched and 4EF Cancelled en route CF22 Officer 1 ALARMF 203 North MEDICAL Drive 02/03/2022 Dispatched and 4EF Information, investigate CF22 Officer 1 ALARMF 3100 West P	258 West 700 South			8LF	Investigate			1	ALARMW
08:16:18 to malfunction 8078 reviewed 2673 South PRESTON Street 0218/2022 Dispatched and cancelled en route 13BF Cancelled en route 6771 reviewed 2 ALARMY 29 East 900 South 03/19/2022 Dispatched and 03/18/2022 8FF Cancelled en route 6721 Officer 1 ALARMF 29 East 900 South 03/18/2022 Dispatched and 03/18/2022 8FF Cancelled en route 6722. Officer 1 ALARMF 295 South FORT DOUGLAS 02/26/2022 Fake alern or false call, 10AF Investigate CF22. Officer 1 ALARMF 204 South FORT DOUGLAS 10/18/2022 Swake detector 10AF Investigate CF22. Officer 1 ALARMF 30 North MEDICAL Drive 02/03/2022 Dispatched and 11/28/2022 Les alarm or false call, 4EF Cancelled en route CF22. Officer 1 ALARMF 310 North MEDICAL Drive 03/08/2022 Dispatched and 11/28/20 Les alarm or false call, 14BF Cancelled en route C	258 West 700 South		Water or steam leak	8LF	Shut down system			2	ALARMW
11:55:10 cancelled en route 6071 reviewed 29 East 900 South 0319/2022 Dispatched and cancelled en route 8FF Cancelled en route 6F2: Officer reviewed 1 ALARMF 29 East 900 South 03/18/2022 Dispatched and cancelled en route 8FF Cancelled en route 6F2: Officer reviewed 1 ALARMF 295 South FORT DOUGLAS 02/26/2022 False alarm of false call, outer activation due to activation activation, activation activation, activation activation, activation activation, atter vuintentional 14BF Cancelled en route activation due to activation activation, activation activation, activation activation, activation activation, activation activation, atter vuintentional 14BF Investigate activation activation, activation activation, activation activation, activation activation, activation activativation, atter vuintentional 14	2673 South PRESTON Street			13BF	Investigate			2	ALARMW
00.03.18 cancelled en route 967.6 reviewed 29 East 900 South 03/16/2022 Dispatched and cancelled en route 8FF Cancelled en route CF22. Officer 1 ALARMF 295 South FORT DOUGLAS 02/26/202 False alarm or false call, 10AF Investigate CF22. Officer 1 ALARMF 295 South FORT DOUGLAS 01/08/2022 Smoke detector 10AF Investigate CF22. Officer 1 ALARMF 30 North MEDICAL Drive 01/08/2022 Dispatched and cancelled en route 4EF Cancelled en route CF22. Officer 1 ALARMF 310 North MEDICAL Drive 01/18/2022 Dispatched and cancelled en route 4EF Information, investigation CF22. Officer 1 ALARMF 3190 West PROFESSIONAL 02/08/2022 Dispatched and cancelled en route 4BF Investigate CF22. Officer 1 ALARMF 3190 West PROFESSIONAL 02/08/2022 Alarm system activation, the "uninentional" 1BF Provide information to CF22. Officer 1	2673 South PRESTON Street		•	13BF	Cancelled en route			2	ALARMW
17:56:20cancelled en route9631reviewed295 South FORT DOUGLAS Boulevard02/26/202False alarm or false call, other10AFInvestigateCF22. CF22.Officer reviewed1ALARMF295 South FORT DOUGLAS Boulevard01/08/2022Smoke detector maffunction10AFInvestigateCF22. CF22.Officer reviewed1ALARMF30 North MEDICAL Drive 30 North MEDICAL Drive02/03/2022Dispatched and cancelled en route4EFCancelled en routeCF22. CfficerOfficer reviewed1ALARMF3190 West PROFESSIONAL Circle03/06/2022False alarm or false call, unintentional14BFCancelled en routeCF22. CfficerOfficer reviewed2ALARMF3190 West PROFESSIONAL Circle02/205/202Alarm system activation, no fire - unintentional14BFInvestigateCF22. CfficerOfficer reviewed1ALARMF330 East 400 South02/05/202Sprinkler activation, no fire - unintentional1FShut down system A526CF22. reviewedOfficer reviewed1ALARMF336 East 400 South03/01/2022False alarm or false call, ther - unintentional1FShut down system A526CF22. reviewedOfficer reviewed1ALARMF336 West 1820 South03/01/2022False alarm or false call, tother14BFInvestigateCF22. CfficerOfficer reviewed1ALARMF350 West 140PE Avenue03/02/202Service call, ot	29 East 900 South			8FF	Cancelled en route			1	ALARMF
Boulevard09:37:05other7070reviewed295 South FORT DOUGLAS Boulevard01/08/2022 12:48:47Smoke detector activation due to malfunction10AFInvestigateCF22- 4228Officer reviewed1ALARMF30 North MEDICAL Drive02/03/2022 12:39:51Dispatched and cancelled en route4EFCancelled en routeCF22- & erviewedOfficer1ALARMF310 North MEDICAL Drive01/16/202 12:39:51False alarm or false call.4EFCancelled en routeCF22- & erviewedOfficer1ALARMF3190 West PROFESSIONAL Circle02/02/2022 20ispatched and cancelled en route14BFCancelled en routeCF22- & OfficerOfficer1ALARMF3190 West PROFESSIONAL Circle02/02/2022 20/05/272 20/3577Alarm system activation, no fire - unintentional1HFProvide information to public or mediaCF22- & OfficerOfficer reviewed1ALARMF330 East 400 South 330 East 400 South02/05/2022 03/07/2022 False alarm or false call.1HFInvestigateCF22- & OfficerOfficer1ALARMF336 Ewest 1820 South03/01/2022 03/07/2022 False alarm or false call.14BFInvestigateCF22- & OfficerOfficer1ALARMF336 West HOPE Avenue 3360 West HOPE Avenue 03/03/202203/03/02022 Heat from short circuit winnig. defective/worn8HFAssistance, otherCF22- & OfficerOfficer1ALARMF350 West HOPE Avenue 03	29 East 900 South			8FF	Cancelled en route			1	ALARMF
Boulevard12:46:47activation due to maifunction1015reviewed30 North MEDICAL Drive02/03/2022Dispatched and cancelled en route4EFCancelled en routeCF22- 4228Officer reviewed1ALARMF30 North MEDICAL Drive01/16/2022Dispatched and cancelled en route4EFInformation, investigationCF22- 8 enforcement, otherOfficer reviewed1ALARMF3190 West PROFESSIONAL Orice03/08/2022Dispatched and cancelled en route14BFCancelled en routeRF22- 8 enforcement, otherOfficer reviewed1ALARMW3190 West PROFESSIONAL Orice02/05/2022Alarm system activation, no fire - unintentional14BFInvestigateCF22- 6558Officer reviewed1ALARMF330 East 400 South02/05/2022Sprinkler activation, no fire - unintentional11FProvide information to public or mediaCF22- 4555Officer reviewed1ALARMF336 East 400 South03/01/2022False alarm or false call, other14BFInvestigateCF22- 7456Officer reviewed1ALARMF3366 West 1820 South03/01/2022False alarm or false call, other14BFInvestigateCF22- CF22- CfficerOfficer reviewed1ALARMF350 West HOPE Avenue03/03/2022False alarm or false call, other14BFInvestigateCF22- CF22- CfficerOfficer reviewed1ALARMF350 West HOPE Avenue03/03/02/22 <t< td=""><td></td><td></td><td></td><td>10AF</td><td>Investigate</td><td></td><td></td><td>1</td><td>ALARMF</td></t<>				10AF	Investigate			1	ALARMF
11:28:29cancelled en route4228reviewed30 North MEDICAL Drive01/16/2022False alarm or false call, other4EFInformation, investigate & enforcement, otherCF22- 8415Officer reviewed1ALARMF3190 West PROFESSIONAL Circle03/08/2022Dispatched and cancelled en route14BFCancelled en routeCF22- 8415Officer reviewed2ALARMW3190 West PROFESSIONAL Circle02/22/2022Alarm system activation, no fire - unintentional14BFProvide Information to public or mediaCF22- verviewedOfficer reviewed1ALARMF330 East 400 South02/05/2022 (205/2022Alarm system activation, no fire - unintentional1FProvide Information to public or mediaCF22- verviewedOfficer reviewed1ALARMF330 East 400 South02/05/2022 (205/2022Sprinkler activation, no fire - unintentional1FProvide Information to public or mediaCF22- verviewedOfficer reviewed1ALARMF3366 West 1820 South03/01/2022 (14:38:49)False alarm or false call, other14BFInvestigateCF22- verviewedOfficer reviewed1ALARMF330 West HOPE Avenue03/23/2022 (21:57:33False alarm or false call, other14BFInvestigateCF22- verviewedOfficer reviewed1ALARMF350 West HOPE Avenue03/04/2022 (21:57:33Ease alarm or false call, other14BFInvestigateCF22- verviewedOfficer <td>295 South FORT DOUGLAS Boulevard</td> <td></td> <td>activation due to</td> <td>10AF</td> <td>Investigate</td> <td></td> <td></td> <td>1</td> <td>ALARMF</td>	295 South FORT DOUGLAS Boulevard		activation due to	10AF	Investigate			1	ALARMF
12:39:51other& enforcement, other1967reviewed3190 West PROFESSIONAL Circle03/08/202 19:05:21Dispatched and cancelled en route14BFCancelled en routeCF22- 6536Officer reviewed1ALARMW3190 West PROFESSIONAL Circle02/22/2022 	30 North MEDICAL Drive			4EF	Cancelled en route			1	ALARMF
Circle19:05:39cancelled en route8415reviewed3190 West PROFESSIONAL Circle02/22/2022 0052:15Alarm system activation, no fire - unintentional14BFInvestigateCF22- public or mediaOfficer cerviewed1ALARMW330 East 400 South02/05/2022 02/05/2022 043:57Alarm system activation, no fire - unintentional1IFProvide information to public or mediaCF22- 4525Officer reviewed1ALARMF330 East 400 South02/05/2022 040:522Sprinkler activation, no fire - unintentional1IFShut down system public or mediaCF22- 4526Officer reviewed1ALARMF336 East 400 South03/01/2022 16:40:51Sprinkler activation, no inter - unintentional1IFShut down system public or mediaCF22- 4526Officer reviewed1ALARMF3366 West 1820 South03/01/2022 14:35:47:18False alarm or false call, other14BFInvestigateCF22- 7436Officer reviewed1ALARMF350 West HOPE Avenue03/23/2022 21:57:33Service call, other8HFAssistance, otherCF22- 722Officer reviewed1ALARMF365 West PAXTON Avenue03/30/2022 21:159Heat from short circuit (wing), defective/worn8AFInvestigateCF22- 722Officer reviewed1ALARMF365 West PAXTON Avenue03/31/2022 21:159Heat from short circuit (wing), defective/worn8AFInvestigateCF22- 722Officer re	30 North MEDICAL Drive			4EF				1	ALARMF
Circle00:52:15no fire - unintentional06536reviewed330 East 400 South02/05/2022Alarm system activation, no fire - unintentional11FProvide information to public or mediaCF22- 4555Officer reviewed1ALARMF330 East 400 South02/05/2022Sprinkler activation, no fire - unintentional11FShut down systemCF22- 4526Officer reviewed1ALARMF3366 West 1820 South03/01/2022False alarm or false call, to ther14BFInvestigateCF22- 7436Officer reviewed1ALARMF3366 West 1820 South03/01/2022 15:47:18False alarm or false call, other14BFInvestigateCF22- 7436Officer reviewed1ALARMF3360 West HOPE Avenue03/23/2022 21:57:33Service call, other8HFAssistance, otherCF22- 10238Officer reviewed1ALARMW350 West HOPE Avenue03/04/2022 16:44:23Dispatched and cancelled en route8HFCancelled en routeCF22- CF22- CfficerOfficer reviewed1ALARMF365 West PAXTON Avenue03/30/2022 19:52:05Heat from short circuit (wiring), defective/worn8AFInvestigateCF22- CF22- CfficerOfficer reviewed1ALARMF365 North WRIGHT03/17/2022 19:52:05Alarm system sounded (wiring), defective/worn9AFInvestigateCF22- CF22- CfficerOfficer reviewed1ALARMF385 North WRIGHT03/15/2022 19	3190 West PROFESSIONAL Circle			14BF	Cancelled en route			2	ALARMW
20:43:57no fire - unintentionalpublic or media4555reviewed330 East 400 South02/05/2022 16:40:28Sprinkler activation, no fire - unintentional1IFShut down systemCF22- 4526Officer 	3190 West PROFESSIONAL Circle			14BF	Investigate			1	ALARMW
16:40:28fire - unintentional4526reviewed3366 West 1820 South03/01/2022 15:47:18False alarm or false call, other14BFInvestigateCF22- 7445Officer 	330 East 400 South			1IF				1	ALARMF
15:47:18other7445reviewed3366 West 1820 South03/01/2022 (14:38:49)False alarm or false call, other14BFInvestigateCF22- (7436)Officer reviewed1ALARMF350 West HOPE Avenue03/23/2022 (21:57:33)Service call, other8HFAssistance, otherCF22- (102:38)Officer reviewed1ALARMW350 West HOPE Avenue03/04/2022 (21:57:33)Dispatched and cancelled en route8HFCancelled en routeCF22- (7826)Officer reviewed1ALARMW365 West PAXTON Avenue03/30/2022 (21:21:59)Heat from short circuit (wiring), defective/worn8AFInvestigateCF22- (11090)Officer reviewed1ALARMF365 West PAXTON Avenue03/30/2022 (19:52:05)Heat from short circuit (wiring), defective/worn8AFInvestigateCF22- (11090)Officer reviewed1ALARMF385 North WRIGHT BROTHERS Drive03/17/2022 (10:24:118Alarm system sounded due to malfunction9AFInvestigateCF22- (9429)Officer reviewed1ALARMW385 North WRIGHT BROTHERS Drive03/15/2022 (10:24:18Dispatched and cancelled en route9AFCancelled en routeCF22- (9429)Officer reviewed1ALARMW422 North 800 West02/15/2022 (16:40:28)Dispatched and cancelled en route7BFCancelled en routeCF22- (72:05)Officer reviewed1ALARMF422 North 800 West01/25/2022False	330 East 400 South			1IF	Shut down system			1	ALARMF
14:38:49other7436reviewed350 West HOPE Avenue03/23/2022 21:57:33Service call, other8HFAssistance, otherCF22- 10238Officer reviewed1ALARMW350 West HOPE Avenue03/04/2022 16:44:23Dispatched and cancelled en route8HFCancelled en routeCF22- 7826Officer reviewed2ALARMW365 West PAXTON Avenue03/30/2022 12:1:59Heat from short circuit (wiring), defective/worn8AFInvestigateCF22- 11101Officer reviewed1ALARMF365 West PAXTON Avenue03/30/2022 19:52:05Heat from short circuit (wiring), defective/worn8AFInvestigateCF22- 11090Officer reviewed1ALARMF385 North WRIGHT BROTHERS Drive03/17/2022 15:24:18Alarm system sounded cancelled en route9AFCancelled en routeCF22- 0fficer reviewedOfficer reviewed1ALARMW422 North 800 West02/15/2022 16:40:28Dispatched and cancelled en route7BFCancelled en routeCF22- 0fficer 9219Officer reviewed1ALARMF422 North 800 West01/25/2022 16:40:28Talse alarm or false call,7BFInvestigateCF22- 0fficerOfficer reviewed1ALARMF422 North 800 West01/25/2022 16:40:28Talse call,7BFInvestigateCF22- 0fficerOfficer reviewed1ALARMF422 North 800 West01/25/2022 16:40:28Talse call,7BFInvestigate<	3366 West 1820 South			14BF	Investigate			1	ALARMF
21:57:3310238reviewed350 West HOPE Avenue03/04/2022 16:44:23Dispatched and cancelled en route8HFCancelled en routeCF22- 7826Officer reviewed2ALARMW365 West PAXTON Avenue03/30/2022 21:21:59Heat from short circuit (wiring), defective/worn8AFInvestigateCF22- 11101Officer reviewed1ALARMF365 West PAXTON Avenue03/30/2022 (wiring), defective/wornHeat from short circuit (wiring), defective/worn8AFInvestigateCF22- 11090Officer reviewed1ALARMF365 West PAXTON Avenue03/30/2022 (wiring), defective/wornHeat from short circuit (wiring), defective/worn8AFInvestigateCF22- 9429Officer reviewed1ALARMF385 North WRIGHT BROTHERS Drive03/17/2022 10:24:41Alarm system sounded due to malfunction9AFInvestigateCF22- 9429Officer reviewed1ALARMW385 North WRIGHT BROTHERS Drive03/15/2022 15:24:18Dispatched and cancelled en route9AFCancelled en routeCF22- 9219Officer reviewed2ALARMW422 North 800 West02/15/2022 16:40:28Dispatched and cancelled en route7BFCancelled en routeCF22- 5746Officer 11ALARMF422 North 800 West01/25/2022 16:40:28False alarm or false call, 7BFInvestigateCF22- 5746Officer 11ALARMF	3366 West 1820 South			14BF	Investigate			1	ALARMF
16:44:23cancelled en route7826reviewed365 West PAXTON Avenue03/30/2022 21:21:59Heat from short circuit (wiring), defective/worn8AFInvestigateCF22- 11101Officer reviewed1ALARMF365 West PAXTON Avenue03/30/2022 19:52:05Heat from short circuit (wiring), defective/worn8AFInvestigateCF22- 11090Officer reviewed1ALARMF385 North WRIGHT BROTHERS Drive03/17/2022 10:24:41Alarm system sounded due to malfunction9AFInvestigateCF22- 9429Officer reviewed1ALARMW385 North WRIGHT BROTHERS Drive03/15/2022 15:24:18Dispatched and cancelled en route9AFCancelled en routeCF22- 9219Officer reviewed2ALARMW422 North 800 West02/15/2022 16:40:28Dispatched and cancelled en route7BFCancelled en routeCF22- 9746Officer reviewed1ALARMF422 North 800 West01/25/2022False alarm or false call,7BFInvestigateCF22- 9219Officer reviewed1ALARMF422 North 800 West01/25/2022False alarm or false call,7BFInvestigateCF22- 9219Officer 11ALARMF422 North 800 West01/25/2022False alarm or false call,7BFInvestigateCF22- 9219Officer 11ALARMF422 North 800 West01/25/2022False alarm or false call,7BFInvestigateCF22- 9219Officer 1<	350 West HOPE Avenue		Service call, other	8HF	Assistance, other			1	ALARMW
21:21:59(wiring), defective/worn11101reviewed365 West PAXTON Avenue03/30/2022 19:52:05Heat from short circuit (wiring), defective/worn8AFInvestigateCF22- 11090Officer reviewed1ALARMF385 North WRIGHT BROTHERS Drive03/17/2022 10:24:41Alarm system sounded due to malfunction9AFInvestigateCF22- 9429Officer reviewed1ALARMW385 North WRIGHT BROTHERS Drive03/15/2022 15:24:18Dispatched and cancelled en route9AFCancelled en routeCF22- 9219Officer reviewed2ALARMW422 North 800 West02/15/2022 16:40:28Dispatched and cancelled en route7BFCancelled en routeCF22- 5746Officer reviewed1ALARMF422 North 800 West01/25/2022False alarm or false call, reviewed7BFInvestigateCF22- CF22- CF22- CF22-Officer reviewed1ALARMF422 North 800 West01/25/2022False alarm or false call, reviewed7BFInvestigateCF22- CF22- CF22-Officer reviewed1ALARMF	350 West HOPE Avenue			8HF	Cancelled en route			2	ALARMW
19:52:05(wiring), defective/worn11090reviewed385 North WRIGHT BROTHERS Drive03/17/2022 10:24:41Alarm system sounded due to malfunction9AFInvestigateCF22- 9429Officer reviewed1ALARMW385 North WRIGHT BROTHERS Drive03/15/2022 15:24:18Dispatched and cancelled en route9AFCancelled en routeCF22- 9219Officer reviewed2ALARMW422 North 800 West02/15/2022 16:40:28Dispatched and cancelled en route7BFCancelled en routeCF22- 5746Officer reviewed1ALARMF422 North 800 West01/25/2022False alarm or false call, reviewed7BFInvestigateCF22- CF22-Officer reviewed1ALARMF	365 West PAXTON Avenue			8AF	Investigate			1	ALARMF
BROTHERS Drive10:24:41due to malfunction9429reviewed385 North WRIGHT BROTHERS Drive03/15/2022 15:24:18Dispatched and cancelled en route9AFCancelled en routeCF22- 9219Officer reviewed2ALARMW422 North 800 West02/15/2022 16:40:28Dispatched and cancelled en route7BFCancelled en routeCF22- S746Officer reviewed1ALARMF422 North 800 West01/25/2022False alarm or false call, reviewed7BFInvestigateCF22- CF22-Officer reviewed1ALARMF	365 West PAXTON Avenue			8AF	Investigate			1	ALARMF
BROTHERS Drive 15:24:18 cancelled en route 9219 reviewed 422 North 800 West 02/15/2022 Dispatched and cancelled en route 7BF Cancelled en route CF22- Officer reviewed 1 ALARMF 422 North 800 West 01/25/2022 False alarm or false call, 7BF Investigate CF22- Officer 1 ALARMF	385 North WRIGHT BROTHERS Drive			9AF	Investigate			1	ALARMW
16:40:28 cancelled en route 5746 reviewed 422 North 800 West 01/25/2022 False alarm or false call, 7BF Investigate CF22- Officer 1 ALARMF	385 North WRIGHT BROTHERS Drive			9AF	Cancelled en route			2	ALARMW
0	422 North 800 West			7BF	Cancelled en route			1	ALARMF
	422 North 800 West		,	7BF	Investigate			1	ALARMF

Address	Incident Date	Incident Type	Response Zone	Primary Action Taken	Incident Number	Incident Status	Number of Apparatus	Dispatch Code
424 West 100 South	02/10/2022 18:50:03	Dispatched and cancelled en route	2AF	Cancelled en route	CF22- 5177	Officer reviewed	1	ALARMF
424 West 100 South	02/01/2022 07:15:45	Dispatched and cancelled en route	2AF	Cancelled en route	CF22- 3932	Officer reviewed	2	ALARMW
439 South DENVER Street	03/02/2022 20:40:11	Local alarm system, malicious false alarm	1IF	Investigate	CF22- 7609	Officer reviewed	1	ALARMF
439 South DENVER Street	01/30/2022 13:48:18	Smoke detector activation, no fire - unintentional	1IF	Restore fire alarm system	CF22- 3670	Officer reviewed	1	ALARMF
44 North MARIO CAPECCHI Drive	02/28/2022 10:10:46	Smoke detector activation, no fire - unintentional	10AF	Investigate	CF22- 7289	Officer reviewed	1	ALARMF
44 North MARIO CAPECCHI Drive	02/22/2022 11:16:08	Smoke detector activation, no fire - unintentional	10AF	Investigate	CF22- 6589	Officer reviewed	1	ALARMF
451 South 1400 East	01/28/2022 09:14:37	Unintentional transmission of alarm, other	10BF	Investigate	CF22- 3417	Officer reviewed	1	ALARMF
451 South 1400 East	01/20/2022 20:44:57	Dispatched and cancelled en route	10BF	Cancelled en route	CF22- 2533	Officer reviewed	1	ALARMF
455 South 700 East	03/06/2022 11:22:30	Dispatched and cancelled en route	1CF	Cancelled en route	CF22- 8118	Officer reviewed	2	ALARMF
455 South 700 East	01/06/2022 21:48:01	Alarm system activation, no fire - unintentional	1CF	Investigate	CF22- 854	Officer reviewed	3	ALARMW
4603 West 2100 South	01/25/2022 13:00:58	Dispatched and cancelled en route	14FF	Cancelled en route	CF22- 3052	Officer reviewed	1	ALARMF
4603 West 2100 South	01/17/2022 19:54:29	Dispatched and cancelled en route	14FF	Cancelled en route	CF22- 2150	Officer reviewed	1	ALARMF
4650 West 700 South	02/22/2022 11:56:07	System malfunction, other	9AF	Investigate	CF22- 6594	Officer reviewed	2	ALARMW
4650 West 700 South	01/06/2022 09:29:35	Unintentional transmission of alarm, other	9AF	Investigate	CF22- 725	Officer reviewed	1	ALARMF
4883 West DOUGLAS CORRIGAN Way	03/27/2022 00:21:16	System malfunction, other	9AF	Investigate	CF22- 10660	Officer reviewed	1	ALARMF
4883 West DOUGLAS CORRIGAN Way	03/02/2022 03:27:23	Dispatched and cancelled en route	9AF	Cancelled en route	CF22- 7503	Officer reviewed	1	ALARMF
500 South FOOTHILL Boulevard	01/27/2022 13:37:27	Dispatched and cancelled en route	10BF	Cancelled en route	CF22- 3313	Officer reviewed	1	ALARMF
500 South FOOTHILL Boulevard	01/17/2022 14:02:28	Dispatched and cancelled en route	10BF	Cancelled en route	CF22- 2115	Officer reviewed	1	ALARMF
500 South FOOTHILL Drive	03/25/2022 11:07:50	Dispatched and cancelled en route	10BF	Cancelled en route	CF22- 10437	Officer reviewed	1	ALARMF
500 South FOOTHILL Drive	02/20/2022 12:03:03	Dispatched and cancelled en route	10BF	Cancelled en route	CF22- 6346	Officer reviewed	1	ALARMF
500 South HUNTSMAN Way	02/10/2022 01:05:27	Sprinkler activation due to malfunction	10BF	Investigate	CF22- 5066	Officer reviewed	1	ALARMF
500 South HUNTSMAN Way	02/10/2022 00:37:08	Dispatched and cancelled en route	10BF	Cancelled en route	CF22- 5064	Officer reviewed	1	ALARMF
505 West 100 South	02/21/2022 19:54:18	Smoke detector activation, no fire - unintentional	2AF	Investigate	CF22- 6507	Officer reviewed	1	ALARMF
505 West 100 South	01/04/2022 22:22:47	Alarm system activation, no fire - unintentional	2AF	Investigate	CF22- 565	Officer reviewed	1	ALARMF
514 West PICKETT Circle	04/03/2022 10:36:13	Alarm system activation, no fire - unintentional	8KF	Investigate	CF22- 11520	Officer reviewed	1	ALARMF
514 West PICKETT Circle	03/02/2022 14:33:45	Unintentional transmission of alarm, other	8KF	Investigate	CF22- 7550	Officer reviewed	1	ALARMF
5151 West WILEY POST Way	03/28/2022 01:04:26	Overpressure rupture, explosion, overheat, other	9AF	Investigate	CF22- 10776	Officer reviewed	1	ALARMF
5151 West WILEY POST Way	03/21/2022 10:09:09	Dispatched and cancelled en route	9AF	Cancelled en route	CF22- 9923	Officer reviewed	1	ALARMF
5178 West 150 South 16 of 31	03/08/2022	Dispatched and	9AF	Cancelled en route	CF22-	Officer Printed On	1 : 04/04/2022 0	ALARMF

Printed On: 04/04/2022 08:39:47 AM

Address	Incident Date	Incident Type	Response Zone	Primary Action Taken	Incident Number	Incident Status	Number of Apparatus	Dispatch Code
	14:09:57	cancelled en route		1	8381	reviewed		I
5178 West 150 South	03/08/2022 13:21:58	Dispatched and cancelled en route	9AF	Cancelled en route	CF22- 8368	Officer reviewed	2	ALARMW
535 West 300 North	03/19/2022 18:41:52	False alarm or false call, other	2AF	Investigate	CF22- 9749	Officer reviewed	1	ALARMF
535 West 300 North	01/21/2022 01:37:30	False alarm or false call, other	2AF	Systems and services, other	CF22- 2542	Officer reviewed	1	ALARMF
550 South 400 East	01/29/2022 10:33:19	Alarm system activation, no fire - unintentional	1IF	Investigate	CF22- 3551	Officer reviewed	4	ALARMF
550 South 400 East	01/10/2022 10:33:38	Dispatched and cancelled en route	1IF	Cancelled en route	CF22- 1237	Officer reviewed	1	ALARMF
550 West 900 South	04/02/2022 02:05:47		6HF		CF22- 11383	Initiated	0	ALARMF
550 West 900 South	02/24/2022 10:50:52	Sprinkler activation, no fire - unintentional	6HF	Provide manpower	CF22- 6851	Officer reviewed	0	ALARMF
5520 West HAROLD GATTY Drive	02/20/2022 18:04:18	Dispatched and cancelled en route	9AF	Cancelled en route	CF22- 6390	Officer reviewed	1	ALARMF
5520 West HAROLD GATTY Drive	02/20/2022 16:37:40	Dispatched and cancelled en route	9AF	Cancelled en route	CF22- 6380	Officer reviewed	1	ALARMF
580 South 500 West	02/21/2022 20:44:16	Dispatched and cancelled en route	2CF	Cancelled en route	CF22- 6516	Officer reviewed	1	ALARMF
580 South 500 West	02/03/2022 18:34:28	Dispatched and cancelled en route	2CF	Cancelled en route	CF22- 4292	Officer reviewed	1	ALARMF
6 North RIO GRANDE Street	02/10/2022 19:21:47	Dispatched and cancelled en route	2AF	Cancelled en route	CF22- 5179	Officer reviewed	1	ALARMF
6 North RIO GRANDE Street	01/29/2022 01:34:30	Hazardous condition, other	2AF	Investigate	CF22- 3513	Officer reviewed	1	ALARMF
60 East SOUTH TEMPLE Street	03/25/2022 00:13:28		1AF		CF22- 10405	Initiated	1	ALARMF
60 East SOUTH TEMPLE Street	03/24/2022 14:04:43	Alarm system sounded due to malfunction	1AF	Investigate	CF22- 10323	Officer reviewed	1	ALARMF
607 East 200 South	03/02/2022 10:30:16	Dispatched and cancelled en route	1KF	Cancelled en route	CF22- 7525	Officer reviewed	1	ALARMF
607 East 200 South	01/23/2022 17:28:38	Dispatched and cancelled en route	1KF	Cancelled en route	CF22- 2828	Officer reviewed	1	ALARMF
61 North TOMMY THOMPSON Road	04/02/2022 13:00:12	Malicious, mischievous false call, other	9AF	Investigate	CF22- 11413	Officer reviewed	1	ALARMF
61 North TOMMY THOMPSON Road	02/27/2022 17:58:09	Malicious, mischievous false call, other	9AF	Investigate	CF22- 7229	Officer reviewed	1	ALARMF
615 South 6400 West	02/04/2022 13:55:27	Unintentional transmission of alarm, other	9AF	Investigate	CF22- 4377	Officer reviewed	1	ALARMF
615 South 6400 West	01/20/2022 15:09:49	Unintentional transmission of alarm, other	9AF	Investigate	CF22- 2501	Officer reviewed	1	ALARMF
641 West NORTH TEMPLE Street	02/14/2022 05:06:28	False alarm or false call, other	2AF	Investigate	CF22- 5593	Officer reviewed	1	ALARMF
641 West NORTH TEMPLE Street	01/04/2022 06:35:48	Water problem, other	2AF	Investigate	CF22- 448	Officer reviewed	1	ALARMF
645 South 1300 East	03/31/2022 23:08:37	Unintentional transmission of alarm, other	5BF	Investigate	CF22- 11254	Officer reviewed	1	ALARMF
645 South 1300 East	02/13/2022 17:07:09	System malfunction, other	5BF	Investigate	CF22- 5543	Officer reviewed	1	ALARMF
650 South 300 East	02/18/2022 13:58:20	Dispatched and cancelled en route	1DF	Cancelled en route	CF22- 6085	Officer reviewed	1	ALARMF
650 South 300 East	01/10/2022 08:46:06	Dispatched and cancelled en route	1DF	Cancelled en route	CF22- 1224	Officer reviewed	1	ALARMF
688 North SIR PATRICK Drive	03/08/2022 20:52:27	Smoke detector activation, no fire - unintentional	11AF	Investigate	CF22- 8432	Officer reviewed	1	ALARMF
688 North SIR PATRICK Drive	01/31/2022 18:25:44	Dispatched and cancelled en route	11AF	Cancelled en route	CF22- 3881	Officer reviewed	1	ALARMF
714 East KENSINGTON	01/10/2022	Dispatched and	5KF	Cancelled en route	CF22-	Officer	1	ALARMF

Address	Incident Date	Incident Type	Response Zone	Primary Action Taken	Incident Number	Incident Status	Number of Apparatus	Dispatch Code
Avenue	11:28:19	cancelled en route			1247	reviewed		
714 East KENSINGTON Avenue	01/07/2022 12:26:35	Dispatched and cancelled en route	5KF	Cancelled en route	CF22- 906	Officer reviewed	1	ALARMF
737 South 1300 East	03/28/2022 18:09:42	False alarm or false call, other	5BF	Investigate	CF22- 10874	Officer reviewed	1	ALARMF
737 South 1300 East	01/25/2022 08:23:34	False alarm or false call, other	5BF	Information, investigation & enforcement, other	CF22- 3023	Officer reviewed	1	ALARMF
824 South 400 West	02/08/2022 08:30:44		6HF		CF22- 4850	Initiated	0	ALARMF
824 South 400 West	01/29/2022 09:19:45	Local alarm system, malicious false alarm	6HF	Restore fire alarm system	CF22- 3543	Officer reviewed	0	ALARMF
828 South RICHARDS Street	02/24/2022 11:32:42	Dispatched and cancelled en route	8EF	Cancelled en route	CF22- 6858	Officer reviewed	1	ALARMW
828 South RICHARDS Street	02/24/2022 04:31:26	Water or steam leak	8EF	Shut down system	CF22- 6819	Officer reviewed	2	ALARMW
840 South 1300 East	02/28/2022 01:31:21	False alarm or false call, other	5HF	Investigate	CF22- 7261	Officer reviewed	1	ALARMF
840 South 1300 East	02/15/2022 12:21:41	Dispatched and cancelled en route	5HF	Cancelled en route	CF22- 5723	Officer reviewed	1	ALARMF
875 South DONNER Way	03/03/2022 13:08:52	Dispatched and cancelled en route	10DF	Cancelled en route	CF22- 7673	Officer reviewed	1	ALARMF
875 South DONNER Way	03/03/2022 10:48:31	Dispatched and cancelled en route	10DF	Cancelled en route	CF22- 7660	Officer reviewed	1	ALARMF
95 South STATE Street	02/24/2022 12:20:34	Dispatched and cancelled en route	1AF	Cancelled en route	CF22- 6861	Officer reviewed	1	ALARMF
95 South STATE Street	01/24/2022 20:34:28	Alarm system activation, no fire - unintentional	1AF	Investigate	CF22- 2985	Officer reviewed	1	ALARMF
Alarm Count: 1								
10 East EXCHANGE Place	03/14/2022 12:24:27	Dispatched and cancelled en route	1HF	Cancelled en route	CF22- 9088	Officer reviewed	2	ALARMW
100 East SOUTH TEMPLE Street	03/05/2022 15:23:43	Dispatched and cancelled en route	1AF	Cancelled en route	CF22- 7925	Officer reviewed	1	ALARMF
100 North MARIO CAPECCHI Drive	05:03:49	False alarm or false call, other	4EF	Investigate	CF22- 11132	Officer reviewed	1	ALARMF
100 South 1100 East	09:21:56	False alarm or false call, other	5EF	Investigate	CF22- 7783	Officer reviewed	1	ALARMF
100 South MARIO CAPECCHI Drive	01/28/2022 02:52:00	Smoke detector activation due to malfunction	10AF	Investigate	CF22- 3388	Officer reviewed	1	ALARMF
1011 North CATHERINE Street	02/23/2022 14:08:20	Dispatched and cancelled en route	7AF	Cancelled en route	CF22- 6746	Officer reviewed	1	ALARMF
1020 South MAIN Street	02/23/2022 13:02:27	Alarm system sounded due to malfunction	8EF	Investigate	CF22- 6740	Officer reviewed	1	ALARMF
1024 South 200 West	14:43:08	Dispatched and cancelled en route	8EF	Cancelled en route	CF22- 11187	Officer reviewed	1	ALARMF
1025 South 700 West	03/09/2022 07:48:13	Alarm system activation, no fire - unintentional	6DF	Investigate	CF22- 8471	Officer reviewed	1	ALARMW
1027 West WENCO Drive	03/02/2022 16:18:51	Smoke detector activation, no fire - unintentional	6PF	Investigate	CF22- 7571	Officer reviewed	1	ALARMF
1028 East 2100 South	01/06/2022 19:41:18	False alarm or false call, other	3CF	Investigate	CF22- 837	Officer reviewed	1	ALARMF
1037 East WILSON Avenue	01/12/2022 19:33:40	Smoke detector activation due to malfunction	3BF	Investigate	CF22- 1545	Officer reviewed	1	ALARMF
1038 North TOPAZ Drive	04/03/2022 12:46:58	Dispatched and cancelled en route	7BF	Cancelled en route	CF22- 11534	Officer reviewed	1	ALARMF
1044 East 2100 South	03/11/2022 06:19:12	Unintentional transmission of alarm, other	3CF	Investigate	CF22- 8676	Officer reviewed	1	ALARMF
1051 South 300 West	02/04/2022 15:34:32	False alarm or false call, other	8EF	Information, investigation & enforcement, other	CF22- 4394	Officer reviewed	0	ALARMF
1076 East 700 South	03/02/2022 14:43:12	Dispatched and cancelled en route	5GF	Cancelled en route	CF22- 7554	Officer reviewed	1	ALARMF

			-	B 1 1 1 1 1				D .
Address	Incident Date	Incident Type	Response Zone	Primary Action Taken	Incident Number	Incident Status	Number of Apparatus	Dispatch Code
1081 South LAKE Street	02/26/2022 08:23:39	Smoke or odor removal	5KF	Investigate fire out on arrival	CF22- 7066	Officer reviewed		ALARMF
1085 North GARNETTE Circle	03/10/2022 18:57:27	Dispatched and cancelled en route	7AF	Cancelled en route	CF22- 8639	Officer reviewed	1	ALARMF
1095 South 300 West	01/17/2022 13:53:54	Dispatched and cancelled en route	8EF	Cancelled en route	CF22- 2113	Officer reviewed	1	ALARMF
1095 South 4800 West	01/20/2022 00:23:13	False alarm or false call, other	14FF	Investigate	CF22- 2439	Officer reviewed	1	ALARMW
1095 West MOTOR Avenue	02/15/2022 09:49:47	Dispatched and cancelled en route	7BF	Cancelled en route	CF22- 5709	Officer reviewed	1	ALARMF
110 West 600 South	03/30/2022 17:06:22	Alarm system activation, no fire - unintentional	8LF	Investigate	CF22- 11071	Officer reviewed	1	ALARMF
111 East 300 South	01/29/2022 18:22:18	Alarm system activation, no fire - unintentional	1FF	Investigate	CF22- 3594	Officer reviewed	1	ALARMF
111 North C Street	03/10/2022 02:52:40	False alarm or false call, other	4AF	Information, investigation & enforcement, other	CF22- 8561	Officer reviewed	1	ALARMF
1135 East 2100 South	03/03/2022 11:43:28	False alarm or false call, other	3BF	Investigate	CF22- 7663	Officer reviewed	1	ALARMF
1136 South 3600 West	03/11/2022 10:16:35	False alarm or false call, other	14EF	Investigate	CF22- 8700	Officer reviewed	1	ALARMF
1140 East BRICKYARD Road	03/22/2022 11:31:48	Dispatched and cancelled en route	3EF	Cancelled en route	CF22- 10063	Officer reviewed	1	ALARMF
1140 South 3200 West	01/10/2022 06:53:10	Alarm system sounded due to malfunction	14EF	Investigate	CF22- 1214	Officer reviewed	1	ALARMF
1142 South PROSPECT Street	02/24/2022 18:47:32	Public service assistance, other	6LF	Provide manpower	CF22- 6894	Officer reviewed	0	ALARMF
1146 South ALTON Way	02/06/2022 08:56:39	Dispatched and cancelled en route	10DF	Cancelled en route	CF22- 4615	Officer reviewed	1	ALARMF
115 South 300 East	03/26/2022 08:14:30	Alarm system activation, no fire - unintentional	1GF	Investigate	CF22- 10554	Officer reviewed	1	ALARMF
1155 East 2100 South	03/07/2022 11:41:23	Dispatched and cancelled en route	3BF	Cancelled en route	CF22- 8249	Officer reviewed	2	ALARMW
1171 South RICHARDS Street	03/26/2022 14:17:14	Outside rubbish fire, other	8EF	Extinguishment by fire service personnel	CF22- 10593	Officer reviewed	1	ALARMF
1174 South DENVER Street	03/13/2022 12:13:10	Alarm system sounded due to malfunction	8GF	Investigate	CF22- 8967	Officer reviewed	1	ALARMF
1175 South MERIDIAN PARK Road	01/06/2022 19:50:56	Water problem, other	14FF	Investigate	CF22- 841	Officer reviewed	1	ALARMW
1180 East ZENITH Avenue	02/08/2022 14:53:12	Dispatched and cancelled en route	3EF	Cancelled en route	CF22- 4900	Officer reviewed	1	ALARMF
1180 North FLYER Way	02/25/2022 11:27:16	Dispatched and cancelled en route	11AF	Cancelled en route	CF22- 6970	Officer reviewed	1	ALARMF
1184 East BLAINE Avenue	03/08/2022 17:13:21	Dispatched and cancelled en route	3BF	Cancelled en route	CF22- 8400	Officer reviewed	1	ALARMF
1186 North VICTORIA Way	01/17/2022 18:06:12	False alarm or false call, other	7BF	Investigate	CF22- 2138	Officer reviewed	1	ALARMF
12 North C Street	02/21/2022 12:56:54	Smoke detector activation, no fire - unintentional	1JF	Investigate	CF22- 6469	Officer reviewed	1	ALARMF
120 South CONNOR Road	02/05/2022 02:13:58	Sprinkler activation due to malfunction	10AF	Shut down system	CF22- 4457	Officer reviewed	1	ALARMF
1215 East WILMINGTON Avenue	01/26/2022 21:23:16	False alarm or false call, other	3CF	Investigate	CF22- 3232	Officer reviewed	1	ALARMF
122 North K Street	02/10/2022 02:40:28	Good intent call, other	4CF	Information, investigation & enforcement, other	CF22- 5069	Officer reviewed	1	ALARMF
122 South 900 East	04/01/2022 06:59:37		1CF		CF22- 11276	Initiated	1	ALARMF
122 West SOUTH TEMPLE Street	03/30/2022 10:43:18	Dispatched and cancelled en route	2GF	Cancelled en route	CF22- 11037	Officer reviewed	1	ALARMF
123 North WRIGHT BROTHERS Drive	02/04/2022 13:31:58	Unintentional transmission of alarm, other	9AF	Investigate	CF22- 4370	Officer reviewed	1	ALARMF
1234 East ALAMEDA Avenue	01/10/2022 21:43:59	False alarm or false call, other	4DF	Information, investigation & enforcement, other	CF22- 1320	Officer reviewed	1	ALARMF

Address	Incident Date	Incident Type	Response Zone	Primary Action Taken	Incident Number	Incident Status	Number of Apparatus	Dispatch Code
1236 West 900 North	03/29/2022 15:45:34		7AF		CF22- 10966	Initiated	1	ALARMF
1239 South GLENDALE Drive	02/28/2022 17:47:37	Overheated motor	6MF	Investigate	CF22- 7340	Officer reviewed	3	ALARMF
1240 East STRINGHAM Avenue	03/07/2022 13:12:58	Dispatched and cancelled en route	3CF	Cancelled en route	CF22- 8264	Officer reviewed	1	ALARMF
1240 North AMERICAN BEAUTY Drive	01/06/2022 13:31:43	False alarm or false call, other	7BF	Investigate	CF22- 772	Officer reviewed	1	ALARMF
1242 East WILMINGTON Avenue	01/14/2022 06:30:52	Unintentional transmission of alarm, other	3CF	Investigate	CF22- 1691	Officer reviewed	1	ALARMF
1275 East 2ND Avenue	03/13/2022 15:45:43	False alarm or false call, other	4BF	Investigate	CF22- 8991	Officer reviewed	1	ALARMF
1276 South 500 West	03/25/2022 09:45:37	Dispatched and cancelled en route	8AF	Cancelled en route	CF22- 10433	Officer reviewed	1	ALARMW
1291 South EMERY Street	02/17/2022 13:15:01	Dispatched and cancelled en route	6MF	Cancelled en route	CF22- 5961	Officer reviewed	0	ALARMF
1297 North GARNETTE Street	03/16/2022 07:17:11	Carbon monoxide incident	7AF	HazMat detection, monitoring, sampling, & analysis	CF22- 9286	Officer reviewed	1	ALARMF
1307 South 900 West	03/25/2022 09:44:58	Dispatched and cancelled en route	6PF	Cancelled en route	CF22- 10434	Officer reviewed	0	ALARMF
131 North 800 West	04/02/2022 11:32:28	False alarm or false call, other	7BF	Investigate	CF22- 11407	Officer reviewed	1	ALARMF
1310 East 200 South	02/01/2022 17:01:30	Cooking fire, confined to container	5EF	Investigate	CF22- 3996	Officer reviewed	1	ALARMF
1320 West 1000 North	03/26/2022 17:15:00	Dispatched and cancelled en route	7AF	Cancelled en route	CF22- 10612	Officer reviewed	1	ALARMF
1327 South EDISON Street	03/06/2022 07:11:30	Carbon monoxide detector activation, no CO	8CF	Investigate	CF22- 8065	Officer reviewed	1	ALARMF
133 West 200 North	03/25/2022 06:11:46		2AF		CF22- 10415	Initiated	1	ALARMF
1333 South EMIGRATION Circle	01/28/2022 08:29:14	Heat from short circuit (wiring), defective/worn	10EF	Investigate	CF22- 3412	Officer reviewed	1	ALARMF
134 South MAIN Street	03/02/2022 11:53:17	Dispatched and cancelled en route	2GF	Cancelled en route	CF22- 7536	Officer reviewed	1	ALARMF
135 West 200 South	01/21/2022 10:55:51	False alarm or false call, other	2DF	Investigate	CF22- 2573	Officer reviewed	1	ALARMF
1352 South 1200 West	02/27/2022 18:25:25	Smoke detector activation, no fire - unintentional	6MF	Investigate	CF22- 7230	Officer reviewed	0	ALARMF
1357 East LOGAN Avenue	03/07/2022 21:53:17	CO detector activation due to malfunction	5LF	Investigate	CF22- 8319	Officer reviewed	1	ALARMF
1375 South AMBASSADOR Way	03/20/2022 17:06:37	Dispatched and cancelled en route	10CF	Cancelled en route	CF22- 9846	Officer reviewed	1	ALARMF
1381 West GLENROSE Drive	03/06/2022 20:14:01	Carbon monoxide incident	6KF	Investigate	CF22- 8176	Officer reviewed	1	ALARMF
1390 East PRESIDENTS Circle	01/26/2022 10:51:40	Dispatched and cancelled en route	4EF	Cancelled en route	CF22- 3163	Officer reviewed	1	ALARMF
1394 South 900 East	02/11/2022 18:10:27	Dispatched and cancelled en route	5KF	Cancelled en route	CF22- 5318	Officer reviewed	1	ALARMF
1395 East 100 South	01/21/2022 11:47:55	False alarm or false call, other	4BF	Information, investigation & enforcement, other	CF22- 2579	Officer reviewed	1	ALARMF
140 South 300 West	01/11/2022 15:45:18	Dispatched and cancelled en route	2GF	Cancelled en route	CF22- 1414	Officer reviewed	1	ALARMF
1404 West GILLESPIE Avenue	03/06/2022 07:27:43	Carbon monoxide detector activation, no CO	6JF	Investigate	CF22- 8069	Officer reviewed	1	ALARMF
1415 East LAIRD Circle	04/04/2022 01:24:10		5IF		CF22- 11606	Initiated	2	ALARMF
1418 East MILITARY Way	01/25/2022 22:20:56	Dispatched and cancelled en route	4BF	Cancelled en route	CF22- 3104	Officer reviewed	1	ALARMF
142 West 200 North	03/31/2022		2AF		CF22-	Initiated	2	ALARMF

Address	Incident Date	Incident Type	Response Zone	Primary Action Taken	Incident Number	Incident Status	Number of Apparatus	Dispatch Code
	09:41:03				11151		rippulatao	
1422 East MILITARY Way	03/02/2022 13:59:10	Dispatched and cancelled en route	4BF	Cancelled en route	CF22- 7545	Officer reviewed	1	ALARMF
1430 East PRESIDENTS Circle	03/04/2022 14:08:14	Dispatched and cancelled en route	4EF	Cancelled en route	CF22- 7812	Officer reviewed	1	ALARMF
1431 East GILMER Drive	03/05/2022 18:26:12	Smoke detector activation, no fire - unintentional	5IF	Investigate	CF22- 7951	Officer reviewed	1	ALARMF
1431 South 1000 East	03/06/2022 06:43:37	False alarm or false call, other	5DF	Investigate fire out on arrival	CF22- 8058	Officer reviewed	1	ALARMF
1435 East 100 South	01/21/2022 17:35:18	Dispatched and cancelled en route	4BF	Cancelled en route	CF22- 2610	Officer reviewed	1	ALARMF
1435 East CIRCLE Way	02/20/2022 15:48:06	False alarm or false call, other	4BF	Information, investigation & enforcement, other	CF22- 6377	Officer reviewed	1	ALARMF
1442 East PERRYS HOLLOW Drive	03/31/2022 23:20:22	False alarm or false call, other	4BF	Investigate	CF22- 11256	Officer reviewed	1	ALARMF
146 TERMINAL SL[OVERSIZED BAG BELTS 2ND FLOOR]	03/16/2022 23:48:29	False alarm or false call, other	12BF	Investigate	CF22- 9393	Officer reviewed	2	ALARMF
1461 East 900 South	01/24/2022 07:52:25	False alarm or false call, other	5IF	Information, investigation & enforcement, other	CF22- 2890	Officer reviewed	1	ALARMF
1467 West 800 South	02/26/2022 13:46:05	Carbon monoxide incident	6JF	Investigate	CF22- 7086	Officer reviewed	0	ALARMF
1470 South 2000 East	04/03/2022 16:56:04		10CF		CF22- 11557	Initiated	1	ALARMF
1470 South 400 West	02/18/2022 16:01:09	False alarm or false call, other	8HF	Investigate	CF22- 6105	Officer reviewed	1	ALARMF
1475 South 5070 West	03/22/2022 01:11:21	Sprinkler activation due to malfunction	14JF	Shut down system	CF22- 10025	Officer reviewed	2	ALARMF
1476 South 200 East	02/22/2022 06:59:10	Alarm system sounded due to malfunction	8CF	Investigate	CF22- 6563	Officer reviewed	1	ALARMF
1477 West 200 South	01/27/2022 12:13:48	Dispatched and cancelled en route	6BF	Cancelled en route	CF22- 3304	Officer reviewed	1	ALARMF
1486 South DISTRIBUTION Drive	01/27/2022 15:19:59	Water problem, other	14BF	Shut down system	CF22- 3325	Officer reviewed	1	ALARMF
1495 East 100 South	01/25/2022 15:08:08	Steam, other gas mistaken for smoke, other	4EF	Investigate	CF22- 3064	Officer reviewed	1	ALARMF
1499 South 4800 West	01/25/2022 13:10:34	Alarm system activation, no fire - unintentional	14FF	Investigate	CF22- 3053	Officer reviewed	1	ALARMF
15 South STATE Street	02/20/2022 08:47:35	Smoke detector activation, no fire - unintentional	1AF	Investigate	CF22- 6336	Officer reviewed	1	ALARMF
15 West 200 South	01/05/2022 14:31:21	Dispatched and cancelled en route	2DF	Cancelled en route	CF22- 649	Officer reviewed	1	ALARMF
15 West SOUTH TEMPLE Street	03/11/2022 08:57:48	Dispatched and cancelled en route	2GF	Cancelled en route	CF22- 8689	Officer reviewed	1	ALARMF
150 North MAIN Street	03/28/2022 20:12:17	False alarm or false call, other	2BF	Investigate	CF22- 10891	Officer reviewed	1	ALARMF
150 West GOLTZ Avenue	02/24/2022 02:40:12	Dispatched and cancelled en route	8EF	Cancelled en route	CF22- 6812	Officer reviewed	1	ALARMF
151 South REGENT Street	01/20/2022 10:30:50	Dispatched and cancelled en route	1EF	Cancelled en route	CF22- 2468	Officer reviewed	1	ALARMF
155 North 400 West	01/31/2022 05:43:51	Dispatched and cancelled en route	2AF	Cancelled en route	CF22- 3748	Officer reviewed	1	ALARMF
155 South 1400 East	02/23/2022 13:08:51	Dispatched and cancelled en route	4EF	Cancelled en route	CF22- 6741	Officer reviewed	1	ALARMF
1571 East GLEN ARBOR Street	02/23/2022 17:28:03	Public service	3BF	Investigate	CF22- 6766	Officer reviewed	1	ALARMF
1575 South STATE Street	03/29/2022 15:58:06	Smoke scare, odor of smoke	8CF	Investigate	CF22- 10968	Officer reviewed	1	ALARMF
158 North MAIN Street	02/27/2022 13:05:34	Dispatched and cancelled en route	2BF	Cancelled en route	CF22- 7199	Officer reviewed	1	ALARMF
159 West 300 South	01/19/2022	False alarm or false call,	2DF	Investigate	CF22-	Officer	1	ALARMF

OH 16.31 other Control 2324 reviewed ALARMF 1806 East LARD Avenue 62/15/202 Englatement and the to malfunction of the to malfunction of the to malfunction of the total cancelled en nouse 016F Restore firm alarm, CT22 Officier reviewed 1 ALARMF 181 West 600 South 02/15/202 Dispatched and cancelled en nouse 01F Investigate CF22 Officier reviewed 1 ALARMF 1820 East VALED(EST 03/23/202 Cancelled en nouse 01F Investigate CF22 Officier reviewed 1 ALARMF 1827 South WASATCH Dev 02/22/2022 Dispatched and cancelled en nouse 0FF Cancelled en rouse CF22 Officier reviewed 1 ALARMF 1835 South 300 02/22/202 Dispatched and cancelled en nouse CF22 Officier reviewed 1 ALARMF 1845 South 300 East 01/14 5/18 Smoke denchor activity in reviewed CF22 Officier reviewed 1 ALARMF 1855 South 300 East 01/04/202 Disord monocade denchor activity in reviewed CF22 Officier reviewed 1	Address	Incident Date	Incident Type	Response Zone	Primary Action Taken	Incident Number	Incident Status	Number of Apparatus	Dispatch Code
18.55.03 adduction due to malfunction ypatem 4004 reviewed 161 West 600 South 12/25/222 Spatished and cancellid en route 8LF Cancellid en route 6722 Officer reviewed 1 ALARMF 1620 East 7/AECREST 03/25/2022 Cancellid en route 0162 Treviewed 1 ALARMF 1620 East 7/AECREST 03/25/2022 Strotte dietectur entreviewed 1344 Investigate CF22 Officer reviewed 1 ALARMF 1625 South 300 20/22/202 Strotte dietectur entreviewod 1345 Investigate CF22 Officer reviewed 1 ALARMF 165 South 300 East 01/37/2022 Despatched and enclude on route SEF Cancelled en route CF22 Officer reviewed 1 ALARMF 165 South 300 East 21/21/202 Cancelled en route SFE Cancelled en route CF22 Officer 1 ALARMF 165 South 300 East 21/21/202 Cancelled en route SFE Cancelled en route CF22 Officer 1 ALARMF <tr< th=""><th></th><th>04:18:31</th><th>other</th><th></th><th></th><th>2334</th><th>reviewed</th><th></th><th></th></tr<>		04:18:31	other			2334	reviewed		
12.26.31 cancelled en route 6077 reviewed 1 ALARME Avenue 12.95.31 cancelled en route 19.95.22 Cancon monoxide (CO 10FF Investigate C12.2 Officer 1 ALARME 1827 South WASATCH Driv 22012/222 Depatched and antivation, no fre - antivation, no fre - unintentional IFF Cancelled en route CF22- (CF22- (CF22- (CF22- CF22- (CF22- CF22- (CF22- CF22- (CF22- CF22- (CF22- CF22- (CF22- CF22- (CF22- CF22- CF22- (CF22- CF22- (CF22- CF22- CF22- (CF22- CF22- (CF22- CF22- CF22- CF22- (CF22- CF22- CF22- CF22- CF22- CF22- CF12- CF22- CF22- CF22- CF12- CF22- CF22- CF12- CF22- CF12- CF22- CF22- CF12- CF12- CF12- CF22- CF12	1605 East LAIRD Avenue		activation due to	10EF				1	ALARMF
Avenue 09.58.22 dictor activation, no CO 10.70 reviewed 1627 South VASATCH Driv 22312.22 Dispatched and activation, no file - unitational activation, no file - tivativation, no file - activation activation, no file - activation activation, no file - activati activati actrivation activati actri activation, no file - actr	161 West 600 South			8LF	Cancelled en route			1	ALARMF
23.31.25 activation, no fire- unintentional " 4169 reviewed 1635 South 300 02/23/2022 Dispatched and ancelled en route SE Cancelled en route 7308 Officer reviewed 1 ALARMF 165 South 1000 East 03/17/7022 Dispatched and 01.45.18 SE Cancelled en route GF22 Officer reviewed 1 ALARMF 165 South 1000 East 03/17/7022 Carbon monoxide detector activation, no fire- uninitactivation 1GF Investigate CF22 Officer reviewed 1 ALARMF 1650 East 2700 South 01/04/2022 Carbon monoxide detector activation, no (CO 3EF Investigate CF22 Officer reviewed 1 ALARMF 1687 South 600 East 02/23/2022 Dispatched and 10.52.04 13/F Cancelled en route CF22 Officer reviewed 1 ALARMF 170 South MAIN Street 03/6/02/22 Cancelled en route CF22 Officer reviewed 1 ALARMF 170 East CAMPUS CENTER 01/9/12/22 Cancelled en route CF22 Officer reviewed 1 ALARM			detector activation, no	10EF	Investigate			1	ALARMF
WINDUSTRUL SUPPLY 13.35.48 cancelled en route 7308 reviewed 165 South 1000 East 03/17/2022 Dispatched and 6EF Cancelled en route CF22- Officer 1 ALARMF 165 South 300 East 21/16/40 activation, no fro- 1GF Investigate CF22- Officer 1 ALARMF 1650 East 2700 South 01/04/202 Canco monoxide SEF Investigate CF22- Officer 1 ALARMF 1675 South 600 East 02/23/2022 Dispatched and SF Cancelled en route CF22- Officer 1 ALARMF 1685 South 600 East 02/32/2022 Dispatched and SF Cancelled en route CF22- Officer 1 ALARMF 1685 South 600 East 02/32/2022 Dispatched and 13AF Cancelled en route CF22- Officer 1 ALARMF 1705 South MAIN Street 03/30/2022 Dispatched and 10BF Cancelled en route CF22- Officer 1 ALARMF 1720 East 7300 South	1627 South WASATCH Drive		activation, no fire -	13AF	Investigate			1	ALARMF
O14-518 cancelled en route 9390 reviewed 165 South 300 East 2/1164.40 activation, on fre- unintentional 1GF Investigate 2639 Officer reviewed 1 ALARMF 1650 East 2700 South 2/1164.40 activation, on fre- activation, on fre- concelled en route 3EF Investigate CF22- 672 Officer reviewed 1 ALARMF 1675 South 600 East 0.9273/2022 Dispatched and concelled en route 3EF Cancelled en route CF22- 6721 Officer reviewed 1 ALARMF 1687 South ANN Street 0.932/2022 Dispatched and route intention 13AF Cancelled en route CF22- 722 Initiated 1 ALARMF 1705 South ANIN Street 0.93/2022 Lapatched and route intention 10EF Investigate CF22- 8003 Officer 7222 1 ALARMF 1720 East 1300 South 0.93/62022 Lapatched and route intention 10EF Investigate CF22- 8003 Officer 7222 1 ALARMF 1720 East CADNPO 0.93/62022 Lapatched and route inteninintention 10EF Inves	W[INDUSTRIAL SUPPLY			8IF	Cancelled en route			1	ALARMF
11:16:4.0 activation, no fire - unintentional 26.3 reviewed 1850 East 2700 South 02/01/02/022 Carbon monoide CO 3EF Investigate CF22- 562 Officar reviewed 1 ALARMF 1875 South 600 East 02/23/2022 Dispatched and cancelied en route 8JF Cancelled en route CF22- 6721 Officar reviewed 1 ALARMF 1867 South DEVONSHIRE 03/22/2022 Dispatched and cancelied en route 13AF Cancelled en route CF22- 6721 Officar reviewed 1 ALARMF 170 South MAIN Street 03/30/2022 Alarm system activation, 100:34 10F Investigate CF22- 9305 Initiated 1 ALARMF 1722 South SHELMERDINE 03/16/2022 Dispatched and cancelled en route 10BF Cancelled en route CF22- 9305 Initiated 1 ALARMF 1722 South SHELMERDINE 03/06/2022 Dispatched and cancelled en route 13BF Cancelled en route CF22- 9305 Officar reviewed 1 ALARMF 1723 East REDONDO 03/16/2022 Dispatched and cancelled en route 13BF	165 South 1000 East			5EF	Cancelled en route			1	ALARMF
22:01:49 detector activation, no 56 reviewed 1875 South 600 East 02/23:202 Dispatched and 10:52:04 8JF Cancelled en route CF22 Officier reviewed 1 ALARMF 1875 South DEVONSHIRE 03/22/2022 Dispatched and 13AF Cancelled en route CF22 Officer reviewed 1 ALARMF 170 South MAIN Street 03/20202 Jarabian Concelled en route CF22 Officer reviewed 1 ALARMF 170 South MAIN Street 03/02/022 Jarabian Concelled en route CF22 Officer reviewed 1 ALARMF 1720 East 1300 South 03/16/2022 Jarabian Concelled en route CF22 Officer reviewed 1 ALARMF 1720 East REDONDO 03/02/022 Dispatched and dispatched and 13/05 10/06/04 13/06/04 1 ALARMF 1742 East REDONDO 03/02/022 Dispatched and 13/06 10/06/04 1 ALARMF 1742 West GERTIE Avenue 01/2/0202 Jarabian Concelled en route CF22 Officer reviewed 1 ALARMF 1744 West GERTIE A	165 South 300 East		activation, no fire -	1GF	Investigate			1	ALARMF
10.52.04 cancelled en route 6721 reviewed 1867 South DEVONSHIRE 03/3/2/2022 Dispatched and cancelled en route 13AF Cancelled en route CF22. Officer reviewed 1 ALARMF 170 South MAIN Strete 03/3/2022 Jamm system activation, office - unintentional 10EF Investigate CF22. Officer reviewed 1 ALARMF 1700 East 1300 South 03/16/2022 Jamm system activation, office - unintentional 10EF Investigate CF22. Officer reviewed 1 ALARMF 1720 East CAMPUS CENTER 01/21/2022 Dispatched and office - unintentional 10BF Cancelled en route CF22. Officer reviewed 1 ALARMF 1727 South SHELMERDINE 03/06/2022 Dispatched and office - unintentional 13BF Cancelled en route CF22. Initiated 1 ALARMF 1732 East REDONDO 03/21/2022 Dispatched and fice - unintentional 14F Investigate CF22. Initiated 1 ALARMF 1740 West GRETIE Avenue 01/20/202 Alarm system activation, no 10EF	1650 East 2700 South		detector activation, no	3EF	Investigate			1	ALARMF
Drive 17:54:56 cancelled en route 10093 reviewed 170 South MAIN Street 03/30/2022 Alarm system activation, 10EF Investigate CF22, 11063 Initiated 1 ALARMF 1709 East 1300 South 03/16/2022 Alarm system activation, 10EF Investigate CF22, 076 1 ALARMF 1720 East CAMPUS CENTER 01/21/2022 Dispatched and cancelled en route 10BF Cancelled en route CF22, 076 076 1 ALARMF 727 South SHELMERDINE 01/21/2022 Dispatched and cancelled en route 13BF Cancelled en route CF22, 076 1 ALARMF 7122 East REDONDO 03/06/2022 Dispatched and cancelled en route 13BF Cancelled en route CF22, 076 1 ALARMF 7140 West GERTIE Avenue 01/20/2022 Alarm system activation, no fire - unintentonical 11AF Investigate CF22, 076 1 ALARMF 7144 West GERTIE Avenue 02/04/2022 Detector activation, no fire - unintentonical 10EF Investigate CF22, 076 Officer 1 ALARMF	1675 South 600 East			8JF	Cancelled en route			1	ALARMF
18:5:05 1108 1709 East 1300 South 03/16/202 Alarm system activation, no fire - unintentional 10EF Investigate 27.2 Officer reviewed 1 ALARMF 1720 East CAMPUS CENTER 01/2/12022 Dispatched and cancelled en route 10BF Cancelled en route 2628 reviewed 1 ALARMF 1727 South SHELMERDINE 03/06/2022 Dispatched and cancelled en route 13BF Cancelled en route 2628 reviewed 1 ALARMF 1732 East REDONDO 03/21/2022 Dispatched and cancelled en route 13BF Cancelled en route CF22- Officer reviewed 1 ALARMF 1740 West GERTIE Avenue 03/20/2022 Alarm system activation, no fire - unintentional no fire - unintentional 10EF Investigate CF22- Officer reviewed 1 ALARMF 1745 South MILESTONE 03/06/2022 Detector activation, no fire - unintentional no fire - unintentional 10EF Investigate CF22- Officer reviewed 1 ALARMF 1745 South MILESTONE 02/04/2022 Detector activation, no fire - unintentional 10EF				13AF	Cancelled en route			1	ALARMF
10:06:34 no fire 'unintentional 0 9305 reviewed 1720 East CAMPUS CENTER 01/21/2022 Dispatched and cancelled en route 10BF Cancelled en route 2622 Officer reviewed 1 ALARMF 1727 South SHELMERDINE 03/06/2022 Dispatched and cancelled en route 13BF Cancelled en route CF22- Officer reviewed 1 ALARMF 7232 East REDONDO 03/21/2022 Dispatched and cancelled en route 13BF Cancelled en route CF22- Officer reviewed 1 ALARMF 744 West 300 South 03/01/2022 Cancelled en route CF22- Officer reviewed 1 ALARMF 7140 West GERTIE Avenue 01/20/2022 Alarm system activation, no fire - unintentional 11AF Investigate CF22- Officer reviewed 1 ALARMF 7145 South MILESTONE 03/06/2022 Ealea alarm or false call. 14BF Investigate CF22- Officer reviewed 1 ALARMF 7145 South MILESTONE 03/06/2022 False alarm or false call. 14BF Investigate CF22-	170 South MAIN Street			2GF			Initiated	1	ALARMF
Drive 19:59:22 cancelled en route 2628 reviewed 1727 South SHELMERDINE Court 03/61/2022 BDF 80F 10iliated 1 ALARMF 1732 East REDONDO Avenue 03/21/2022 Dispatched and cancelled en route 13BF Cancelled en route CF22- 10008 Officer reviewed 1 ALARMF 174 West 300 South 03/30/2022 Jaranelled en route 12BF Cancelled en route CF22- 11072 Officer reviewed 1 ALARMF 1740 West GERTIE Avenue 01/20/2022 Alarm system activation, no fire - unintentional 114F Investigate CF22- 4366 Officer reviewed 1 ALARMF 1745 South MILESTONE 03/06/2022 False alarm or false call. 14BF Investigate CF22- 8565 Officer reviewed 1 ALARMF 1745 South MILESTONE 03/06/2022 False alarm or false call. 14BF Investigate CF22- 8565 Officer reviewed 1 ALARMF 1745 South MILESTONE 03/06/2022 Enstecher and cancelled en route 10EF Cancelled en route CF22- 8565	1709 East 1300 South			10EF	Investigate			1	ALARMF
Court07:04:3780631732 East REDOND03/21/2022 21:54:30Dispatched and cancelled en route13FCancelled en routeCF22- 10072Officer reviewed1ALARMF174 West 300 South03/30/2022 17:06:032DFCF22- 11072Initiated1ALARMF1740 West GERTIE Avenue01/20/2022 01/20222Alarm system activation, no fire - unintentional11AFInvestigateCF22- 22481Officer reviewed1ALARMF1745 South MILESTONE03/06/2022 03:66:7False alarm or false call, other14BFInvestigateCF22- 2565Officer reviewed1ALARMF1745 South MILESTONE03/06/2022 03:66:20False alarm or false call, other14BFInvestigateCF22- 2565Officer reviewed1ALARMF1745 South MILESTONE03/06/2022 03:66:20False alarm or false call, cancelled en route10EFCancelled en routeCF22- 2565Officer reviewed1ALARMF1745 South S00 West03/3/2022 03:patched and cancelled en route10EFCancelled en routeCF22- 2565Officer reviewed1ALARMF1760 East 1300 South01/17/2022 15:50:16Dispatched and cancelled en route10EFInormation, investigateCF22- CF22- 0fficerOfficer reviewed1ALARMF1760 East 1300 South01/17/2022 15:50:16Co detector activation, no due to malfunction10EFInormation, investigateCF22- CF22- Cfficer				10BF	Cancelled en route			1	ALARMF
Avenue21:54:30cancelled en route10008reviewed174 West 300 South $03/30/202$ Alarm system activation, n for - unintentional2DF $CF22$ 11072Initiated1ALARMF1740 West GERTIE Avenue $01/20/2022$ 13:15:50Alarm system activation, n for - unintentional11AFInvestigate $CF22$ 2481Officer reviewed1ALARMF1745 East HERBERT Avenue $02/04/2022$ 14:36:36Detector activation, no fire - unintentional10EFInvestigate $CF22$ 4386Officer reviewed1ALARMF1745 South MILESTONE $03/06/2022$ 15:20:48False alarm or false call, other14BFInvestigate $CF22$ 8157Officer reviewed1ALARMF1747 South 900 West $02/11/2022$ 0ispatched and 21:26:29Dispatched and cancelled en route10EFCancelled en route $CF22$ 22:06Officer reviewed1ALARMF1760 East 1300 South $01/17/2022$ 15:56:20Codetector activation fire - unintentional10EFInvestigate $CF22$ 22:07Officer reviewed1ALARMF1760 South OAK SPRINGS Drive $01/17/2022$ 15:56:20Codetector activation fire - unintentional10EFInvestigate $CF22$ 22:07Officer reviewed1ALARMF1760 South OAK SPRINGS Drive $01/17/2022$ 15:56:20Dispatched and cancelled en route13AFCancelled en route $CF22$ 2791Officer reviewed1ALARMF1776 South OAK SPRINGS <br< td=""><td></td><td></td><td></td><td>8DF</td><td></td><td></td><td>Initiated</td><td>1</td><td>ALARMF</td></br<>				8DF			Initiated	1	ALARMF
17:06:03 11072 1740 West GERTIE Avenue 01/20/2022 13:15:50 Alarm system activation, no fire - unintentional 11AF Investigate CF22- 2481 Officer reviewed 1 ALARMF 1745 East HERBERT Avenue 02/04/2022 Detector activation, no 14:36:36 10EF Investigate CF22- 818e Officer reviewed 1 ALARMF 1745 South MILESTONE 03/06/2022 False alarm or false call, other 14BF Investigate CF22- 8151 Officer reviewed 1 ALARMF 1747 South 900 West 02/11/2022 Dispatched and cancelled en route 10EF Cancelled en route CF22- 9122 Officer reviewed 1 ALARMF 1760 East 1300 South 01/21/2022 Dispatched and cancelled en route 10EF Cancelled en route CF22- 9123 Officer reviewed 1 ALARMF 1760 South STATE Street 01/21/2022 Sprinkler activation, no fire - unintentional 10EF Information, investigation & enforcement, other 2605 Officer reviewed 1 ALARMF 1760 South OAK SPRINGS 01/21/2022 Sprinkler activation, no fire - unintentional <td></td> <td></td> <td></td> <td>13BF</td> <td>Cancelled en route</td> <td></td> <td></td> <td>1</td> <td>ALARMF</td>				13BF	Cancelled en route			1	ALARMF
13:15:50no fire - unintentional2481reviewed1745 East HERBERT Avenue02/04/2022Detector activation, no fire - unintentional10EFInvestigateCF22- 4386Officer reviewed1ALARMF1745 South MILESTONE03/06/2022False alarm or false call, other14BFInvestigateCF22- 8151Officer reviewed1ALARMF1747 South 900 West02/11/2022 11:25:55Dispatched and cancelled en route6MFCancelled en routeCF22- 5265Officer reviewed1ALARMF1758 East MICHIGAN Avenue03/23/2022 12:26:29Dispatched and cancelled en route10EFCancelled en routeCF22- 10234Officer reviewed1ALARMF1760 East 1300 South01/17/2022 15:56:16CO detector activation due to malfunction10EFInvestigateCF22- 10234Officer reviewed1ALARMF1760 South OAK SPRINGS Drive01/21/2022 15:56:16Spinkler activation, no fire - unintentional10EFInformation, investigationCF22- 2052Officer reviewed1ALARMF1776 South OAK SPRINGS Drive01/21/2022 10:31:49Dispatched and cancelled en route13AFCancelled en routeCF22- 2076Officer reviewed1ALARMF1780 West NORTH TEMPLE Street03/01/2022 10:31:49Dispatched and cancelled en route11AFCancelled en routeCF22- 2791Officer reviewed1ALARMF1795 South FREMONT Drive 12:25:14	174 West 300 South			2DF			Initiated	1	ALARMF
14:36:36fire - unintentional4386reviewed1745 South MILESTONE03/06/2022 t5:20:48False alarm or false call, other14BFInvestigateCF22- StigateOfficer reviewed1ALARMF1747 South 900 West02/11/2022 t1:25:55Dispatched and cancelled en route6MFCancelled en routeCF22- StigateOfficer reviewed1ALARMF1758 East MICHIGAN Avenue t21:26:2903/23/2022 t2:6:29Dispatched and cancelled en route10EFCancelled en routeCF22- t0234Officer reviewed1ALARMF1760 East 1300 South t15:05:1601/17/2022 tue to matfunctionCO detector activation, of tue to matfunction10EFInvestigateCF22- t2123Officer reviewed1ALARMF1760 South STATE Street Drive01/21/2022 t0:31:49Dispatched and cancelled en route13AFCancelled en routeCF22- tentionOfficer reviewed1ALARMF1776 South OAK SPRINGS Drive01/23/2022 t10:31:49Dispatched and cancelled en route13AFCancelled en routeCF22- tentionOfficer reviewed1ALARMF1795 South FREMONT Drive 10:01:17:0003/01/2022 terted and t2:25:14Dispatched and cancelled en route14BFCancelled en routeCF22- tenteOfficer reviewed1ALARMF1795 South FREMONT Drive 10:01:17:0003/01/2022 cancelled en route14BFCancelled en routeCF22- treviewedOfficer reviewed1ALA	1740 West GERTIE Avenue	01/20/2022 13:15:50		11AF	Investigate			1	ALARMF
Drive15:20:48other8151reviewed1747 South 900 West02/11/2022 11:25:55Dispatched and cancelled en route6MFCancelled en routeCF22- S265Officer reviewed1ALARMW1758 East MICHIGAN Avenue 21:26:2903/23/2022 cancelled en routeDispatched and cancelled en route10EFCancelled en routeCF22- 10234Officer reviewed1ALARMF1760 East 1300 South01/17/2022 15:05:16CO detector activation due to malfunction10EFInvestigateCF22- 2123Officer reviewed1ALARMF1760 South STATE Street01/21/2022 15:56:20Sprinkler activation, no fire - unintentional8DFInformation, investigation & enforcement, otherCF22- 2005Officer reviewed1ALARMF1776 South OAK SPRINGS Drive01/21/2022 10:31:49Dispatched and cancelled en route13AFCancelled en routeCF22- 2016Officer reviewed1ALARMF1780 West NORTH TEMPLE 10:31:4903/01/12/222 cancelled en routeDispatched and cancelled en route14BFCancelled en routeCF22- 2016Officer reviewed1ALARMF1795 South FREMONT Drive 00:04:4303/01/2022 cancelled en route14BFCancelled en routeCF22- 2016Officer reviewed1ALARMF1798 South 500 East 1807 East 1700 South03/20/2022Carbon monoxide detector activation, no CO3AFInvestigateCF22- 2016Officer 11AL	1745 East HERBERT Avenue		,	10EF	Investigate			1	ALARMF
11:25:55cancelled en route5265reviewed1758 East MICHIGAN Avenue03/23/2022 21:28:29Dispatched and cancelled en route10EFCancelled en routeCF22- 10234Officer reviewed1ALARMF1760 East 1300 South01/17/2022 15:06:10CO detector activation due to malfunction10EFInvestigateCF22- 2123Officer reviewed1ALARMF1760 South STATE Street01/21/2022 15:56:10Sprinkler activation, no due to malfunction8DFInformation, investigation & enforcement, otherCF22- 2050Officer reviewed2ALARMF1776 South OAK SPRINGS Drive01/23/2022 10:31:49Dispatched and cancelled en route13AFCancelled en routeCF22- 2791Officer reviewed1ALARMF1780 West NORTH TEMPLE Street03/17/2022 16:17:00Dispatched and cancelled en route14BFCancelled en routeCF22- 2791Officer reviewed1ALARMF1795 South FREMONT Drive 12:25:1403/01/2022 carbon monoxide detector activation, no CO14BFCancelled en routeCF22- 2791Officer reviewed1ALARMF1798 South 500 East 10:01:4303/29/2022Carbon monoxide detector activation, no CO3AFInvestigateCF22- 2769Officer reviewed1ALARMF1807 East 1700 South03/29/2022Carbon monoxide detector activation, no CO13AFInvestigateCF22- 2769Officer reviewed1ALARMF			,	14BF	Investigate			1	ALARMF
21:26:29cancelled en route10234reviewed1760 East 1300 South01/17/2022 15:05:16CO detector activation due to malfunction10EFInvestigateCF22- 2123Officer reviewed1ALARMF1760 South STATE Street01/21/2022 15:05:16Sprinkler activation, no fire - unintentional8DFInformation, investigation & enforcement, otherCF22- 2605Officer reviewed2ALARMF1776 South OAK SPRINGS Drive01/23/2022 10:31:49Dispatched and cancelled en route13AFCancelled en routeCF22- 2791Officer reviewed1ALARMF1780 West NORTH TEMPLE Street03/17/2022 16:17:00Dispatched and cancelled en route11AFCancelled en routeCF22- 9476Officer reviewed1ALARMF1795 South FREMONT Drive 00:04:4301/14/2022 cancelled en route14BFCancelled en routeCF22- 9476Officer reviewed1ALARMF1798 South 500 East 00:04:4303/01/2022 carbon monoxide colo3AFInvestigateCF22- 0fficer reviewedOfficer reviewed1ALARMF1807 East 1700 South03/29/2022Carbon monoxide colo13AFInvestigateCF22- 0fficerOfficer reviewed1ALARMF1807 East 1700 South03/29/2022Carbon monoxide colo13AFInvestigateCF22- 0fficerOfficer reviewed1ALARMF1807 East 1700 South03/29/2022Carbon monoxide colo13AFInve	1747 South 900 West			6MF	Cancelled en route		• • • • • • •	1	ALARMW
15:05:16due to malfunction2123reviewed1760 South STATE Street01/21/2022 15:56:20Sprinkler activation, no fire - unintentional8DFInformation, investigation & enforcement, otherCF22- 2605Officer reviewed2ALARMW1776 South OAK SPRINGS Drive01/23/2022 10:31:49Dispatched and cancelled en route13AFCancelled en routeCF22- 2791Officer reviewed1ALARMF1780 West NORTH TEMPLE Street03/17/2022 16:17:00Dispatched and cancelled en route11AFCancelled en routeCF22- 9476Officer reviewed1ALARMF1795 South FREMONT Drive 12:25:1401/14/2022 2:25:14Dispatched and cancelled en route14BFCancelled en routeCF22- 9476Officer reviewed1ALARMF1798 South 500 East 0:04:4303/01/2022 0:04:43Carbon monoxide detector activation, no CO3AFInvestigateCF22- 97369Officer reviewed1ALARMF1807 East 1700 South03/29/2022Carbon monoxide tot13AFInvestigateCF22- 0ficerOfficer reviewed1ALARMF	1758 East MICHIGAN Avenue			10EF	Cancelled en route			1	ALARMF
15:56:20fire - unintentional& enforcement, other2605reviewed1776 South OAK SPRINGS Drive01/23/2022 10:31:49Dispatched and cancelled en route13AFCancelled en routeCF22- 2791Officer reviewed1ALARMF1780 West NORTH TEMPLE Street03/17/2022 16:17:00Dispatched and cancelled en route11AFCancelled en routeCF22- 9476Officer reviewed1ALARMF1795 South FREMONT Drive 12:25:1401/14/2022 cancelled en routeDispatched and cancelled en route14BFCancelled en routeCF22- 9476Officer reviewed1ALARMF1798 South 500 East 00:04:4303/01/2022 Carbon monoxide detector activation, no CO3AFInvestigateCF22- 7369Officer reviewed1ALARMF1807 East 1700 South03/29/2022Carbon monoxide tele to monoxide13AFInvestigateCF22- CF22- OfficerOfficer reviewed1ALARMF	1760 East 1300 South			10EF	Investigate			1	ALARMF
Drive10:31:49cancelled en route2791reviewed1780 West NORTH TEMPLE Street03/17/2022 16:17:00Dispatched and cancelled en route11AFCancelled en routeCF22- 9476Officer reviewed1ALARMF1795 South FREMONT Drive 12:25:1401/14/2022 cancelled en routeDispatched and cancelled en route14BFCancelled en routeCF22- 1721Officer reviewed1ALARMF1798 South 500 East 00:04:4303/01/2022 O0:04:43Carbon monoxide detector activation, no CO3AFInvestigateCF22- 7369Officer reviewed1ALARMF1807 East 1700 South03/29/2022Carbon monoxide telector activation, no CO13AFInvestigateCF22- CF22- CF22-Officer1ALARMF	1760 South STATE Street			8DF				2	ALARMW
Street16:17:00cancelled en route9476reviewed1795 South FREMONT Drive01/14/2022 12:25:14Dispatched and cancelled en route14BFCancelled en routeCF22- 1721Officer reviewed1ALARMF1798 South 500 East03/01/2022 00:04:43Carbon monoxide detector activation, no CO3AFInvestigateCF22- 7369Officer reviewed1ALARMF1807 East 1700 South03/29/2022Carbon monoxide tector activation, no13AFInvestigateCF22- CF22-Officer reviewed1ALARMF				13AF	Cancelled en route			1	ALARMF
12:25:14cancelled en route1721reviewed1798 South 500 East03/01/2022 00:04:43Carbon monoxide detector activation, no CO3AFInvestigateCF22- 7369Officer reviewed1ALARMF1807 East 1700 South03/29/2022Carbon monoxide13AFInvestigateCF22- CF22-Officer1ALARMF				11AF	Cancelled en route			1	ALARMF
00:04:43 detector activation, no 7369 reviewed 1807 East 1700 South 03/29/2022 Carbon monoxide 13AF Investigate CF22- Officer 1 ALARMF	1795 South FREMONT Drive			14BF	Cancelled en route			1	ALARMF
	1798 South 500 East		detector activation, no	3AF	Investigate			1	ALARMF
	1807 East 1700 South			13AF	Investigate			1	ALARMF

Address	Incident Date	Incident Type	Response Zone	Primary Action Taken	Incident Number	Incident Status	Number of Apparatus	Dispatch Code
1819 West CORNWALL Place	03/01/2022 10:28:17	Dispatched and cancelled en route	11AF	Cancelled en route	CF22- 7405	Officer reviewed		ALARMF
1821 West VILLAGE PARK Avenue	03/23/2022 18:28:58	Detector activation, no fire - unintentional	11AF	Investigate	CF22- 10220	Officer reviewed	1	ALARMF
1840 South LAKE Street	03/01/2022 12:48:17	Malicious, mischievous false call, other	3BF	Investigate	CF22- 7421	Officer reviewed	1	ALARMF
1845 West 1040 South	02/15/2022 16:24:49	Dispatched and cancelled en route	14DF	Cancelled en route	CF22- 5745	Officer reviewed	2	ALARMW
185 South STATE Street	02/14/2022 16:45:45	Dispatched and cancelled en route	1EF	Cancelled en route	CF22- 5658	Officer reviewed	1	ALARMF
1851 East SUNNYSIDE Avenue	01/26/2022 14:26:42	Alarm system activation, no fire - unintentional	10BF	Investigate	CF22- 3187	Officer reviewed	1	ALARMF
1858 South 200 East	01/29/2022 21:07:43	Smoke or odor removal	8DF	Investigate	CF22- 3607	Officer reviewed	1	ALARMF
1872 West ROUNDUP Circle	02/15/2022 20:24:24	CO detector activation due to malfunction	11AF	Investigate	CF22- 5775	Officer reviewed	1	ALARMF
1890 East ATKIN Avenue	03/08/2022 19:14:43	Dispatched and cancelled en route	13CF	Cancelled en route	CF22- 8417	Officer reviewed	1	ALARMF
1910 South 5500 West	02/08/2022 00:02:18	Alarm system sounded due to malfunction	14JF	Investigate	CF22- 4813	Officer reviewed	1	ALARMF
1910 South LAURELHURST Drive	03/14/2022 18:55:11	Dispatched and cancelled en route	13AF	Cancelled en route	CF22- 9130	Officer reviewed	1	ALARMF
1912 East YALECREST Avenue	04/01/2022 08:23:12		10DF		CF22- 11285	Initiated	1	ALARMF
1912 South DOUGLAS Street	03/14/2022 11:05:53	False alarm or false call, other	3BF	Investigate	CF22- 9078	Officer reviewed	1	ALARMF
1933 East BRYAN Avenue	03/09/2022 11:01:27	Citizen complaint	10CF	Investigate	CF22- 8481	Officer reviewed	1	ALARMF
1940 South 800 East	02/20/2022 14:14:14	System malfunction, other	3BF	Investigate	CF22- 6360	Officer reviewed	1	ALARMF
1955 South MILESTONE Drive	01/10/2022 11:20:23	Dispatched and cancelled en route	14BF	Cancelled en route	CF22- 1245	Officer reviewed	1	ALARMF
1974 South LAURELHURST Drive	03/06/2022 08:38:37	Alarm system activation, no fire - unintentional	13AF	Investigate	CF22- 8080	Officer reviewed	1	ALARMF
1992 South 200 East	03/29/2022 18:29:08		8DF		CF22- 10979	Initiated	1	ALARMF
1995 West 400 North	02/09/2022 06:52:03	Dispatched and cancelled en route	11AF	Cancelled en route	CF22- 4956	Officer reviewed	1	ALARMF
1999 West NORTH TEMPLE Street	01/13/2022 00:19:42	Carbon monoxide detector activation, no CO	11AF	Investigate	CF22- 1559	Officer reviewed	1	ALARMF
2 North MEDICAL Drive	03/10/2022 15:50:45	Dispatched and cancelled en route	4BF	Cancelled en route	CF22- 8626	Officer reviewed	1	ALARMF
200 North 2100 West	02/04/2022 21:03:06	Dispatched and cancelled en route	11AF	Cancelled en route	CF22- 4439	Officer reviewed	1	ALARMF
200 South 300 East	01/16/2022 20:53:22	Good intent call, other	1GF	Investigate	CF22- 2024	Officer reviewed	1	ALARMF
200 South WEST TEMPLE Street	03/19/2022 20:35:48	Smoke detector activation, no fire - unintentional	2DF	Investigate	CF22- 9757	Officer reviewed	1	ALARMF
2002 South 5070 West	01/14/2022 14:24:45	Dispatched and cancelled en route	14JF	Cancelled en route	CF22- 1741	Officer reviewed	2	ALARMW
2005 South 900 East	01/04/2022 10:58:10	Unintentional transmission of alarm, other	3BF	Restore fire alarm system	CF22- 476	Officer reviewed	1	ALARMF
2018 East PRINCETON Drive	03/11/2022 21:01:37	Carbon monoxide detector activation, no CO	10DF	Investigate	CF22- 8779	Officer reviewed	1	ALARMF
2029 East 2700 South	01/20/2022 20:23:58	Carbon monoxide detector activation, no CO	13BF	Investigate	CF22- 2531	Officer reviewed	1	ALARMF
205 West 1700 South	03/24/2022 20:04:36	Dispatched and cancelled en route	8DF	Cancelled en route	CF22- 10378	Officer reviewed	1	ALARMF
206 South WEST TEMPLE	03/19/2022	Dispatched and	2DF	Cancelled en route	CF22-	Officer	1	ALARMF

Street18:14:57cancelled en route9746reviewed2079 South 1200 East03/09/2022 18:54:25Smoke or odor removal 18:54:253BFInvestigateCF22- 8521Officer reviewed21 East 500 North03/25/2022 03:43:422EFCF22- 10411Initiated 1041121 North I Street02/02/2022 18:12:12False alarm or false call, other1BFInvestigateCF22- 4131Officer reviewed210 South 300 East01/16/2022 10:35:16Smoke detector activation, no fire - unintentional1GFInvestigateCF22- 1957Officer reviewed2102 East STOVER Street01/04/2022 09:28:29Dispatched and cancelled en route10AFCancelled en routeCF22- 461Officer reviewed211 West NORTH TEMPLE Street03/09/2022 14:20:53False alarm or false call, other2GFInvestigateCF22- 8500Officer reviewed2120 South 1300 East01/05/2022 03:59:39 cancelled en route3CFCancelled en routeCF22- 8500Officer reviewed2139 South HANNIBAL Street02/07/2022 02/27/2022False alarm or false call, cancelled en route13BFInvestigateCF22- 8521Officer reviewed2139 South HANNIBAL Street02/07/2022 02/27/2022False alarm or false call, cancelled en route13BFInvestigateCF22- 8500Officer reviewed	1	ALARMF ALARMF ALARMF ALARMF
18:54:258521reviewed21 East 500 North03/25/2022 03:43:422EFCF22- 10411Initiated 1041121 North I Street02/02/2022 18:12:12False alarm or false call, other1BFInvestigateCF22- 4131Officer reviewed210 South 300 East01/16/2022 10:35:16Smoke detector activation, no fire - 	1	ALARMF
03:43:421041121 North I Street02/02/2022 18:12:12False alarm or false call, other1BFInvestigateCF22- 4131Officer reviewed210 South 300 East01/16/2022 10:35:16Smoke detector activation, no fire - unintentional1GFInvestigateCF22- 1957Officer reviewed2102 East STOVER Street01/04/2022 09:28:29Dispatched and cancelled en route10AFCancelled en routeCF22- 461Officer reviewed211 West NORTH TEMPLE Street03/09/2022 14:20:53False alarm or false call, other2GFInvestigateCF22- 8500Officer reviewed2120 South 1300 East01/05/2022 03:59:39Dispatched and cancelled en route3CFCancelled en routeCF22- 852Officer reviewed2139 South HANNIBAL Street02/07/2022 02/07/2022False alarm or false call, cancelled en route13BFInvestigateCF22- CF22- Cficer cancelled en route	1	ALARMF
18:12:12other4131reviewed210 South 300 East01/16/2022 10:35:16Smoke detector activation, no fire - unintentional1GFInvestigateCF22- 1957Officer reviewed2102 East STOVER Street01/04/2022 09:28:29Dispatched and cancelled en route10AFCancelled en routeCF22- 461Officer reviewed211 West NORTH TEMPLE Street03/09/2022 14:20:53False alarm or false call, other2GFInvestigateCF22- 8500Officer reviewed2120 South 1300 East01/05/2022 03:59:39Dispatched and cancelled en route3CFCancelled en routeCF22- StreetOfficer reviewed2139 South HANNIBAL Street02/07/2022False alarm or false call, cancelled en route13BFInvestigateCF22- CF22-Officer reviewed		
10:35:16activation, no fire - unintentional1957reviewed2102 East STOVER Street01/04/2022 09:28:29Dispatched and cancelled en route10AFCancelled en routeCF22- 461Officer reviewed211 West NORTH TEMPLE Street03/09/2022 14:20:53False alarm or false call, other2GFInvestigateCF22- 8500Officer reviewed2120 South 1300 East01/05/2022 03:59:39Dispatched and cancelled en route3CFCancelled en routeCF22- 582Officer reviewed2139 South HANNIBAL Street02/07/2022 02/07/2022False alarm or false call, cancelled en route13BFInvestigateCF22- CF22-Officer reviewed	1	
09:28:29cancelled en route461reviewed211 West NORTH TEMPLE03/09/2022 14:20:53False alarm or false call, other2GFInvestigateCF22- 8500Officer reviewed2120 South 1300 East01/05/2022 03:59:39Dispatched and cancelled en route3CFCancelled en routeCF22- \$82Officer reviewed2139 South HANNIBAL Street02/07/2022False alarm or false call, raise alarm or false call, 13BF13BFInvestigateCF22- CF22-Officer reviewed		ALAKIVIF
Street14:20:53other8500reviewed2120 South 1300 East01/05/2022 03:59:39Dispatched and cancelled en route3CFCancelled en routeCF22- 582Officer reviewed2139 South HANNIBAL Street02/07/2022 02/07/2022False alarm or false call, reviewed13BFInvestigateCF22- CF22-Officer		ALARMF
03:59:39cancelled en route582reviewed2139 South HANNIBAL Street02/07/2022False alarm or false call, 13BFInvestigateCF22-Officer	1	ALARMF
		ALARMF
		ALARMF
2144 East 2700 South03/08/2022Dispatched and cancelled en route13CFCancelled en routeCF22- 8401Officer reviewed	1	ALARMF
2164 South 2300 East 03/04/2022 Smoke detector 13BF Information, investigation CF22- Officer 11:02:11 activation, no fire - unintentional unintentional Smoke detector 13BF Smoke detector Smoked	1	ALARMF
2170 West NORTH TEMPLE01/11/2022Unintentional11AFInvestigateCF22-OfficerStreet12:11:41transmission of alarm, otherother1388reviewed	1	ALARMF
2177 West NORTH TEMPLE01/25/2022Dispatched and cancelled en route11AFCancelled en routeCF22- 3073Officer reviewed	1	ALARMF
2206 East REDONDO 04/03/2022 13AF CF22- Initiated Avenue 22:07:47 11589 11589	1	ALARMF
223 East 3RD Avenue 03/04/2022 Good intent call, other 4AF Information, investigation CF22- Officer reviewed		ALARMF
2234 South 2100 East02/22/2022 14:00:55Dispatched and cancelled en route13BFCancelled en routeCF22- 6605Officer reviewed		ALARMF
225 East 5TH Avenue03/18/2022 21:26:40Dispatched and cancelled en route4AFCancelled en routeCF22- 9657Officer reviewed		ALARMF
2254 East PARLEYS Terrace 02/13/2022 False alarm or false call, 13BF Investigate CF22- Officer reviewed		ALARMF
230 East 300 Street South 02/20/2022 Smoke detector 1IF Investigate CF22- Officer activation, no fire - unintentional 6372 reviewed	1	ALARMF
230 North L Street03/20/2022False alarm or false call, other4CFInvestigateCF22- 9824Officer reviewed	1	ALARMF
2324 South 900 East03/28/2022 22:00:46Carbon monoxide incident3CFInvestigateCF22- 10903Officer reviewed	1	ALARMF
234 North M Street02/03/2022False alarm or false call,4CFInvestigateCF22-Officer11:16:24otherother4226reviewed	1	ALARMF
235 West 600 North 03/27/2022 False alarm or false call, 2AF Incident command CF22- Officer reviewed	1	ALARMF
240 South 1500 East02/16/2022 16:33:23False alarm or false call, 10AFInvestigateCF22- 5864Officer reviewed	1	ALARMF
244 West REED Avenue02/24/2022 13:09:57Dispatched and cancelled en route2FFCancelled en routeCF22- 6868Officer reviewed		ALARMF
2473 South 700 East01/07/2022Smoke detector activation due to malfunction3CFInvestigateCF22- 909Officer reviewed	1	ALARMF
250 East 300 South01/21/2022 08:39:04False alarm or false call, other1IFInvestigateCF22- 2559Officer reviewed		ALARMF
250 West 600 South 01/04/2022 Dispatched and 2DF Cancelled en route CF22- Officer 17:32:18 cancelled en route 527 reviewed	1	ALARMF
251 South 700 East03/29/2022Dispatched and cancelled en route1CFCancelled en routeCF22-Officer09:18:59cancelled en route10939reviewed	1	ALARMF
2545 South 1500 East 02/20/2022 Dispatched and 3DF Cancelled en route CF22- Officer 19:14:08 cancelled en route 6402 reviewed	1	ALARMF

								1
Address	Incident Date	Incident Type	Response Zone	Primary Action Taken	Incident Number	Incident Status	Number of Apparatus	Dispatch Code
2546 South DEARBORN Street	01/29/2022 05:08:20	Carbon monoxide detector activation, no CO	3DF	Investigate	CF22- 3528	Officer reviewed	1	ALARMF
255 North 400 West	01/06/2022 09:28:06	Water problem, other	2AF	Incident command	CF22- 724	Officer reviewed	2	ALARMW
2560 West CALIFORNIA Avenue	03/02/2022 08:02:13	Dispatched and cancelled en route	14EF	Cancelled en route	CF22- 7514	Officer reviewed	1	ALARMF
259 South 500 East	03/06/2022 11:47:20	Alarm system activation, no fire - unintentional	1CF	Investigate	CF22- 8123	Officer reviewed	1	ALARMF
26 North MEDICAL Drive	03/22/2022 19:59:04	False alarm or false call, other	4EF	Information, investigation & enforcement, other	CF22- 10107	Officer reviewed	1	ALARMF
260 South 500 East	02/26/2022 16:17:08	Water evacuation	1CF	Remove water	CF22- 7102	Officer reviewed	2	ALARMF
2601 East SUNNYSIDE Avenue	02/24/2022 04:36:39	Dispatched and cancelled en route	10BF	Cancelled en route	CF22- 6820	Officer reviewed	2	ALARMW
2682 East ST MARYS Way	01/11/2022 11:35:41	Dispatched and cancelled en route	10CF	Cancelled en route	CF22- 1384	Officer reviewed	1	ALARMF
270 South 1400 East	01/15/2022 13:11:47	False alarm or false call, other	4EF	Information, investigation & enforcement, other	CF22- 1849	Officer reviewed	1	ALARMF
2705 East PARLEYS Way	02/16/2022 05:27:20	Extinguishing system activation due to malfunction	13AF	Investigate	CF22- 5811	Officer reviewed	2	ALARMW
2767 East COMMONWEALTH Avenue	03/09/2022 11:08:09	Dispatched and cancelled en route	13AF	Cancelled en route	CF22- 8484	Officer reviewed	1	ALARMF
280 West 500 North	03/31/2022 09:46:51		2AF		CF22- 11152	Initiated	2	ALARMF
283 East SOUTH TEMPLE Street	01/06/2022 18:44:23	Alarm system activation, no fire - unintentional	1JF	Investigate	CF22- 832	Officer reviewed	1	ALARMF
2879 East SHERWOOD Drive	01/15/2022 13:25:30	Dispatched and cancelled en route	10CF	Cancelled en route	CF22- 1851	Officer reviewed	1	ALARMF
288 North 1460 West	03/18/2022 15:35:14	Dispatched and cancelled en route	7CF	Cancelled en route	CF22- 9609	Officer reviewed	1	ALARMF
29 South STATE Street	02/20/2022 06:02:53	False alarm or false call, other	1AF	Investigate	CF22- 6324	Officer reviewed	1	ALARMF
295 South 1500 East	03/25/2022 06:31:00	False alarm or false call, other	10AF	Investigate	CF22- 10416	Officer reviewed	1	ALARMF
299 South MAIN Street	02/28/2022 14:38:29	Dispatched and cancelled en route	1FF	Cancelled en route	CF22- 7317	Officer reviewed	2	ALARMF
3 PARKING STRUCTURE GL[LV1 FSZ-2 PRESSURE	01/27/2022 19:57:53	Water or steam leak	12BF	Investigate	CF22- 3364	Officer reviewed	2	ALARMF
309 East 100 South	02/13/2022 21:56:00	False alarm or false call, other	1GF	Investigate	CF22- 5569	Officer reviewed	1	ALARMF
3125 East KENNEDY Drive	03/09/2022 12:08:23	False alarm or false call, other	10DF	Investigate	CF22- 8488	Officer reviewed	1	ALARMF
315 East 200 South	02/14/2022 14:33:14	Dispatched and cancelled en route	1GF	Cancelled en route	CF22- 5642	Officer reviewed	2	ALARMW
315 West PIERPONT Avenue	03/26/2022 19:23:13	Unintentional transmission of alarm, other	2CF	Investigate	CF22- 10630	Officer reviewed	5	ALARMF
315 West REED Avenue	03/01/2022 17:29:14	Alarm system sounded due to malfunction	2FF	Investigate	CF22- 7455	Officer reviewed	1	ALARMF
32 East EXCHANGE Place	02/26/2022 23:31:06	Detector activation, no fire - unintentional	1HF	Investigate	CF22- 7138	Officer reviewed	1	ALARMF
320 South 200 West	02/10/2022 03:43:07	False alarm or false call, other	2CF	Investigate	CF22- 5073	Officer reviewed	1	ALARMF
320 South WAKARA Way	02/27/2022 10:31:18	Sprinkler activation, no fire - unintentional	10BF	Investigate	CF22- 7185	Officer reviewed	1	ALARMF
320 West 1300 South	01/25/2022 13:12:40	Dispatched and cancelled en route	8AF	Cancelled en route	CF22- 3054	Officer reviewed	1	ALARMF
328 West 200 South	03/28/2022 07:07:37	False alarm or false call, other	2GF	Incident command	CF22- 10796	Officer reviewed	1	ALARMF
3370 West 1820 South	01/06/2022 10:10:25	Dispatched and cancelled en route	14BF	Cancelled en route	CF22- 731	Officer reviewed	1	ALARMF
346 East 100 South	03/25/2022	Alarm system activation,	1GF	Investigate	CF22-	Officer	1	ALARMF

13.82.52 Cancelled an nutle 93.28 reverse 945 South 200 East 0.338.144 Cancelled an nutle Cancelled an nutle 64.02.00 1 ALARME 95 North WEST TEMPE 0.142.0222 Faber almann false call. 2GF Investigate 62.00 0.010 error 1 ALARME 950 North STATE Street 0.312.0222 Cancelled nortoute 2BF HazMatetecton, annyoin,	Address	Incident Date	Incident Type	Response Zone	Primary Action Taken	Incident Number	Incident Status	Number of Apparatus	Dispatch Code
13:82:52 Calibration of the second of the seco		22:36:39	no fire - unintentional			10510	reviewed		1
Instruction B496 reviewed Storb WEST TEMPLE 13.38.14 cancelled an route 2.0.7 Investigate 0.722. Officer 1 ALARME Storb WEST TEMPLE 0.122.02 Carbon monoxide 2.0.7 Investigate 0.713 reviewed 1 ALARME Storb WEST TEMPLE 0.312.2022 Dispatched an route 2.0.6 Cancelled en route 0.722. Officer 1 ALARME Storb WEST TEMPLE 0.312.2022 Dispatched an route 0.0.6 CF22. Officer 1 ALARME Storb WEST TEMPLE 0.0208.2022 False alarm or false call. 0.0.6 File Investigate 0.722. Officer 1 ALARME Storb WEST TEMPLE 0.0208.202 Service call office 6.6 File Investigate 0.722.0 Officer 1 ALARME Storb WEST TEMPLE 0.0208.202 Service call office 6.6 Investigate 0.726.0 Officer 1 ALARME Store Storb WEST TEMPLE 0.0208.20	349 East 1ST Avenue		•	1BF	Cancelled en route			1	ALARMF
Sitnet 16.46.28 other 1 2 3466 reviewed 350 North STATE Sitnet 032/2022 Carbon monoxide indident 28F HazMat detection, analysian 672.3 Officar reviewed 1 ALARME analysian 332 East KENSINGTON 03/12/2022 Dispatched and 03/08/2022 False alarm or false call. 9AF Investigate CF2.2 Officar reviewed 1 ALARME ALARME ALARME 355 South S700 West 02/09/2022 Service call. other SEF Investigate CF2.2 Officar reviewed 1 ALARME ALARME ALARME 356 South 200 East 02/09/2022 Service call. other SEF Investigate CF2.2 Officar reviewed 1 ALARME ALARME ALARME 360 South 400 West 02/09/2022 Carbon monoxid indicent activation, no activation, no fire - unitaritaritaritaritaritaritaritaritaritar	349 South 200 East		•	1IF	Cancelled en route			1	ALARMF
12:17.33 incident monitoring, asmpling, & 10713 reviewed 333: Eats KENSINGTON 03/12/2022 Dispatched and concute SF Cancelled on route CF22- Officer 1 ALARMF Wave for eviewed 355: South 5700 West 03/09/2022 False alarm or false call. SF Investigate CF22- Officer 1 ALARMF Wave for eviewed 356: South 1200 East 02/09/2022 Service call, other SEF Investigate CF22- Officer 1 ALARMF Wave for eviewed 358: South 700 East 02/07/2022 False alarm or false call. 1CF Information, investigate CF22- Officer 1 ALARMF wave for eviewed 360: South 400 West 01/30/2022 Carbon monode monde CFF HazMat detection, monitor invitational Indext detection, manitoring, sampling, & 10299 Officer 1 ALARMF wave for eviewed 365 East 1300 South 02/16/2022 Carbon monode monde IAF Cancelled en route CF22- Officer 1 ALARMF wave for eviewed 376 East 8TH Avenue 02/16/2022	35 North WEST TEMPLE Street			2GF	Investigate			1	ALARMF
Venue 14.41.22 andrelied en route 8864 reviewed 355 South 5700 West 03/07022 False alarm or false call 04 Investigate CF22. Officer 1 ALARMF 356 South 5700 West 02/17/202 False alarm or false call 1CF Investigate CF22. Officer 1 ALARMF 356 South 5700 West 02/17/202 False alarm or false call 1CF Investigate CF22. Officer 1 ALARMF 350 South 700 East 01/30/2022 Smoke detector 2CF Investigate CF22. Officer 1 ALARMF 364 West 600 North 02/10/2022 Carbon monoxide 2FF HazMat detaction, monitariter investigate CF22. Officer 1 ALARMF 365 East 1300 South 02/10/202 Carbon monoxide investigate CF22. Officer 1 ALARMF 376 East STH Avenue 02/10/202 Dispatched and the route 14F Cancelled en route CF22. Officer 1 ALARMF 376 West 300 South 0	350 North STATE Street			2BF	monitoring, sampling, &			1	ALARMF
14/12/53 other B4B reviewed 356 South 1200 East 02/09/202 Service call, other SEF Investigate CF22 Officer 1 ALARMF 358 South 700 East 02/17/202 False alarm or false call, and the service of the servi	353 East KENSINGTON Avenue		•	8JF	Cancelled en route			1	ALARMF
13:16:40 500 reviewed 358 South 700 East 02:172022 False alam or false call, 06:26:51 1CF Information, investigate 6722. Officer reviewed 1 A LARMF 360 South 400 West 01:30:2022 Smole delector incident 2CF Investigate CF22. Officer reviewed 1 A LARMF 364 West 600 North 03:74/2022 Carbon monoxide incident 2FF HazMat detection, montoring, sampling, & 1299 CF22. Officer reviewed 1 A LARMF 365 East 1300 South 02:05/2022 Carbon monoxide cancelled en route 8GF Investigate CF22. Officer reviewed 1 A LARMF 365 East 1300 South 02:05/2022 Carbon monoxide cancelled en route 8GF Investigate CF22. Officer reviewed 1 A LARMF 376 Feast 8TH Avenue 03:18/2022 Dispatched and cancelled en route CF22. Officer reviewed 1 A LARMF 378 West 300 South 02:25:55 Carbon monoxide cancelled en route CF22. Officer reviewed 1 A LARMF 380	355 South 5700 West			9AF	Investigate			1	ALARMF
08-26:51 other & enforcement, other 5353 reviewed 360 South 400 West 01/30/202 Snoke delector antivation, no fire - unintenional 2CF Investigate CF22- 3099 Officer reviewed 1 ALARMF 364 West 600 North 02/24/2022 Carbon monoxide incident 2FF HazMid detection, analysis CF22- 3099 Officer reviewed 1 ALARMF 365 East 1300 South 02/05/202 Carbon monoxide incident noute 8GF Investigate CF22- 4548 Officer reviewed 1 ALARMF 365 East 13100 South 02/03/2022 Dispatched and cancelled en route GF22- 313017 Officer reviewed 1 ALARMF 376 East 8TH Avenue 03/18/2022 Dispatched and cancelled en route GF22- 313007 Officer reviewed 1 ALARMF 378 Best 8TH Avenue 03/18/2022 Carbon monoxide cancelled en route CF22- 30007 Officer reviewed 1 ALARMF 380 South 400 East 03/18/2022 Carbon monoxide carbon monoxide 11F Investigate CF22- 300 Officer reviewed 1 ALARMF	356 South 1200 East		Service call, other	5EF	Investigate			1	ALARMF
18:21:19activation, no fire - unintentional3699reviewed364 West 600 North03/24/2022 11:40:19Carbon monoxide incident2FFHazMat detection monotoring, sampling, a analysisCF22- reviewedOfficer reviewed1ALARMF365 East 1300 South02/05/2022 19:35:07Carbon monoxide detector activation, no cancelled en route6F2Officer reviewed1ALARMF365 East 1300 South03/18/2022 19:35:07Dispatched and cancelled en route149FCancelled en routeCF22- Cofficer reviewed1ALARMF376 East 8TH Avenue03/18/2022 19:31:1202Dispatched and cancelled en route149FCancelled en routeCF22- Cofficer reviewed1ALARMF378 West 300 South03/18/2022 19:21:2022 19:30:071ALARMFCancelled en routeCF22- CofficerOfficer reviewed1ALARMF380 South 400 East02/18/2022 19:22:6:5Carbon monoxide11FInvestigateCF22- CofficerOfficer reviewed1ALARMF383 South UNIVERSITY02/17/2022 19:22:6:5Carbon monoxide14FAction taken, otherCF22- CofficerOfficer reviewed1ALARMF383 South UNIVERSITY02/17/2022 19:22:6:5False alarm or false call, inder4FFAction taken, otherCF22- CofficerOfficer reviewed1ALARMF400 West 300 South03/28/2022 19:06:4602/28/2022 inderFalse alarm or false call, inder4F	358 South 700 East		,	1CF	, U			1	ALARMF
11-40:19incidentmonitoring, sampling, & analysis10299reviewed365 East 1300 South02/05/2022 (19:3507 C)Carbon monoxide detector activation, no CO8GFInvestigateCF22- 9623Officer reviewed1ALARMF reviewed365 West NINIGRET Drive03/18/2022 (19:314-10)Dispatched and (17:46:54)14BFCancelled en routeCF22- (10:002)Officer reviewed1ALARMF reviewed376 East 8TH Avenue03/31/2022 (19:314-10)Dispatched and (20:2022)4AFCancelled en routeCF22- (10:002)Officer reviewed1ALARMF reviewed378 West 300 South03/21/2022 (20:2022)False alarm or false call, (20:2022)2CFInvestigateCF22- (9565Officer (10:002)1ALARMF reviewed380 South 400 E [BLOCK 4402:02/2022 (20:2022)Carbon monoxide (20:2022)1FInvestigateCF22- (9565Officer (12:000)1ALARMF reviewed380 South 400 East03/18/2022 (20:2022)Good intent call, other1IFInvestigateCF22- (9545)Officer (12:000)1ALARMF reviewed383 South UNIVERSITY02/17/2022 (20:222)False alarm or false call, (11:34:01)4AFInformation, investigation (20:26:55)CF22- (0fficerOfficer (12:022)1ALARMF reviewed40 South 800 East02/02/2022 (20:222)Smoke detector (20:222)1ALARMF (20:220)Incident2AFInvestigateCF22- <td>360 South 400 West</td> <td></td> <td>activation, no fire -</td> <td>2CF</td> <td>Investigate</td> <td></td> <td></td> <td>1</td> <td>ALARMF</td>	360 South 400 West		activation, no fire -	2CF	Investigate			1	ALARMF
19:33:07detector activation, no4548reviewed3655 West NINIGRET Drive03/18/2022 (15:31:42)Dispatched and cancelled en route14BFCancelled en routeCF22- 9623Officer 	364 West 600 North			2FF	monitoring, sampling, &			1	ALARMF
16:31:41cancelled en route9623reviewed376 East 8TH Avenue03/31/2022Dispatched and cancelled en route4AFCancelled en routeCF22- 11215Officer reviewed1ALARMF378 West 300 South03/21/2022False alarm or false call, uniter2CFInvestigateCF22- 1448Officer reviewed1ALARMF380 South 400 E [BLOCK 4402/02/2022Carbon monoxide incident1IFInvestigateCF22- 9545Officer reviewed1ALARMF380 South 400 E ast03/18/2022 02/17/202Good intent call, other other1IFInvestigateCF22- 9545Officer reviewed1ALARMF383 South UNIVERSITY02/17/2022False alarm or false call, other4EFAction taken, otherCF22- 9593Officer reviewed1ALARMF400 South 800 East02/02/2022 016/cSmoke detector activation, no fire autivation, no fire unintentional1KFInvestigateCF22- 016/cOfficer reviewed1ALARMF410 North 800 West03/28/2022 01/16/2022Jispatched and cancelled an route2CFInvestigateCF22- 016/cerOfficer reviewed1ALARMF413 North 800 West01/18/2022 01/16/2022Dispatched and cancelled an route2CFInvestigateCF22- 016/cerOfficer reviewed1ALARMF414 North 800 West01/18/2022 01/16/2022Dispatched and cancelled an route2CFInvestigateCF22- 	365 East 1300 South		detector activation, no	8GF	Investigate			1	ALARMF
17.46:54cancelled en route11215reviewed378 West 300 South03/21/2022False alarm or false call, other2CFInvestigateCF22. (1000000000000000000000000000000000000	3655 West NINIGRET Drive			14BF	Cancelled en route			1	ALARMF
21:30:07other10002reviewed380 South 400 E [BLOCK 4402/02/022Carbon monoxide1/FInvestigateCF22-Officer1ALARMF380 South 400 E ast03/18/2022Good intent call, other1/FInvestigateCF22-Officer6ALARMF380 South 400 E ast02/17/2022False alarm or false call, other4EFAction taken, otherCF22- 9545Officer1ALARMF383 South UNIVERSITY02/17/2022False alarm or false call, other4EFAction taken, otherCF22- 9548Officer1ALARMF385 East 5TH Avenue01/28/2022False alarm or false call, other4AFInformation, investigationCF22- 9548Officer1ALARMF400 South 800 East02/02/2022Smoke detector activation, no fire - unintentional1KFInvestigateCF22- 10626Officer1ALARMF400 West 300 South03/26/2022Alarm system sounded due to malfunction2CFInvestigateCF22- 10626Officer1ALARMF410 North 800 West01/08/2022False alarm or false call, cancelled en route7BFRestore fire alarm systemCF22- 10626Officer1ALARMF413 North WEST CAPITOL01/31/2023 Cascelled en routeCF22- cascelled en routeCF22- reviewedOfficer1ALARMF413 North WEST CAPITOL01/31/2022 Cascelled en routeCF2- cascelled en routeCF22- reviewedOfficer <td< td=""><td>376 East 8TH Avenue</td><td></td><td>•</td><td>4AF</td><td>Cancelled en route</td><td></td><td></td><td>1</td><td>ALARMF</td></td<>	376 East 8TH Avenue		•	4AF	Cancelled en route			1	ALARMF
380 South 400 E [BLOCK 44 02/02/2022 Carbon monoxide incident 1IF Investigate CF22- 4148 Officer reviewed 1 ALARMF APARTMENTS] 03/18/2022 Good intent call, other 1IF Investigate CF22- 9545 Officer reviewed 6 ALARMF 380 South 400 E ast 02/26:55 03/18/2022 False alarm or false call, other 4EF Action taken, other CF22- 9545 Officer reviewed 1 ALARMF 380 South UNIVERSITY 02/17/2022 False alarm or false call, other 4AF Information, investigation & enforcement, other CF22- 9433 Officer reviewed 1 ALARMF 400 South 800 East 02/02/2022 02/2022 Smoke detector activation, no fire - unintentional 1KF Investigate CF22- 0fficer Officer reviewed 1 ALARMF 400 West 300 South 03/26/2022 Dapatched and cancelled en route 2CF Investigate CF22- 0fficer Officer reviewed 1 ALARMF 410 North 800 West 01/08/2022 Eas alarm or false call, 01/81/2022 7BF Restore fire alarm system CF22- 0fficer Officer reviewed 1 ALARMF 413 North WEST CAPITOL	378 West 300 South			2CF	Investigate			1	ALARMF
02:26:559545reviewed383 South UNIVERSITY02/17/2022False alarm or false call, other4EFAction taken, otherCF22- S938Officer reviewed1ALARMF385 East 5TH Avenue01/28/2022False alarm or false call, other4AFInformation, investigation & enforcement, otherCF22- 3433Officer reviewed1ALARMF40 South 800 East01/28/2022Smoke detector activation, no fire - unintentional1KFInvestigateCF22- CF22-Officer reviewed1ALARMF400 West 300 South03/26/2022Dispatched and cancelled en route2CFInvestigateCF22- CF22-Officer reviewed1ALARMF410 North 800 West01/16/2022Dispatched and cancelled en route4AFCancelled en routeCF22- CF22-Officer reviewed1ALARMF411 North 800 West01/16/2022False alarm or false call, other7BFRestore fire alarm systemCF22- CF22-Officer reviewed1ALARMF413 North WEST CAPITOL01/31/2022Smoke detector activation, no fire - unintentional2AFRestore fire alarm systemCF22- CF22-Officer reviewed1ALARMF423 West 300 South02/17/1/2022Dispatched and cancelled en route2CFCancelled en routeCF22- CF22-Officer reviewed1ALARMF423 West 300 South02/17/1/2022Dispatched and cancelled en route2CFCancelled en routeCF22- 	380 South 400 E [BLOCK 44 APARTMENTS]			1IF	Investigate		Officer	1	ALARMF
Street08:52:16other5938reviewed385 East 5TH Avenue01/28/2022 (1:34:01)False alarm or false call, other4AFInformation, investigation & enforcement, otherCF22- 	380 South 400 East		Good intent call, other	1IF	Investigate			6	ALARMF
11:34:01other& enforcement, other3433reviewed40 South 800 East02/02/2022Smoke detector activation, no fire - unintentional1KFInvestigateCF22- 4111Officer reviewed1ALARMF400 West 300 South03/26/2022 19:06:46Alarm system sounded due to malfunction2CFInvestigateCF22- 10626Officer reviewed1ALARMF402 East 6TH Avenue01/16/2022 20:56:40Dispatched and cancelled en routeAFCancelled en route 20:56:40CF22- reviewedOfficer reviewed1ALARMF410 North 800 West01/08/2022 11:34:09False alarm or false call, other7BFRestore fire alarm systemCF22- 1006Officer reviewed1ALARMF413 North WEST CAPITOL Street01/31/2022 18:15:23Smoke detector activation, no fire - unintentional2AFRestore fire alarm systemCF22- 1006Officer reviewed1ALARMF423 West 300 South02/17/2022 09:17:28Carbon monoxide incident4AFInvestigateCF22- 1421Officer reviewed1ALARMF426 South 500 East01/21/2022 10:43:54Smoke detector activation, no fire - unintentional1IFInvestigateCF22- CfficerOfficer reviewed1ALARMF428 West 1385 South01/22/2022 11:37:56Dispatched and cancelled en route14FCancelled en routeCF22- CfficerOfficer reviewed1ALARMF428 South 80	383 South UNIVERSITY Street			4EF	Action taken, other			1	ALARMF
14:51:58activation, no fire - unintentional4111reviewed400 West 300 South03/26/2022Alarm system sounded ue to malfunction2CFInvestigateCF22- 10626Officer 	385 East 5TH Avenue			4AF				1	ALARMF
19:06:46due to malfunction10626reviewed402 East 6TH Avenue01/16/2022 20:56:40Dispatched and cancelled en route4AFCancelled en routeCF22- 2026Officer reviewed1ALARMF410 North 800 West01/08/2022 11:34:09False alarm or false call, other7BFRestore fire alarm systemCF22- 1006Officer reviewed1ALARMF413 North WEST CAPITOL Street01/31/2022 18:15:23Smoke detector activation, no fire - unintentional2AFRestore fire alarm systemCF22- 3877Officer reviewed1ALARMF418 North B Street01/11/2022 17:35:25Carbon monoxide incident4AFInvestigateCF22- 1421Officer reviewed1ALARMF423 West 300 South02/17/2022 09:17:28Dispatched and cancelled en route2CFCancelled en routeCF22- S942Officer reviewed0ALARMF426 South 500 East01/21/2022 10:43:54Dispatched and cancelled en route1FInvestigateCF22- S272Officer reviewed1ALARMF4285 West 1385 South01/26/2022 11:37:56Dispatched and cancelled en route14FCancelled en routeCF22- S272Officer reviewed2ALARMF429 South 800 East01/12/2022 11:37:56Dispatched and cancelled en route14FCancelled en routeCF22- S272Officer reviewed2ALARMF429 South 800 East01/12/2022 19Dispatched and <br< td=""><td>40 South 800 East</td><td></td><td>activation, no fire -</td><td>1KF</td><td>Investigate</td><td></td><td></td><td>1</td><td>ALARMF</td></br<>	40 South 800 East		activation, no fire -	1KF	Investigate			1	ALARMF
20:56:40cancelled en route2026reviewed410 North 800 West01/08/2022 11:34:09False alarm or false call, other7BFRestore fire alarm systemCF22- 1006Officer reviewed1ALARMF413 North WEST CAPITOL Street01/31/2022 18:15:23Smoke detector activation, no fire - unintentional2AFRestore fire alarm systemCF22- 3877Officer reviewed1ALARMF418 North B Street01/11/2022 17:35:25Carbon monoxide incident4AFInvestigateCF22- 1421Officer reviewed1ALARMF423 West 300 South02/17/2022 09:17:28Dispatched and cancelled en route2CFCancelled en routeCF22- 5942Officer reviewed0ALARMF426 South 500 East01/21/2022 10:43:54Smoke detector activation, no fire - unintentional1HFInvestigateCF22- 10:43:54Officer reviewed1ALARMF4285 West 1385 South01/26/2022 11:37:56Dispatched and cancelled en route14FFCancelled en routeCF22- 3169Officer reviewed2ALARMF429 South 800 East01/12/2022 11:37:56Dispatched and cancelled en route14FFCancelled en routeCF22- 3169Officer reviewed2ALARMF429 South 800 East01/12/2022 11:37:56Dispatched and cancelled en route14FFCancelled en routeCF22- 3169Officer reviewed2ALARMF	400 West 300 South		5	2CF	Investigate			1	ALARMF
11:34:09othersystem1006reviewed413 North WEST CAPITOL Street01/31/2022 18:15:23Smoke detector activation, no fire - unintentional2AFRestore fire alarm systemCF22- 3877Officer reviewed1ALARMF418 North B Street01/11/2022 17:35:25Carbon monoxide incident4AFInvestigateCF22- 1421Officer reviewed1ALARMF423 West 300 South02/17/2022 09:17:28Dispatched and cancelled en route2CFCancelled en routeCF22- 5942Officer reviewed0ALARMF426 South 500 East01/21/2022 10:43:54Smoke detector activation, no fire - unintentional1IFInvestigateCF22- 2572Officer reviewed1ALARMF4285 West 1385 South01/26/2022 11:37:56Dispatched and cancelled en route14FFCancelled en routeCF22- 2572Officer reviewed2ALARMF429 South 800 East01/12/2022Dispatched and cancelled en route1CFCancelled en routeCF22- 3169Officer 242ALARMF	402 East 6TH Avenue			4AF	Cancelled en route			1	ALARMF
413 North WEST CAPITOL Street01/31/2022 18:15:23Smoke detector activation, no fire - unintentional2AFRestore fire alarm systemCF22- 3877Officer reviewed1ALARMF418 North B Street01/11/2022 17:35:25Carbon monoxide incident4AFInvestigateCF22- 1421Officer reviewed1ALARMF423 West 300 South02/17/2022 09:17:28Dispatched and cancelled en route2CFCancelled en routeCF22- 19:42Officer reviewed0ALARMF426 South 500 East01/21/2022 10:43:54Smoke detector activation, no fire - unintentional1IFInvestigateCF22- 2572Officer reviewed1ALARMF4285 West 1385 South01/26/2022 11:37:56Dispatched and cancelled en route14FFCancelled en routeCF22- 2572Officer reviewed2ALARMF429 South 800 East01/12/2022Dispatched and cancelled en route1CFCancelled en routeCF22- 2572Officer reviewed2ALARMF429 South 800 East01/12/2022Dispatched and cancelled en route1CFCancelled en routeCF22- 2572Officer 25722ALARMF	410 North 800 West		,	7BF				1	ALARMF
17:35:25incident1421reviewed423 West 300 South02/17/2022 09:17:28Dispatched and cancelled en route2CFCancelled en routeCF22- 5942Officer reviewed0ALARMF426 South 500 East01/21/2022 10:43:54Smoke detector activation, no fire - unintentional1IFInvestigateCF22- 2572Officer reviewed1ALARMF4285 West 1385 South01/26/2022 11:37:56Dispatched and cancelled en route14FFCancelled en routeCF22- 2572Officer reviewed2ALARMF429 South 800 East01/12/2022Dispatched and cancelled en route1CFCancelled en routeCF22- 3169Officer reviewed2ALARMF	413 North WEST CAPITOL Street		activation, no fire -	2AF	Restore fire alarm			1	ALARMF
423 West 300 South02/17/2022 09:17:28Dispatched and cancelled en route2CFCancelled en routeCF22- 5942Officer 	418 North B Street			4AF	Investigate			1	ALARMF
426 South 500 East01/21/2022 10:43:54Smoke detector activation, no fire - unintentional1IFInvestigateCF22- 2572Officer reviewed1 ALARMF4285 West 1385 South01/26/2022 11:37:56Dispatched and cancelled en route14FFCancelled en routeCF22- 3169Officer reviewed2 ALARMF429 South 800 East01/12/2022Dispatched and cancelled en route1CFCancelled en routeCF22- 3169Officer reviewed1 ALARMF	423 West 300 South	02/17/2022	Dispatched and	2CF	Cancelled en route	CF22-		0	ALARMF
11:37:56 cancelled en route 3169 reviewed 429 South 800 East 01/12/2022 Dispatched and 1CF Cancelled en route CF22- Officer 1 ALARMF	426 South 500 East	01/21/2022	Smoke detector activation, no fire -	1IF	Investigate	CF22-	Officer	1	ALARMF
	4285 West 1385 South			14FF	Cancelled en route			2	ALARMW
	429 South 800 East		•	1CF	Cancelled en route			1	ALARMF

Address	Incident Date	Incident Type	Response Zone	Primary Action Taken	Incident Number	Incident Status	Number of Apparatus	Dispatch Code
44 West 300 South	01/17/2022 18:56:06	Central station, malicious false alarm	2DF	Investigate	CF22- 2143	Officer reviewed		ALARMF
442 South HOLD Avenue	03/03/2022 09:22:21	Dispatched and cancelled en route	1IF	Cancelled en route	CF22- 7655	Officer reviewed	1	ALARMF
447 South BLAIR Street	03/30/2022 10:56:51	Alarm system activation, no fire - unintentional	1IF	Investigate	CF22- 11040	Officer reviewed	1	ALARMF
449 East BLAINE Avenue	03/03/2022 02:34:00	CO detector activation due to malfunction	3AF	Investigate	CF22- 7639	Officer reviewed	1	ALARMF
45 North WEST TEMPLE Street	01/10/2022 11:00:48	Dispatched and cancelled en route	2GF	Cancelled en route	CF22- 1239	Officer reviewed	1	ALARMF
45 South 700 East	03/06/2022 10:26:58	Dispatched and cancelled en route	1KF	Cancelled en route	CF22- 8107	Officer reviewed	1	ALARMF
455 South 500 East	01/05/2022 12:27:09	Alarm system activation, no fire - unintentional	1IF	Investigate	CF22- 630	Officer reviewed	2	ALARMW
457 East EMERSON Avenue	01/23/2022 18:26:54	Alarm system activation, no fire - unintentional	8JF	Investigate	CF22- 2832	Officer reviewed	1	ALARMF
460 South 1000 West	02/26/2022 19:27:55	Unintentional transmission of alarm, other	6CF	Investigate	CF22- 7116	Officer reviewed	0	ALARMF
460 West 50 North	01/12/2022 18:08:09	False alarm or false call, other	2AF	Incident command	CF22- 1536	Officer reviewed	1	ALARMF
463 South 400 West	01/18/2022 14:52:24	Service call, other	2CF	Investigate	CF22- 2269	Officer reviewed	1	ALARMF
465 South 400 East	03/20/2022 12:19:32	False alarm or false call, other	1IF	Investigate	CF22- 9817	Officer reviewed	1	ALARMF
470 South 1300 East	03/06/2022 21:11:00	Cooking fire, confined to container	5EF	Investigate	CF22- 8185	Officer reviewed	1	ALARMF
474 North GRANT Street	02/24/2022 19:46:18	Dispatched and cancelled en route	7BF	Cancelled en route	CF22- 6902	Officer reviewed	1	ALARMF
4750 West WILEY POST Way	02/07/2022 08:13:13	Dispatched and cancelled en route	9AF	Cancelled en route	CF22- 4713	Officer reviewed	1	ALARMF
4752 West CALIFORNIA Avenue	03/17/2022 14:13:47	Dispatched and cancelled en route	14FF	Cancelled en route	CF22- 9456	Officer reviewed	2	ALARMF
48 West 300 South	04/03/2022 10:15:28	Alarm system activation, no fire - unintentional	2DF	Investigate	CF22- 11515	Officer reviewed	1	ALARMF
480 East SOUTH TEMPLE Street	03/31/2022 17:47:06	False alarm or false call, other	1GF	Investigate	CF22- 11214	Officer reviewed	1	ALARMF
489 East 400 South	02/21/2022 15:02:34	Dispatched and cancelled en route	1IF	Cancelled en route	CF22- 6482	Officer reviewed	1	ALARMF
497 North MORTON Drive	02/24/2022 09:57:01	Dispatched and cancelled en route	11AF	Cancelled en route	CF22- 6847	Officer reviewed	1	ALARMF
4975 West WILEY POST Way	03/18/2022 07:16:26	False alarm or false call, other	9AF	Investigate	CF22- 9554	Officer reviewed	1	ALARMW
50 East NORTH TEMPLE Street	02/01/2022 04:42:34	Detector activation, no fire - unintentional	2BF	Systems and services, other	CF22- 3922	Officer reviewed	2	ALARMW
50 West NORTH TEMPLE Street	02/02/2022 08:55:49	Smoke detector activation, no fire - unintentional	2GF	Investigate	CF22- 4061	Officer reviewed	1	ALARMF
500 South CHIPETA Way	02/11/2022 16:32:30	Heat detector activation due to malfunction	10BF	Investigate	CF22- 5305	Officer reviewed	1	ALARMF
515 South 1000 East	01/18/2022 10:04:41	Alarm system activation, no fire - unintentional	5FF	Investigate	CF22- 2228	Officer reviewed	2	ALARMW
5225 West WILEY POST Way	03/24/2022 08:49:50	Smoke detector activation, no fire - unintentional	9AF	Investigate	CF22- 10282	Officer reviewed	1	ALARMF
525 East 100 South	01/04/2022 22:38:52	Alarm system activation, no fire - unintentional	1KF	Investigate	CF22- 566	Officer reviewed	1	ALARMF
5270 West JOHN CANNON Drive	01/18/2022 08:32:33	Dispatched and cancelled en route	9AF	Cancelled en route	CF22- 2218	Officer reviewed	1	ALARMW
532 East 400 South	02/02/2022 18:30:33	Alarm system activation, no fire - unintentional	1IF	Investigate	CF22- 4133	Officer reviewed	1	ALARMF
534 West 800 South	02/04/2022 12:48:58	Dispatched and cancelled en route	6HF	Cancelled en route	CF22- 4368	Officer reviewed	0	ALARMF
536 North 1000 West	03/17/2022	Dispatched and	7BF	Cancelled en route	CF22-	Officer	1	ALARMF

Address	Incident Date	Incident Type	Response Zone	Primary Action Taken	Incident Number	Incident Status	Number of Apparatus	Dispatch Code
	11:21:17	cancelled en route		1	9435	reviewed		1
538 North COLUMBUS Street	02/19/2022 15:28:51	False alarm or false call, other	2EF	Restore fire alarm system	CF22- 6232	Officer reviewed	1	ALARMF
54 South 700 East	02/11/2022 15:37:03	Dispatched and cancelled en route	1KF	Cancelled en route	CF22- 5296	Officer reviewed	1	ALARMF
540 East 200 South	02/02/2022 07:25:35	False alarm or false call, other	1CF	Investigate	CF22- 4059	Officer reviewed	1	ALARMF
5405 West 300 South	02/05/2022 10:50:31	Dispatched and cancelled en route	9AF	Cancelled en route	CF22- 4494	Officer reviewed	2	ALARMW
5420 West 2100 South	02/03/2022 11:50:26	Dispatched and cancelled en route	14JF	Cancelled en route	CF22- 4233	Officer reviewed	2	ALARMF
545 East 700 South	03/12/2022 06:36:33	Good intent call, other	1IF	Investigate	CF22- 8825	Officer reviewed	1	ALARMF
545 South 700 East	03/01/2022 19:33:20	False alarm or false call, other	5AF	Information, investigation & enforcement, other	CF22- 7478	Officer reviewed	1	ALARMF
555 South FOOTHILL Drive	01/06/2022 11:09:27	Heat from short circuit (wiring), defective/worn	10BF	Investigate	CF22- 738	Officer reviewed	1	ALARMF
556 West 700 South	01/26/2022 14:38:01	False alarm or false call, other	6IF	Information, investigation & enforcement, other	CF22- 3190	Officer reviewed	0	ALARMF
558 North REDWOOD Road	03/10/2022 23:14:56	Detector activation, no fire - unintentional	11AF	Investigate	CF22- 8659	Officer reviewed	1	ALARMF
560 East 200 South	02/05/2022 23:20:25	Alarm system activation, no fire - unintentional	1CF	Investigate	CF22- 4574	Officer reviewed	2	ALARMF
565 North MORTON Drive	03/31/2022 17:49:26	Alarm system activation, no fire - unintentional	11AF	Investigate	CF22- 11216	Officer reviewed	1	ALARMF
577 South 900 West	01/14/2022 08:15:24	Dispatched and cancelled en route	6FF	Cancelled en route	CF22- 1697	Officer reviewed	0	ALARMF
579 South CHIPETA Way	03/11/2022 18:33:19	System malfunction, other	10BF	Investigate	CF22- 8763	Officer reviewed	1	ALARMF
580 North WRIGHT BROTHERS Drive	02/16/2022 07:30:54	Alarm system sounded due to malfunction	9AF	Investigate	CF22- 5816	Officer reviewed	1	ALARMF
580 South GUARDSMAN Way	03/27/2022 23:01:31	Steam, other gas mistaken for smoke, other	5BF	Investigate	CF22- 10769	Officer reviewed	1	ALARMF
5850 West AMELIA EARHART Drive	01/05/2022 15:43:08	Dispatched and cancelled en route	9AF	Cancelled en route	CF22- 663	Officer reviewed	1	ALARMF
586 East BROWNING Avenue	03/21/2022 10:06:34	Smoke detector activation due to malfunction	8JF	Investigate	CF22- 9922	Officer reviewed	1	ALARMF
600 South KOMAS Drive	03/14/2022 04:21:09		10BF		CF22- 9051	Initiated	2	ALARMW
6020 West 300 South	02/16/2022 15:50:39	Dispatched and cancelled en route	9AF	Cancelled en route	CF22- 5860	Officer reviewed	2	ALARMW
6050 West 700 South	03/31/2022 16:22:17		9AF		CF22- 11196	Initiated	1	ALARMW
610 South FOOTHILL Drive	01/12/2022 02:05:58	Trash or rubbish fire, contained	10BF	Investigate	CF22- 1460	Officer reviewed	1	ALARMF
621 East BRYAN Avenue	02/22/2022 16:15:25	Carbon monoxide detector activation, no CO	8JF	Investigate	CF22- 6620	Officer reviewed	1	ALARMF
63 South 900 East	02/21/2022 19:29:17	Good intent call, other	1CF	Investigate	CF22- 6503	Officer reviewed	1	ALARMF
638 East 500 South	01/23/2022 20:14:54	False alarm or false call, other	5AF	Information, investigation & enforcement, other	CF22- 2846	Officer reviewed	1	ALARMF
640 East WILMINGTON Avenue	01/04/2022 06:29:44	Alarm system activation, no fire - unintentional	3AF	Investigate	CF22- 447	Officer reviewed	2	ALARMW
640 North 2200 West	02/10/2022 07:28:38	Alarm system activation, no fire - unintentional	11AF	Investigate	CF22- 5086	Officer reviewed	1	ALARMF
644 West NORTH TEMPLE Street	01/10/2022 09:17:55	Sprinkler activation, no fire - unintentional	2AF	Investigate	CF22- 1229	Officer reviewed	2	ALARMW
650 North SADDLE HILL Road	02/19/2022 15:21:41	Dispatched and cancelled en route	4BF	Cancelled en route	CF22- 6231	Officer reviewed	1	ALARMF
650 South 1100 East	03/21/2022 14:35:16	False alarm or false call, other	5FF	Information, investigation & enforcement, other	CF22- 9954	Officer reviewed	1	ALARMF

Address	Incident Date	Incident Type	Response Zone	Primary Action Taken	Incident Number	Incident Status	Number of Apparatus	Dispatch Code
650 South 300 West	01/10/2022 09:48:22	Dispatched and cancelled en route	6IF	Cancelled en route	CF22- 1234	Officer reviewed	0	ALARMF
650 West 800 South	02/04/2022 10:01:35	Unintentional transmission of alarm, other	6FF	Information, investigation & enforcement, other	CF22- 4347	Officer reviewed	1	ALARMW
660 South 400 West	01/16/2022 02:48:17	Detector activation, no fire - unintentional	6IF	Investigate	CF22- 1928	Officer reviewed	0	ALARMF
6628 West 700 North	03/02/2022 11:03:48	False alarm or false call, other	9AF	Investigate	CF22- 7529	Officer reviewed	1	ALARMF
673 South 1200 West	02/19/2022 09:54:03	Dispatched and cancelled en route	6JF	Cancelled en route	CF22- 6189	Officer reviewed	0	ALARMF
678 North F Street	03/11/2022 02:57:37	Good intent call, other	4AF	Information, investigation & enforcement, other	CF22- 8670	Officer reviewed	1	ALARMF
681 East 6TH Avenue	03/13/2022 11:12:17	False alarm or false call, other	4CF	Investigate	CF22- 8958	Officer reviewed	1	ALARMF
681 South EGLI Court	02/23/2022 00:12:08	CO detector activation due to malfunction	5AF	Investigate	CF22- 6678	Officer reviewed	1	ALARMF
694 North WEST CAPITOL Street	03/30/2022 07:00:30	Carbon monoxide detector activation, no CO	2FF	Investigate	CF22- 11027	Officer reviewed	1	ALARMF
697 North RICHLAND Drive	03/08/2022 22:28:37	Dispatched and cancelled en route	4CF	Cancelled en route	CF22- 8439	Officer reviewed	1	ALARMF
7 East 400 South	03/24/2022 15:26:58	Dispatched and cancelled en route	1HF	Cancelled en route	CF22- 10342	Officer reviewed	1	ALARMF
700 South FOOTHILL Boulevard	03/17/2022 09:27:35	Dispatched and cancelled en route	10BF	Cancelled en route	CF22- 9423	Officer reviewed	1	ALARMF
711 East HARRISON Avenue	01/13/2022 19:57:09	Dispatched and cancelled en route	5KF	Cancelled en route	CF22- 1655	Officer reviewed	1	ALARMF
718 South 600 East	03/02/2022 18:46:46	Cooking fire, confined to container	5AF	Investigate	CF22- 7590	Officer reviewed	1	ALARMF
719 East 900 South	02/26/2022 04:41:34	CO detector activation due to malfunction	5JF	Investigate	CF22- 7056	Officer reviewed	1	ALARMF
720 South GUARDSMAN Way	02/23/2022 16:41:03	Service call, other	5BF	Remove water	CF22- 6761	Officer reviewed	2	ALARMF
73 East COLUMBUS Court	01/12/2022 14:05:00	False alarm or false call, other	2EF	Incident command	CF22- 1507	Officer reviewed	1	ALARMF
744 East HARRISON Avenue	03/13/2022 21:15:55	CO detector activation due to malfunction	5KF	Investigate	CF22- 9021	Officer reviewed	1	ALARMF
750 North 5600 West	01/04/2022 03:30:12	Dispatched and cancelled en route	9AF	Cancelled en route	CF22- 430	Officer reviewed	2	ALARMW
76 South 500 East	04/03/2022 16:05:16		1GF		CF22- 11553	Initiated	1	ALARMF
761 East 6TH Avenue	01/11/2022 23:14:18	Smoke detector activation, no fire - unintentional	4CF	Investigate	CF22- 1447	Officer reviewed	1	ALARMF
765 East NORTHCLIFFE Drive	03/31/2022 04:50:43	False alarm or false call, other	4CF	Investigate	CF22- 11131	Officer reviewed	1	ALARMF
77 West 1300 South	02/03/2022 04:13:41	Sprinkler activation, no fire - unintentional	8IF	Provide manpower	CF22- 4182	Officer reviewed	2	ALARMW
777 North 5600 West	03/24/2022 16:59:49	Smoke detector activation, no fire - unintentional	9AF	Investigate	CF22- 10352	Officer reviewed	1	ALARMF
777 South 1300 East	02/26/2022 09:25:31	Dispatched and cancelled en route	5BF	Cancelled en route	CF22- 7069	Officer reviewed	1	ALARMF
797 North NORTHSHORE Street	01/30/2022 05:29:56	False alarm or false call, other	4CF	Investigate	CF22- 3637	Officer reviewed	1	ALARMF
808 North 1200 West	03/17/2022 18:50:31	False alarm or false call, other	7BF	Investigate	CF22- 9500	Officer reviewed	1	ALARMF
808 North 6550 West	03/23/2022 08:28:54	Dispatched and cancelled en route	9AF	Cancelled en route	CF22- 10162	Officer reviewed	1	ALARMF
814 North NORTHPOINT Drive	02/19/2022 11:07:51	False alarm or false call, other	4AF	Information, investigation & enforcement, other	CF22- 6200	Officer reviewed	1	ALARMF
819 East 900 South	03/03/2022 15:51:47	Smoke detector activation due to	5JF	Investigate	CF22- 7692	Officer reviewed	1	ALARMF

Address	Incident Date	Incident Type	Response Zone	Primary Action Taken	Incident Number	Incident Status	Number of Apparatus	Dispatch Code
		malfunction						
822 South 500 East	02/15/2022 20:30:45	False alarm or false call, other	5JF	Investigate	CF22- 5776	Officer reviewed	1	ALARMF
825 South GLADIOLA Street	01/04/2022 08:15:14	Dispatched and cancelled en route	14AF	Cancelled en route	CF22- 456	Officer reviewed	1	ALARMW
843 North GRANDRIDGE Court	02/10/2022 15:36:51	False alarm or false call, other	4AF	Investigate	CF22- 5154	Officer reviewed	1	ALARMF
845 South 400 East	02/15/2022 20:33:04	Alarm system sounded due to malfunction	5JF	Investigate	CF22- 5777	Officer reviewed	1	ALARMF
846 North WOODEN Lane	01/21/2022 19:33:11	CO detector activation due to malfunction	11AF	Investigate	CF22- 2623	Officer reviewed	1	ALARMF
85 North MEDICAL Drive	01/19/2022 00:23:10	Dispatched and cancelled en route	4EF	Cancelled en route	CF22- 2325	Officer reviewed	1	ALARMF
855 West 800 South	02/25/2022 16:45:31	Defective elevator, no occupants	6DF	Information, investigation & enforcement, other	CF22- 7007	Officer reviewed	0	ALARMF
857 East YALE Avenue	01/15/2022 21:16:56	Carbon monoxide detector activation, no CO	5JF	Investigate	CF22- 1899	Officer reviewed	1	ALARMF
859 South 600 West	04/02/2022 08:00:04		6HF		CF22- 11396	Initiated	0	ALARMF
863 West 500 South	01/20/2022 18:49:08	Dispatched and cancelled en route	6FF	Cancelled en route	CF22- 2521	Officer reviewed	0	ALARMF
871 North POINSETTIA Drive	01/30/2022 13:22:29	Dispatched and cancelled en route	7BF	Cancelled en route	CF22- 3666	Officer reviewed	1	ALARMF
880 East 2100 South	02/19/2022 09:51:37	Water or steam leak	3CF	Remove water	CF22- 6188	Officer reviewed	2	ALARMW
888 South 200 West	03/19/2022 20:34:19	Smoke detector activation, no fire - unintentional	8EF	Investigate	CF22- 9756	Officer reviewed	1	ALARMF
89 North B Street	03/02/2022 13:51:33	Dispatched and cancelled en route	1JF	Cancelled en route	CF22- 7543	Officer reviewed	1	ALARMF
910 West 2100 South	02/22/2022 12:22:13	Cooking fire, confined to container	6MF	Investigate fire out on arrival	CF22- 6601	Officer reviewed	0	ALARMF
923 North 900 West	02/06/2022 07:10:13	Dispatched and cancelled en route	7BF	Cancelled en route	CF22- 4606	Officer reviewed	1	ALARMF
924 North STAR CREST Drive	01/26/2022 18:06:08	False alarm or false call, other	11AF	Information, investigation & enforcement, other	CF22- 3214	Officer reviewed	1	ALARMF
933 East 2ND Avenue	02/17/2022 21:11:07	Dispatched and cancelled en route	4DF	Cancelled en route	CF22- 6018	Officer reviewed	1	ALARMF
936 South 200 West	03/02/2022 09:38:43	Unintentional transmission of alarm, other	8EF	Investigate	CF22- 7520	Officer reviewed	1	ALARMF
936 South 300 West	03/31/2022 09:32:08	Dispatched and cancelled en route	8AF	Cancelled en route	CF22- 11150	Officer reviewed	1	ALARMF
940 West NORTH TEMPLE Street	04/01/2022 18:23:03	False alarm or false call, other	7BF	Investigate	CF22- 11345	Officer reviewed	1	ALARMF
955 East SOUTH TEMPLE Street	01/10/2022 09:31:29	Dispatched and cancelled en route	1KF	Cancelled en route	CF22- 1231	Officer reviewed	1	ALARMF
980 South BENDING RIVER Road	02/10/2022 20:30:41	Overheated motor	14DF	Investigate	CF22- 5188	Officer reviewed	1	ALARMF
99 West SOUTH TEMPLE Street	03/24/2022 14:10:30	Dispatched and cancelled en route	2GF	Cancelled en route	CF22- 10327	Officer reviewed	1	ALARMF
996 South 200 East	01/28/2022 13:55:10	Service call, other	8FF	Assistance, other	CF22- 3446	Officer reviewed	1	ALARMF
998 South OAK HILLS Way	01/21/2022 14:34:31	Dispatched and cancelled en route	10DF	Cancelled en route	CF22- 2591	Officer reviewed	1	ALARMF

Report Criteria

Incident Date:

Is Within last_90_days

Dispatch Code: Begins With alarm

Need help? Call Nicole at 801-799-4103, or email us.